TENDER ENQUIRY

Dt. 11/09/2024

Tender Ref No: MP1/ARC/FRESH WATER/CMSRU

Dear Sir,

Sealed Tenders in Two Bid, super scribing the Enquiry Number & Last date for receipt of Quotations on the envelope, are invited in two separate covers as 'Part I Techno Commercial' & 'Part II Price' for ANNUAL RATE CONTRACT FOR SUPPLY OF FRESH WATER AT CMSRU (Cochin Shipyard Mumbai Ship Repair Unit)

- 1 The offers as above should reach the undersigned on or before the last date and time shown. Tenders should be addressed to "The Deputy General Manager (CMSRU), Cochin Shipyard Ltd-Mumbai Ship Repair Unit, Mumbai Port Trust, and Mumbai-400001".
- 2. Techno Commercial offers can also be made by e-mail, with price bid duly Locked with password, before 11.00 hrs (IST) on 21 September 2024, if delivery of sealed offers cannot be ensured at CSL on the due date.
- 3. The offer shall indicate payment terms and other terms and conditions.
- 4. Vendors are strongly advised to visit work site prior to quoting.
- 5. Quotation should be valid for a period of 3 months.
- 6. Quotation can be submitted by email as a password protected document (price part only) to the following email address.

ashutosh.pande@cochinshipyard.in

lijo.jacob@cochinshipyard.in

cmsru.materials@cochinshipyard.in

OR

In a sealed envelope addressed to "The Deputy General Manager (CMSRU), Cochin Shipyard Ltd-Mumbai Ship Repair Unit, Mumbai Port Trust, Mumbai-400001".

Last Date & Time of Receipt of Tender: 21 September 2024 at 11.00 Hrs IST.

Last Date & Time of Clarification: 19 September 2024 at 17.00 Hrs IST.

Tender Opening date & time: 21 September 2024 at 11.30 Hrs IST.

NOTE: Amendment if any will be notified on CSL/Govt. Website. The bidders are requested to keep themselves informed of the development by visiting CSL website www.cochinshipyard.com and the CPP portal www.eprocure.gov.in regularly. Such amendments shall be binding upon them.

Enclosures: -

- 1. Special Instruction for Two Bid Systems
- 2. Scope of work
- 3. Price bid format
- 4. Rules for engaging workmen at CMSRU
- 5. CMSRU HSE booklet
- 6. Specific Terms &conditions
- 7. General Terms &conditions
- 8. Compliance matrix
- 9. Unprice bid format
- 10. HSE Guidelines.
- 11. Prequalification criteria

Signed copy of following documents shall be submitted along with <u>unpriced Price bid format</u> <u>clearly indicating quoted/not quoted</u> against each job scope as per CSL P- bid format (Un priced bid no need to protect with password, if send as soft copy in E mail).

- 1. Scope of work
- 2. Price bid format
- 3. Rules for engaging workmen at CMSRU.
- 4. CMSRU HSE booklet
- 5. Specific Terms &conditions
- 6. General Terms &conditions
- 7. Compliance matrix
- 8. HSE Guidelines.
- 9. Prequalification criteria

Price bid duly signed and sealed by the authorized person need to be protected with password and shall be separately attached/enclosed in the mail. Offer submitted in single bid will not be considered.

In case of technical queries, please contact Mr. Sebi Augustine, (Project Officer - CMSRU)

(e-Mail: sebi.augustine@cochinshipayrd.in, Mob no. +91 8714630958)

Yours faithfully,

Deputy General Manager (CMSRU)

COCHIN SHIPYARD LIMITED

COCHIN - 682 015

SPECIAL INSTRUCTION FOR TWO BID SYSTEMS

1. MODE OF SUBMISSION OF TENDERS

Tenders should be submitted in two separate sealed covers super scribed in capital letters as **PART-I "TECHNO-COMMERCIAL" & PART-II "PRICE"** indicating the tender number, due date and name & address of the tenderer.

2. TECHNO-COMMERCIAL PART SHOULD CONTAIN FOLLOWING DETAILS:-

- I. Drawings & Technical Literature, if any
- II. Other conditions, if any
- III. Signed and stamped copy of TENDER TERMS AND CONDITIONS (Annexure 1)
- IV. Deviation list, if any
- V. Price bid without price clearly indicating quoted/ not quoted against each line item/ DL.

3. PRICE PART SHOULD CONTAIN FOLLOWING DETAILS:-

- a. Price against each work.
- b. Taxes & duties as applicable shall be indicated.
- 4. CSL reserves the right to alter, modify the scope of supply at their discretion and consistent with the Navy Policy as applicable to the contract from time to time.
- 5. The Techno-commercial part alone will be opened initially on the due date and time of tender. The price part will be opened only after evaluation of the Techno commercial Part. Firms will be intimated the date of opening of the price part, whose Techno-commercial bid is acceptable, in due course.
- 6. The tenderer shall ensure that their Indian Agent is not representing any other suppliers for the same Tender. In other words, Indian Agents are not permitted to represent more than one firm for a particular Tender.

- 7. Deviations, if any, in the offer submitted from that of the tender enquiry in any form, should be clearly furnished in a separate document titled as "List of Deviations".
- 8. Details of optional items, if any, should be indicated under separate heading in the technical bid and the respective price details should be given in the price bid.
- 9. After submission of quotation / price bid opening, no unsolicited correspondence will be entertained.
- 10. Clarifications, either technical or commercial, should be submitted to points specially asked for only. The opportunity so given should not be used for correcting/changing amending the data/conditions already submitted with the tender.
- 11. Price should be quoted separately for each item. Combining of figures against more than one item and ambiguous clauses will lead to rejection of the bid.
- 12. Offers should be clear and unambiguous. Incomplete/ambiguous offers are likely to be rejected.
- 13. The bidder shall submit a signed & sealed copy of the tender document including the TENDER TERMS AND CONDITIONS (Annexure 1) along with their bid as token of acceptance of terms & Conditions.
- 14. An Integrity Pact as per CSL format is to be signed and submitted later (if necessary).
- 15. The quantity projected in the scope of work is estimated. There may be upward/downward variations in actual quantity.

Deputy Manager (CMSRU)

MP1/ARC/FRESH WATER/CMSRU

Scope of work

Encl.1

- 1. Supply of fresh water in tanker to ships/vessels berthed in Indira Docks (ID) and Hughes Dry Dock inside MbPA (Mumbai Port) via tanker as per requirement. The water quantity might be up to 60Kilolitre/day which may increase 50% more depending on the requirement of ships docked at CMSRU, which would be informed by CMSRU officer in-charge. Supply should be completed within 24 hours from intimation.
- 2. Usage of water is for drinking consumption, vendor should provide for the same. Hence certificate of water quality to be submitted as and when requested by officer in-charge.
 - Note:Please be informed that there would be random inspection from CMSRU also.
- 3. The vendor shall keep record of water quantity supplied as per Enclosure a, with signature from concerned ship in-charge. The work completion record duly signed, respective request from CMSRU etc. should be submitted for verification along with Invoices.
- 4. Tanker should have a capacity of minimum 10 kilolitre (10 ton) with pumping facility (preferably diesel pump, which should be arranged, in case electrical power supply is not available) of minimum 10 Meter delivery head. Fuel if required, should be arranged by vendor.
- 5. Tanker must also be equipped with at least 50 meters of hoses and Vendor shall arrange for extra length of hoses and, couplings and fittings in accordance to the site requirement.
- 6. Laying of hoses and all connections necessary to supply water from tanker to storage space in ships/vessels as informed by officer in-charge are in the scope of vendor. Ropes might be required to secure the hoses and adequate manpower should be arranged by the vendor for the same
- 7. All the personnel should wear proper PPEs including Safety helmets and shoes
- 8. All necessary gate passes, dock entry permits and other MbPA formalities for movement of man, materials (including water) and vehicles (including tanker) are to be arranged by vendor.

<u>Note:</u> The expected requirement is up to 3000 kilolitres of fresh water in a year, however estimated quantity is tentative and may increase by 50% more as per actual requirements. Payment shall be done at actuals.

Terms and Conditions

- 1. The contractor shall quote in the price bid format only and submit along with signed copy of agreed terms and conditions.
- 2. Offer Validity: The offer should be valid for a minimum period of three months from date of submission of offer.
- 3. Validity of the Annual Contract shall be for a period one year w.e.f. the date of issuance of contract with a provision for extending to one more year with same rate, terms and condition
- 4. Terms of Payment: Monthly Payment at actuals as certified by officer in-charge upon furnishing bill in triplicate along with Work completion certificate as per enclosed format and copy of request from CMSRU.
- 5. Penalty: In case the quantity or quality of the supply is found lacking, contractor shall be liable for penalties as per Enclosure b.
- 6. Firms shall mention their PAN No. and GSTIN No in the offer.
- 7. The firm should depute competent personnel for the execution of the work.
- 8. CMSRU reserves the right to award the contract to one or more contractors on parallel or split basis depending upon the actual necessity
- 9. Indemnity: Notwithstanding that all reasonable and proper precautions may have been taken by the contractor at all times during the progress of the work, the contractor shall nevertheless be wholly responsible for all damages, whether to the works, themselves or to any other property or to the lives or persons or property of others during the progress of the works.
- 10. All applicable taxes, duties, transportation, loading, unloading, insurance, port clearance etc. should be included in the rate quoted, unless specified otherwise.
- 11. The contractor shall have to provide all the required tools, tackles, testing equipment, machinery, vehicles for transportation, loading, unloading etc for carrying out subject work within the quoted price.
- 12. CMSRU safety procedures to be followed for entire period of work by contractor
- 13. The contractor shall get familiarize with exact scope and quantum of work before quoting for the same. Once offer received, it is deemed that the bidder has assessed the exact quantum of work and accepted all terms and condition for the subject work. Work has to be carried out as per the direction of CMSRU officer- in-charge.
- 14. PROHIBITION OF CHILDREN'S EMPLOYMENT: Contractor shall note and follow the Govt. of India Notification of `Prohibition of Children's employment in the schedule occupation and process under the Child Labour (Provision and Regulation) Act, 1986".
- 15. Safety Provision: Attention is invited regarding safety provisions and adheres to the same while executing the work. In addition to the instructions stipulated therein, contractor should note that it is compulsory that every worker employed by the contractor/successful tenderers shall use PPE while the contract work is in progress, at CMSRU premises / site. The contractor should take necessary safety measures to carry out the job, without causing any accident, and shall not cause any Loss to CMSRU either directly or indirectly. However, if any such incident took place while carrying out the work, loss to the CMSRU properties will be borne by the contractor.
- 16. CMSRU / officer in charge has the right to reject the water supplied if the water is found to be not suitable for consumption

WORK COMPLETION RECORD

Fresh Water Supply to Vessel

SI No.	Request Date	Requested Quantity in ton	Supply Date	Supplied Quantity in ton	Ship staff sign

PENALTIES

SI	Nature of Default	Default Details		
No.			Penalties	
			1 st Instance	2 nd Instance Onwards
1	Non-Supply	Failing to supply the	Warning	Fine equivalent to 10% of
		requested quantity as a		requested order value
		whole		from previous months
				bill.
2	Partial supply (incompletion	Incomplete supply of	Warning	5% Deduction in payment
	even after 3days will be	requested quantity		of supplied quantity
	considered as Non-supply)			
3	Delayed supply by 2 days	Supply not completed	Warning	5% Deduction in payment
	(more than 2days will be	within 3 days of		of supplied quantity
	considered as Non-supply)	request		
4	Lack of Quality	The quality of water	Rejection of	Rejection of supply & Fine
		supplied is found to be	supply & treated	equivalent to 10% of
		unsuitable for drinking	as Non-supply	requested order value
				from previous months bill.

	PRICE BID FORMAT		
MP1/AR	C/FRESH WATER/CMSRU		Encl.3
	ANNUAL RATE CONTRACT FOR SUPPLY OF FRESH AT CMSRU	•	
Sl No.	Description	Unit rate per Ton (Rs.)	GST(%)
1	Supply of Fresh Water as per scope of work, terms & conditions		
		<u> </u>	

Contractor's Seal & Signature

Rules for engaging contractor's workmen in CSL-MSRU

- I) The following labour statutory compliance measures should be followed by contractors working in CSL Mumbai Ship Repair Unit;
 - 1. If the contractor is engaging 10 or above contract workmen, their firm must have independent establishment registration under EPF.
 - 2. If the contractor is engaging 10 or above contract workmen, their firm must have independent establishment registration under ESI.
 - 3. If the contractor is engaging less than 10 contract workmen and they are exempted under ESI/EPF, their workmen should be covered under Employee Compensation policy.
 - 4. The wage payment for workers should be disbursed through bank payment only and contractor have to submit monthly Challan for ESI Remittance ,EPF Remittance and bank statement of wage disbursement along with their monthly bills.
 - 5. If the contractor is engaging 20 or above contract workmen, they should take the Labour Licence under Contract Labour Contract Act.
- II) The contractor is solely responsible for complying ESI & EPF rules for contract workmen engaged by them for the work.
- III) It is mandatory to submit police clearance from Mumbai Police station to issue gate entry pass. Hence all the workmen belong to other states shall have to take police clearance from their respective home station to submit application form for obtaining police clearance from Mumbai Police Station.
- IV) Employee/worker deputed for the work shall not be over 58 Years of age.

Seal & Sign of Authorized Person

BASIC SHIP TERMINOLGY

6. Bulbous Bow 1. Funnel


7. Bow 2. Stern

4. Port Side [Right side "Starboard side"] 9. Super Structure

8. Deck

3. Propeller

5. Anchor



Cochin Shipyard Limited Mumbai Ship Repair Unit QHSE Department



HSE Hand book

Rev A00 - Jan-2019

Emergency Telephone Numbers

022-?????

WHILE MAKE AN EMERGENCY CALL!!!

Clearly State;

- What type of emergency (eg. Ambulance, fire/rescue
- Where is the emergency (eg: Repair dock BY 90 tank no. 2(p))
- Guide the emergency crew to the location
- Responsible person or supervisor must be with victim



INDEX

- 1. INTRODUCTION.
- 2. QHSE POLICY
- 3. HSE MANAGEMENT SYSTEM IN CSL-MSRU
- 4. SAFETY INDUCTION
- 5. WORK AREAS IN CSL-MSRU
- 6. RESTRICTED ENTRY AREAS IN CSL-MSRU
- 7. GENERAL SAFETY GUIDELINES
- 8. HSE GUIDELINES
- 9. RESPONSIBILITIES OF CONTRACTOR
- 10. REPORTING OF INCIDENTS
 - 11. PERMIT TO WORK SYSTEM
- 12. PERSONAL PROTECTIVE EQUIPMENT
- 13. HOUSE KEEPING
- 14. WELDING & CUTTING
- 15. SURFACE PREPARATION
- 16. PAINTING
- 17. WORKING AT HEIGHTS
- 18. WORKING OVER WATER
- 19. CONFINED SPACE
- 20. HAND TOOLS AND POWER TOOLS
- 21. WORKING ON MEACHINE TOOLS AND MACHINERES

- 22. HANDLING ELECTRICITY
- 23. MANUAL HANDLING
- 24. LIFTING OPERATIONS
- 25. BASIC RIGGING SIGNALS, TACKLES AND

METHODS


- 26. DOCKING & UNDOCKING
- 27. SLIPS, TRIPS AND FALLS
- **28. FIRE**
- 29. GENERAL PERSONAL FACTORS LEAD AN INCIDENT
- 30. OFFICE SAFETY
- 31. WASTE MANAGEMENT
- 32. OCCUPATIONAL HEALTH
- 33. FIRST AID
- 34. COLOUR CODING WITH TYPES OF SERVICE MANIFLODS/PIPE LINES & ELECTRICAL
 - **DISTRIBUTION BOXES**
- 35. CONSEQUENCE MANAGEMENT
- 36. SAFETY COMMITTEE
- 37. STEPS TO REDUCE ENVIORNMETAL IMPACTS

its employees on rolls, Partners, subcontractors & their workmen and Owners/ Classification societies and will do INTRODUCTION
 Cochin Shipyard Limited – Mumbai Ship Repair Unit
 (CSL-MSRU) places utmost importance on the safety of its best to provide and maintain a safe and healthy working environment.

personnel. Every employee in the yard from the Grade down to the Workman level has a The responsibility for safety does not end with the safety definite role to play their work is safe. Managerial

This Safety hand book has been compiled by QHSE Department for the use of all personnel working or visiting inside the yard.

clarification on HSE requirements, QHSE team will guide This book does not replace the detailed requirements, safety rules in vogue practiced by CSL-MSRU, for further you to work safely.



2. QHSE POLICY



We are committed to provide ship building, ship repair services and training of marine engineers to the total satisfaction of customers. We undertake these in healthy & safe working conditions, an eco friendly environment and ensure continual improvement of management systems performance.

We endeavour to achieve the above by:-

Meeting or exceeding customer requirements.

Assuring quality of the products and services.

Developing competent marine engineers.

Preventing occupational ill health and injuries.

Ensuring safe work sites.

Conserving natural resources.

Preventing / Minimising air, water and land pollution.

Handling and disposal of hazardous wastes safely.

Complying with statutory & regulatory and other requirements.

Developing skills and motivating employees.



3. HSE MANAGEMENT SYSTEM IN CSL-MSRU

3.1 QHSE Statement

The long-term business success of CSL-MSRU depends on our ability to continuously its performance in providing assured quality of the ship repair services. Enhanced the occupational health of the employees, Environment & safety, by following best practices within the organization and sustained environmental protection for the benefit of the society.

3.2 Health & Safety

CSL-MSRU strives to conduct all its activities in such a way as to prevent injuries and ill health to our employees, contractors and visitors. CSL-MSRU record and investigate all the incidents occurring in the work place in order to identify the cause and take necessary measures within the ship yard. CSL-MSRU achieving this by identifying the high risk hazards, eliminating or if not at least reducing the risk involved to acceptable level. CSL-MSRU take necessary measures to educating all people involved in ship repair activities on health and safety practices within the work place and off the job safely.

3.3 Environment

CSL-MSRU commitment to the Mother Nature is demonstrated through the ongoing effort to reduce the adverse impact on the environment and reinforcing the positive contribution. This is achieved by identifying the significant environmental aspects related to its activities and products and developing programs and processes to reduce or control them with an aim of protecting the environment.

SAFETY INDUCTION

All entrants to CSL-MSRU are made aware about basic CSL-MSRU requirements with respect to Health, Safety, Environment & Emergency Response. This training is imparted to all newly inducted CSL-MSRU Employee/Trainees/ Contractors workmen, who will be engaged in ship repair/ maintenance / construction activities on installations. The individual passes will be issued only

after successful completion the HSE induction training programme.

WORK AREAS IN CSL-MSRU ъ.

- a. Dry dock 305 X 30 X 15 meters b. Berth- 5,6,7 & 8 (Indira Dock)

RESTRICTED ENTRY AREAS IN CSL-MSRU <u>ن</u>

Due to potential hazards, entry restricted to authorized persons in the following areas.

- Substations a.
- Flammable gas storage area
- Barricade the locations with warnings as and when required. ن <u>ن</u>

GENERAL GUIDELINES 7

- Every individual is responsible and obliged to "Suraka Keliye Rukem" for the non compliance of 12 Silent Safety Rules published by CSL and this is to be performed as per the quidelines mentioned towards an interdependent safety culture. 7
 - Smoking is strictly prohibited
 - Unauthorized use of cameras and mobile phones in CSL-MSRU is forbidden. 33
- Parking of vehicle is only in approved parking locations. Priority is for Material Movement and private vehicles shall
 - make way for material movement. 40
- The use or possession or influence of non-prescription drugs, alcohol and the abuse of substances is strictly prohibited in CSL-MSRU. 9
 - Speed Limit of vehicle in the yard is 20km/Hr
 - Fishing is not permitted in yard 83
- Everyone should observe and obey regulatory signs. 6
- 10)Use of mobile phones is strictly prohibited while at work and driving including while cycling.
- 11)Horse play is not entertained in CSL-MSRU. (Example: Direct compressed air or gas on any person)
 - the guidelines, Refer entry management system for machinery in CSL-MSRU premises to be followed as per 12) Hiring or bringing the materials / equipments /

Hiring or bringing the materials / equipments / machinery (Annexure 4 - Entry Checklist for equipment and toos)

HSE GUIDELINES œ.

- Usage of Safety Helmet with chin strap, safety shoe and cotton working dress are compulsory at CSL-MSRU work site, in addition suitable PPEs which are job specific are to be used. (refer CSL- PPE'S Matrix) 7
- before commencement of work. These measures are to be Risk assessments of non routine works are to be done before the work is started and control measures identified communicated to the workers involved through tool box approved by CSL-MSRU officer In charge and confirm by talks. These works to be performed through Job Safety These control measures Analysis (JSA)(Refer Annexure 2) QHSE Dept. 7
- Workers and supervisors engaged in the works shall be competent. 3
- Supervisor In charge is to Brief the hazards and preventive measure related to the work to be carried out during daily tool box talks. 4
- group only. In case a person has to work alone, the same shall be known to at least two persons who are working People are to be engaged in work activities preferable in 2
- 6) Using Paint tin, CO₂ welding cable bobbin and oil drums as working platform is strictly prohibited.
- Thinner is not to be store in beverage bottles
- Ensure necessary state of mind (eg: lack of proper sleep) by having rest at periodic intervals during extended working hours especially during night time. 8

- Adequate precautions should be taken during welding or gas cutting against hazards such as electric shocks, burns, fumes, explosion and arc eyes.
- 10)Adequate ventilation should be provided while working in confined spaces.
- 13) Check and ensure the adjacent areas compartments are free from flammable hazards and suitable protections are taken before commencing hot work.
- 14) Never start hot work cutting the bottom/side shell of ship from outside to inside.
- 15) During hot work at elevated positions, precautions should be taken to prevent sparks or hot metal slag falling on to the people or material below / nearby and suitable barricade to be done at the ground.
- 16)Industrial Oxygen is not to be used for ventilation purpose.
 - 17) Simultaneous operations of Hot work and painting are not to be carried out in the same area.
- 18) Ensure that no hot work should be carried out in the presence of hydrocarbon fumes.
 - 19)All electrical equipments including AC welding machine should be properly earthed.
- 20)Ensure that ELCB/RCCB is fitted on all Welding Machines and extension boards.
- 21) Ensure cables have sufficient current carrying capacity that is used for all electrical equipments/tools.
- is used for all electrical equipments/tools. 22)Voltage Reducing Devices (VRD) (Safety relay) must be fitted on AC welding Machines.
 - 23) Never Bypass Safety Relay on AC welding machines
- 24) Electrical extension switch boards are in metallic construction with ELCB/RCCB & and individual MCB. Only industrial type plug and socket to be used.
- 25)Only authorized persons are allowed to operate any machine/equipment / Switch boards. Unauthorized operation strictly prohibited. work on yard switch boards only allowed to CSL-MSRU electrical team.
- 26) Never tamper with machine guards.
- 27) Ensured that all portable equipments, welding transformers/rectifiers must be switched off after use.
- 28)230 V hand lamps are not permitted in the yard. Use 110 V hand lamps in open area and 24 V hand lamps are to be uses in confined spaces.

- 29) 24 V Flame proof lamps shall be used inside tanks where while there was hydrocarbon presence and during painting in confined spaces.
- 30) Users are to daily inspect welding cables, cutting hoses and hand tools must be used in the yard.
- 31)All the temporary electrical connection including connection of welding sets, distribution box etc shall be made with the approval of yard electrical safety officer
- 32) Excavated materials should be put away from the edge of the excavated trench to avoid slopping of the excavated materials into the trench.
- 33) Never enter into tanks without permit. Refer Confined space entry procedure.
- 34) People working in tanks or pits must acquaint with the hazard present there and supervisor should advise his employees of the hazards present and precautions that are to be taken.
- 35)Open manholes and places people are liable to fall, those areas must be protected by strong barricade with intermediate railings. Man hole covers should be replaced promptly when work is suspended.
- 36) Jumping from moving vehicle is prohibited. They should wait until the vehicle stop before attempting to enter or leave.
- 37)Any dangerous situation affects the safety of an employee or his fellow employees shall be immediately brought to the notice of site supervisor or reported to CSL-MSRU OHSE team.
- 38)Standing under suspended loads is dangerous and is avoided.
- 39)Compressed air should not be used to clean dust in the clothing.
- 40)Any kind of Gas cylinders (empty/full) should be secured in upright position and away from direct sunlight.
- 41)Air hoses, welding cables, fuel hoses and electric cables should not be allowed to lie across walkways and area they should be suspended from overhead hooks.
- 42) Inflammable liquids must be handled in cans or containers meant for storing it and are to be stored in space having good ventilation. All such containers must be clearly labeled and warnings exhibited visibly.

- 43) Material Handling Equipments to crane tracks through the authorized route only.
 - 44)If a threat to any person's life is observed, anybody can clear the threat and wait for authorized rescue persons for further actions. Rescue operations should be done by authorized persons only.
- 45) Everybody should be responsible for housekeeping at their work site.
 - 46) Avoid activity/action that leads to air/water/soil pollution.
- 47)All the pressure line joints must be connected with whiplash/whip sock arrestor.
- 48) Gas management for cutting operations to be complied as the procedure(Annexure 3- Gas management Procedure)

RESPONSIBILITIES OF CONTRACTORS o.

- The Contractor before starting any work in the CSL-MSRU premises will be issued with these CSL-MSRU HSE guidelines and firm is expected to give a declaration that he receives one copy of the CSL-MSRU HSE guidelines and will comply with laid therein. 7
 - The contractor should convey the HSE guidelines to his 5
- workers and make them aware through tool box talks. A responsible safety Incharge is to be designated by the firm for the activities. The details of the safety Incharge shall be communicated to OHSE team. He shall take a lead to ensure safe work environment for their work sites. 3
- CSL-MSRU reserves its right it suspend work in the event of the contractor not complying with the HSE guide lines with regarding to HSE practices for which no claim of any kind will be entertained. 4
- representative of the contractor should maintain appropriate contract with the CSL-MSRU officer-in-charge To ensure the safe conduct of safety operation a of the work as may be necessary to acquaint himself with any changed conditions of other matters relating to the HSE performance. 2
- employees understand their obligations and they follow all CSL-MSRU all his The contractor shall ensure that HSE rules. 6
- It is the responsibility of the sub- contractor firm to provide their employees with all the necessary PPE'S. \sim

- The contractor is also responsible for controlling the behavior of his personnel and must control their movement to and from the work site. 8
 - The HSE plan of Contractor is detailed in the procedure. (Annexure -5 - Refer HSE Plan of Contractor) 6
- 10) For further clarifications on HSE matters, Contact CSL-HSE Officer.

10.REPORTING OF INCIDENTS

MSRU premises during the duty/after duty hours should be All injury incidents to employees/ trainees/sub-contractors & their workmen/visitors/Ship staff occurring inside CSLreported by supervisor to project manager.

Form 02) to be initiated by the officer in charge of the area CSL-MSRU personal injury reporting form (CSL / SMS / S&F/ and reach to QHSE dept within 24 hrs.

suggestions, violation etc) other than personnel injury Format of HSE Observations (near miss, property damage, incidents shall be available at HSE site cabins/offices.

11.PERMIT TO WORK SYSTEMS

The following activities must not commence unless obtaining issued work permits. (Refer PTW procedure annexure) The type of work permits are:

1) ON BOARD SHIP

- a) Hot work (Oxy Acetylene cutting/Welding On Board Ships)
- Tanks/Confined Confined .⊑ Spaces/other compartments) paintings Buffing (Brush/Spray Painting a
 - Electrical on (Works Shut down installation/Equipments) Electrical \circ

2) INSTALLATIONS

- Excavation/Trenches Opening (any)
- Excavation/Fuel or electrical trench opening) a) Work at Height/fragile roofb) Excavation/Trenches Openiic) Excavation/Fuel or electrica

TYPES OF WORK THAT REQUIRE A PTW (STATUTORY)

- Radioactive materials, Any Expose of radio Active materials) Radiography (NDT tests using
- Electrical Shut Down (Works on Electrical distribution of installations/closed proximity system) a

4) JSA FOR NON ROUTING WORKS

- Chemical cleaning pipe line, tanks, equipment's and spaces etc.
 - STP cleaning 3099¢65±
- Tank testing by filling air(APT)
- Pressure testing of AC lines and plants
 - Charging of Refrigerents
 - Puff filling
- Use of liquid nitrogen
- Simultaneous Operations (SIMOPS)
- Fumigation
- Any Other works directed by the yard QHSE team

(Refer Annexure 2 -JSA)

12.PERSONAL PROTECTIVE EQUIPMENTS

associated with hazards they are exposed to. All PPE'S must Employees are responsible to wear appropriate PPE'S comply with approved Indian or international standards e.g. ISI, BS, DIN, ANSI or CE

Basic PPE'S requirement at CSL-MSRU Site.

- Safety Helmet
 - Safety Shoes
- Cotton Working dress
- Safety Glasses or face shield or goggles. (appropriate to work) 1284
- Hand gloves appropriate to work should be worn
- While welding PPE's like apron, gauntlet, leg guard, face shield should be worn 6)
- While grinding helmet with face shield should be worn 83
 - For further information refer PPE'S Matrix

13.HOUSE KEEPING

personnel to maintain the highest possible standard of important part of HSE ь the responsibility housekeeping in their work area. an it is <u>.s</u> management system; Good housekeeping

This can be maintained by:

- commencing the task and at the end of a work shift <u>.s</u> place that the work or completion of the task. a. Ensuring
 - Ensure obstruction free access to all work places. Ь.
- All the waste generated during project taken back out from CSL-MSRU premises,

Items shall be stored in such a way that it is easily identifiable and traceable.

- Suitable control measures shall be ensured while storing of flammable materials and chemicals. σ.
- measure are to be kept stand by in case of spillage working there. Appropriate first aid and fire fighting The MSDS (Material Safety Data Sheet) of each chemical are to be displayed and known to all on people handling it or during any fire. ė.



14.WELDING & CUTTING

All welding and cutting operations must be carried out by qualified personnel while working inside the yard. While working onboard the vessel the work should be in accordance with the conditions specified in the work permit. The principal hazards associated with welding and cutting operations are

- Fire
- Explosions
- Burns
- Eye in jury
- Respiratory disease.

Additional hazards which may result from arc welding are electric shock, ultra violet radiation.

Whenever, welding or cutting operations are being carried out, flammable materials should be removed from the area, where ever possible, and covered with a wetted fire retardant cloth should be placed in case the flammable materials cannot be removed.

14.1 Electric Arc welding

Check equipment thoroughly, all welding cables shall be fully insulated and periodically check for cuts that could accidently "short" when in contact with an earthed section of any structure. Do not lay cables in water.

When connecting cable lengths together, only approved and insulated connecters shall be used. All cables and connectors must be of adequate current carrying capacity to perform the task.

Avoid lengthy cables if possible and lay between wooden blocks, or cover or hang the cables on hooks or stands to prevent tripping hazard. Only electrode holders specifically designated and fully insulated, and rated to handle the maximum current required by the task, should be used.

The arc produces Ultra-violet (UV) radiation. Exposure of UV radiation leads to reddening of the skin and irritation. The eyes are very sensitive to UV radiation, the effect varying from temporary to permanent damage of the retina.

Ensure VRDs (Safety Relay) & ELCB/RCCB are fitted on the AC welding transformers

All welders must wear the appropriate protective clothing, Gauntlet type welding gloves, leather aprons, leggings and correct shaded filter glass to suit the type of work and also all welding cable must be tested every 6 months.

14.2 Cutting Operations

Only proprietary fittings should be used on flexible gas line. Hoses must be fitted to the equipment using crimped fasting by double ear end clip or crimping and **not jubilee clips** which is prohibited by CSL-MSRU. The color code for Oxygen and acetylene hoses are black and red color Respectively. While checking for leaks, only "Soapy water" to be used. Only Acetylene and Oxygen gases are used for cutting operations.

While working with the gas cylinders flash back arrestors must be fitted at regulator and torch end, and non-return valve must be fitted between the hose and cutting equipment while working with the gas cylinders. Suitable ranged and Calibrated pressure gauges shall be fitted on at gas regulator area to check the cylinder and hose side pressure.



All cutting equipment must be removed from the vessels or enclosed spaces to open spaces/weather deck when not in use for a prolonged period of time ie, during breaks or end

of the shift. This will prevent the build-up of gas, if there are any minute leaks.

If the atmosphere becomes oxygen enriched due to leakage, the work area must be purged with fresh air and all clothing/flammable materials must be well ventilated to prevent the risk of spontaneous combustion. Gas hoses shall be disconnected from the manifold/cylinder for the stoppage of work on the day and to be locked at manifold or cylinder side.

All the gas hose must be tested every 6 months. Only oxygen and acetylene gas's are allowed inside the CSL-MSRU premises.

14.3 Gas Cylinders

Before use, all gas cylinders must be fixed and secured in an upright position, and placed at a safe distance from any heat

When the cylinders are not in use, the valves must be closed. Prior to fitting the regulator, the valve should be opened slightly to blow away any dust or grit from the

Oxygen regulator valves or fittings should be free of Oil and grease to prevent spontaneous combustion in the case of any oxygen leakage.

Cylinders should be kept and moved in purpose built trolleys, when attempting to move cylinders not mounted on trolleys, the regulators and hose must be detached.

If cylinders are to be lifted by crane, they should be secured in a special carrier. On no account they should be lifted by holding the valve as they are not designed to take the stress and no attempt must be made to lift them with chains, ropes or slings as there are chances for it to slip.

Oxygen cylinders and fuel gas cylinders must be stored well apart, at least 6 meters in open space, to prevent an explosive mixture forming from any leakage.

All fuel gases (Acetylene) whether full or empty, must be stored upright and not in a lying position they should be stored separately.

The cylinders should be shielded from direct sun light, or other heat source, to avoid the buildup of excess internal pressure. Valid certificates of cylinders shall be produced while bringing the cylinders to be yard.

15 SURFACE PREPARATION

Surface preparation includes activities such as buffing, grinding etc. The control measures for these activities are discussed in the power tools section in this book.

Surface preparation is also done by blasting using iron shots, copper slag or high pressured water (hydro blasting). Suitable blasting suites, hoods with coolant tubes shall be used while doing such operation. Barricade with warnings to be erected while blasting operations are being carried out.

16 PAINTING

Smoking or any hot working (welding/gas cutting etc) in the vicinity of painting activity is prohibited. Electrical equipments and fittings in the vicinity should be flame proof. For maintaining the air current, blowers should be used at one end and exhaust blowers at the other end.

While painting inside confined spaces, workers should wear air lines respirators with close fitting rubber masks and the equipments should be of the type that the user himself is able to regulate the air pressure.

A worker inside the confined space should be aided by one helper who could be contacted in case of an emergency through a suitable arrangement.

17 WORKING AT HEIGHTS

A suitable means of access and egress must be provided for all working places which cannot be reached from ground level. All work places that are 2 meters or above and does not have a proper working platform, scaffolding are to be made available. All platform structures / scaffolding shall be only erected, altered or dismantled by the authorized scaffolder. The certified scaffolding will have a green tag near the access and if it is not certified, red tag is placed

near the access. Certification of scaffolding done by QHSE Team. Scaffolding requirements are





Red Tag

Green tag

The key points to be observed when erecting scaffolding are.

- The ground must be firm enough to carry the weight of the scaffold, and the load the scaffolding will be carrying.
- There should not be any gaps in the working platform
- Hand rails with mid rails at 1 meter and half meter height should be ensured for the working platform
- working platform. Access ladders are to be provided Access ladders shall be provided to reach the zig zag manner if the height is more than 2 meter.
 - Toe boards must be provided on the working Scaffolding materials must be inspected by CSLplatform.
 - MSRU QHSE team and it shall be made of MS.
- Secondary Platform must be place if the scaffolding height more than 6 meters.
- Scaffolding validity is 15 days from the issue date after 15 days re inspection must be requires.

Full body Harness

areas where it is liable to fall a full body harness shall be worn. The full body harness should be anchored on a rigid structure, and length of the lanyard should be minimized in such a way that the fall height will be minimal. Anchoring When it is necessary to work in temporary work platform hook shall be of scaffold hook.



18 WORKING OVER WATER

Where work takes place over or near water, the following precautions shall be ensured.

- Suitable hand rails shall be ensured to prevent fall of persons into water also full body harness must be worn A

 - Safety net shall be used wherever practicable. Buoyancy aids shall be made available near the work

19 CONFINED SPACE

The term "Confined spaces" covers a great variety of inadequate in hazardous concentration of toxic or flammable gases or vapors. Daily inspection of confined spaces to be done before commencing the operation on the day or shift and details are available at access of the space. Continuous potentially dangerous places to work because workers may get trapped monitoring of the space is required if situation warrants. (Refer CSL Confined space entry procedure for details) are therefore workplaces which have limited access and spaces Confined ventilation.

Very often the dangerous atmosphere can occur in confined welding, painting, and flame-cutting or the use of adhesives Confined space is also liable to become deficient in oxygen. space as a result of the work being done, for instance, and solvents.

The following guidelines to follow while entering into confined spaces.

- Ensure adequate ventilation prior to entry and constant circulation while personnel are inside. Flameproof blowers shall be used where containing hydrocarbons in the spaces.
 - Use only 24V hand lamps while working in confined charge.
- Petroleum and Hot work certificates to be obtained from Petroleum and Safety Organization (PESO) while entry or do hot work in fuel tanks. (Refer CSL Confined space entry procdure)



20 HAND TOOLS AND POWER TOOLS

All personnel using hand or power tools shall be made aware of any dangers which may arise during their use. Adequate supervision must be provided to ensure that the use of such tools is correct and safely performed.



20.1 Hand tools

Hand tools are among the simplest of our work aids and the hazards associated with them are simple and well understood. Because of this simplicity, the safety precautions associated with them are often ignored or forgotten, to the users subsequent regret.

The main cause of injury is the general misuse of tools, the use of unsuitable or poorly maintained tool and improper storage. Injuries can of course be caused by breakage, it is therefore essential that only tools manufactured from the best materials by reputable tool companies are used.

Misuse of tools causes many problems, the use of screwdrivers as chisels, spanners to hammer nails, and pliers to screw up or unscrew nuts are prime examples of this common misuse.



When working at elevated location, all tools should be placed in a tool box to prevent loose tools being dropped from the heights. Where there is a risk of injury from flying objects such as striking two hard surfaces together, e.g. hammer, chisel, punch or similar articles, better to wear an eye protection.

20.1.1Hammer

The faces of hammers should be kept clean and free from grease, and be of sound condition (not pitter or broken edged) and in good shape (Not mushroomed)

Wooden shafts must be of the correct size and securely fixed to the hammer head with fitting wedges – They must be kept from oil and grease and undamaged. Crack or split shafts must not be used.

20.1.2Chisels and punches

There are several types of cold chisels and punches. These must be of good quality materials, properly maintained and inspected, especially for mushrooming of head. All chisels and punches should be dressed frequently to maintain a safe profile.

Cutting edges should be kept sharp to permit accurate working and to avoid the hazards arising from unnecessary hammer striking.

20.1.3Files

A file must never be used without a correct fitting handle; this is to prevent the tang from causing injury to the hand.

Oil must never be applied to files; they must never be struck by other tools as they are brittle and will shatter. To maintain files when clogged with filings clean out the teeth with a file card or fine wire brush.

20.1.4Screw Drivers

Screwdrivers are probably the most common and abused of all the hand tools. When using a screwdriver, make sure that the blade fits the slot in the screw properly. Too large or too small a blade will damage the screw, and not work efficiently. Screw driver blades must be kept square and have a patter to the end.

The shanks are not designed to withstand twisting strain from pliers or grips, which are often mistakenly applied to obtain additional leverage on a stubborn screw. Never expose the blade to excessive heat as this alters the temper of the steel making it too soft or too brittle for this job.

Do not use screwdrivers as scrapers, chisels or levers and the handles may split if hammered. Serious puncture wounds can be sustained as the result of carrying screwdrivers in the pocket of clothing or coveralls.

20.1.5Hacksaws

When using hacksaws, select the correct blades for the work to be carried out. Thick materials require coarse blades to allow chippings to escape. Thin hard materials require a fine blade. Always ensure that at least three consecutive teeth are in contact with the work.

The blade should always be correctly tensioned in the frame, taut but not over tensioned. Use a steady, forward cutting

stroke with just sufficient pressure to cut through the material.

After use when the hacksaw is to be stored, the tension on the blade should be released, and re-tensioned before future

20.1.6 Spanners and wrenches

Always select a spanner which exactly fits the nut or bolt head, never use packing pieces to make the spanner fit as they may slip, causing injury, and also damage the hexagonal contour of the nut or bolt head.

Open-ended spanners should not be tilted. Ring spanners are probably the strongest if they can be used in a particular situation, less chance of slipping.

Pieces of pipe or similar device must not be placed over the end of spanners as extensions to increase the torque.

When using adjustable wrenches, fit tightly against the faces of the nut or bolt head and apply the torque in the direction of the fixed jaw to prevent the spanner from opening.

Spanners and wrenches should not be exposed to excessive heat, or be ground in order to alter their shape as this may ruin the temper of the working parts.

Periodically inspect all spanners and wrenches for any signs of damage or wear. All worn or damaged tools should be discarded or where necessary, moving parts replaced.

20.2 Powered Portable Tools

The efficient and safe use of all powered tools can come only through proper maintenance and from adequate supervision. The power from this type of equipment is usually supplied from Compressed air or electricity.

20.2.1 Pneumatic Tools

All compressed air hose must have standard hose couplings, never use jubilee clips or similar fittings. Tools required clean air and correct lubrication for smooth functioning of the same.

20.2.2 Electrical Tools

body type. Portable electric power tools must not be used if any defect is suspected or any damage apparent. Repair and routine maintenance shall be carried out by trained and All electrical hand tools shall be of double insulated and fiber qualified electricians.

Only chuck keys of the correct type shall be used to operate chucks. Operators shall ensure that the key is removed from the chuck before operating the equipment and ideally, clipped to the cable to avoid improvisation.

20.2.3 Powdered Disc Grinders

impact of the disc to prevent damage and possible disintegration of the disc. The RPM of the grinding machine to use. Care must be taken to avoid knocking or sudden General operation applies equally to both types. The security of the disc and condition must be checked before attempting Powered disc grinders can be air or electrically driven. should be lower than the RPM of the grinding disk

use excessive pressure. Allow the disc to come a stop before Disc that are chipped, out of true or out of adjustment must never be used. Apply the disc to the work piece and do not laying the grinder down. Impact protection must be worn.

Sparks from the disc may ignite flammable materials, or cause injury to personnel in the area.

20.2.4Compressed Air

it is delivered at high pressure. Iron dust and rust particles may be present in compressed air. If it enters the body, it Extreme caution must be used when using compressed air, as can rupture internal organs and cause serious injury and even Do not attempt to clean off coveralls or clothing as it can force harmful particles through the skin.

21 WORKING ON MACHINE TOOLS AND MACHINERIES

While working with Machine tools and machineries the following precautions should be taken.

- Authorized persons should be allowed to use a machine tools and machineries
- Suitable eye & hand protections shall be worn
- Ensure sufficient illumination at the point of operation
- In wood planing machines, Push sticks and push blocks should be used for guiding the wood to the planing machines ς w. 4.
- Stand at a safe distance from the machineries to protect the operator from kick backs, flying materials, moving machinery parts etc. 5.
- Switch off the machine after use Ensure machinery guards in place
- Ensure lubrication oil or coolants are not spillover near and on the machines. 9.7.8

22 HANDLING ELECTRICITY

The main hazards in electrical works are electrocution, burns, fire and explosion.

- All wires must be treated as live wires until it is positively known that they are dead
 - No repairs are to be made to electrical equipments by anyone except qualified authorized electricians. 2
 - Never use an electric light extension cord unless it has an approved insulated handle and standard lamp guard. ω.
 - All portable equipments must be grounded
- Always wear rubber gloves when working around circuits of 110 volts or above 4. 7.
- Do not overload or overuse circuits
- Before starting any repair works or resuming the supply after the repair on electrical installations, Clearance from proper authority should be taken. . . .

- 8. Before resuming the power supply it should be ensured that the grounding of the line or equipment at the work spot has been removed and all men are off the line or equipment
- 9. If any one comes in contact with live wires or cable and becomes unable to release his grip on the wires, do not attempt to pull him off with bare hands. Shut off the current and protect the hands with rubber gloves or if they are not available, use thick fold of dry clothes to cover hands before attempting to release the victim. If wires are directly on top of the victim use a dry stalk to remove them

23 MANUAL HANDLING

Manual handling is a process where the person is prime source of power in moving material and equipment. It includes lifting, pilling, pushing, carrying or moving.

Correct manual lifting and handling can help prevent strains and backaches. Once your back has been injured, that weakness can remain with you for the rest of your life.

To avoid injury, follow these guidelines:

Asses the weight of the load, get help if it is beyond your capacity use mechanical or hydraulic equipment.

Size up the job make sure you have a clear path way to where the load is going. Look for nails or splitters and wear gloves where appropriate.

Adopt the correct stance stand close to the object with your feet apart, giving a balanced position. One foot advance of the other, pointing in the direction you intend to move.

Bend your knees to a crouch position, keeping your chin tucked in and your back straight (not necessarily vertical)


Take a firm grip with the palm and roots of the fingers and thumb, keeping your arms as close to the body as

possible. Keep your shoulders level and face the direction of travel.

Lift with your leg muscles, not back muscles. Carry out the lifting movements smoothly, do not jerk or twits.

Utilize body weight to create momentum and forward with the load.

Use the reverse procedure when setting down the load.



24 LIFTING OPERATIONS

Lifting machineries such as cranes, winches hoists and other lifting tools and tackles include (wire rope sling, web sling, D Shackles, eye bolts chain block etc.) are widely being used in CSL-MSRU.

Lifting must, by its very nature, be regarded as a hazardous operation. The improper usage and inadequate maintenance of lifting tools and machineries may lead to serious consequence to life and property.

Operational Guide lines are:

1. Only authorized, competent persons are allowed to operate cranes.

- 2. Crane operators must only take instruction from designated rigger.
- 3. At no time should the crane be left unattended, even for short periods, unless all loads have been removed, the power off and brakes are to be applied.
 - Crane and Transporter (Commeto) within CSL-MSRU area must be accompanied by a rigger or banks men, they will guide the movements safely.
 Do not use rigging and slinging unless you have been
 - Do not use rigging and slinging unless you have been trained and instructed to do so.
- Use correct lifting hooks fitted with safety latches or shaped to prevent accidental displacement of slings.
- Position the lifting hook over the load as to prevent the load swinging when it is raised.
 - 8. Do not tie a knot in a chain to make it shorter, or attempt to drag if from under a load.
- Check wire ropes for kinks, signs of wear and broken wires.

10.All lifting equipment must have valid test certificates

issued by competent person. 11.All lifting equipment must be test once in a year.



Wire rope - Lifting chart

1,16,	Wire Rope Dlameter	Rope	Single Sing	Two le	legged Sling	g with diffe Angles	i i	included
KE. KE. <th>han</th> <th>m.m</th> <th></th> <th>Č</th> <th>Č</th> <th>e c</th> <th>Č</th> <th>i i</th>	han	m.m		Č	Č	e c	Č	i i
8 5.6. 1.				5	200	-04	20	120
8 7.00 1000 1000 1000 1000 1000 1000 1000 1000 1000 1000 1000 1000 1000 11280			ų į	Ye.	ų į	N. P.	2	Y S
13 17.00 18.00 17.00 18.00 17.00 13 1020 20.00 20.10 18.00 11.00 13 13.80 20.00 20.10 18.00 11.00 13 13.80 20.00 20.10 18.00 17.00 14 17.20 28.40 29.20 22.00 14.00 15 12.20 28.40 28.20 22.20 14.00 16 21.20 28.40 28.40 40.00 14.00 18 28.20 61.00 82.20 28.20 27.20 19 20.20 61.00 82.00 82.00 82.00 82.00 22 44.00 88.00 82.40 42.00 42.00 23 44.00 88.00 82.40 42.40 42.00 24 44.00 88.00 82.40 42.40 42.00 25 67.70 113.40 113.00 113.00 25 <th< td=""><td>19/16</td><td>x (</td><td>05.50</td><td>0001</td><td>0701</td><td></td><td>000</td><td>05.50</td></th<>	19/16	x (05.50	0001	0701		000	05.50
10 10 20 20 20 20 20 20	0/0	, ;	0000	240	277	1240	0707	COLUMN TO A COLUMN
11 1180 2000 2000 1470 1480 13 1180 2000 2000 2000 1480 1480 14 1180 2700 2700 2700 2700 1480 15 1120 3840 3720 2200 2420 16 2120 4300 2700 2700 1400 2420 17 2570 5140 4470 4490 2200 2720 2420 18 2820 5820 7820 7440 4980 7440 4420		2	2000	0000	00000	20000	2000	0000
15 11500 2700 7500 7500 1500 1500 14 11720 3840 3830 2800 2810 2720 15 1170 3810 3710 3710 3610 3210 2720 16 2170 4740 4710 3610 4470 4610 3610 18 2820 5840 5840 5810 4300 4000 4000 21 4700 8200 5820 7520 7400 4000 22 4400 8200 7550 7400 7500 4240 24 4400 8200 8240 7620 4240 5820 27 4400 8200 8240 7620 7620 6240 27 4400 8200 7250 7400 7700 28 1770 12840 17210 7620 7220 29 1770 12840 17200 7700 7700 </td <td>01//</td> <td>7.7</td> <td>000,</td> <td>0000</td> <td>OTON</td> <td>TOCO</td> <td>0/17</td> <td>0001</td>	01//	7.7	000,	0000	OTON	TOCO	0/17	0001
1.0	1	1 1	0 1	0000	0000	2220	0000	0 0
15	1/10		000	0000	0 0 0	0/0/	006	1000
15 1720 3510 3720 3510 2720 1720 1720 3510 37	07/0	†	07/1	0440	0000	0000	0747	7/70
15 7170 5140 4970 4870 4850 18 2820 5540 5470 4900 4000 4000 21 3570 5140 5420 5510 4000 4000 21 3570 7140 6220 5820 7140 5820 22 4100 8200 7950 7140 5820 23 4400 8200 7950 7140 5820 24 4400 8200 7950 7140 5820 25 4400 8200 7950 7740 5820 26 5470 1080 1180 8210 6220 27 6470 1170 1180 8210 8210 27 6470 1180 11080 11080 11080 11080 28 5250 11240 12400 8210 8210 8210 29 525 11240 11240 11240 11080 <td>9</td> <td>15</td> <td>1920</td> <td>0.00</td> <td>37.20</td> <td>3370</td> <td>27.20</td> <td>0201</td>	9	15	1920	0.00	37.20	3370	27.20	0201
18 2820 5440 5470 4470 3650 19 3050 6100 5920 5310 4000 4000 21 3570 740 5820 7540 7540 4000 22 4400 8200 7550 7440 5020 24 4400 8200 7550 740 6240 27 4400 8200 750 740 5020 27 4400 8200 750 740 5020 27 4400 8200 750 740 770 27 4400 8200 750 740 770 28 1200 11340 10180 8310 29 1200 11340 11080 11000 30 7740 1750 11440 11000 31 1010 1100 11000 11000 32 1020 1100 11000 11000 34 </td <td>8/6</td> <td>Ů,</td> <td>2120</td> <td>4240</td> <td>0110</td> <td>3090</td> <td>OLOK</td> <td>0616</td>	8/6	Ů,	2120	4240	0110	3090	OLOK	0616
18 2820 5540 5470 54100 4000 19 2820 5100 5270 7140 670 7140 </td <td>11/16</td> <td>1</td> <td>2570</td> <td>5140</td> <td>4000 C</td> <td>4470</td> <td>26.50</td> <td>2570</td>	11/16	1	2570	5140	4000 C	4470	26.50	2570
11 3050 6100 5910 5810 7820 22 4100 8200 7550 7140 5820 23 4400 8200 7550 7140 5820 24 4400 8200 7550 7140 5820 25 4400 9800 9200 8250 6240 26 5470 10840 11840 9410 7700 27 6770 11700 11840 11080 9610 27 6770 12540 11340 11300 9610 30 7790 15540 17700 14600 11900 31 10750 14600 1870 1450 32 8380 16760 17700 14600 1750 34 10730 18720 16800 1370 35 10730 18720 14600 1750 34 10730 1700 14600 1750	30	35	2820	2640	5470	4500	4000	2820
22 41570 74 A70 6920 7590 740 5820 22 4400 8200 7550 7440 5820 7440 5820 24 4400 8800 7540 7470 9480 6240 6240 24 4400 8800 11340 10180 8210 6240 27 6770 1070 11340 10180 8310 27 6770 12540 12170 1090 9410 20 6770 1310 11040 8310 21 6770 1340 11040 9410 22 6770 1450 14600 11000 30 7790 14740 17700 14470 31 10750 1870 14400 1300 32 10730 1870 14400 14400 34 10730 18400 14400 1450 35 10730 14400 14700	8/1	15	3020	6100	2020	5810	7880	3020
23 4100 88200 7950 7140 5820 23 44100 88400 8540 7640 6240 24 4400 9780 9250 6720 6720 26 5870 11700 11340 10180 8310 27 6270 12540 12170 10940 8910 27 6270 12540 12170 10940 8910 27 6270 12540 12170 10940 8910 27 6270 12540 1710 11800 1440 28 1210 12540 1710 11800 1440 38 1210 1720 1460 1220 1520 38 1210 22280 1770 1440 1440 38 1210 22280 22400 14200 1520 38 1210 22280 22400 1420 12400 40 1770 2480	13/16	2-1	3570	2770	0260	01.00	2070	3570
23 44000 88800 85400 7650 6240 24 4770 9780 9200 8250 6240 26 5850 11700 11840 10180 8310 27 6770 12540 12170 10940 9610 29 6770 12540 11840 9610 30 7790 16560 14600 11500 31 10780 16760 14600 11900 32 8380 16760 14600 1400 34 9650 19300 18720 16800 13700 35 10730 16760 17700 14450 36 10730 18720 16800 13700 37 10730 18720 14600 14200 38 12100 22200 22400 14200 14200 38 12100 22400 27400 14200 14200 40 1570 274	2/8	22	4100	8200	7950	7140	5820	4100
2.1 47.10 9.180 9.200 8220 67.20 2.6 55.50 117.00 118.40 10.18 8210 2.7 62.70 112.40 112.40 10.40 8210 2.7 62.70 125.40 121.70 10.90 8210 2.9 62.70 125.40 121.40 118.00 8210 3.0 77.90 167.60 146.00 119.00 15100 3.2 82.80 167.60 167.60 146.00 119.00 3.4 92.820 167.60 146.00 119.00 15100 3.4 107.80 187.00 144.20 119.00 15100 3.4 107.80 187.00 187.00 142.00 152.00 3.5 107.80 224.00 197.00 142.00 152.00 3.6 107.80 224.00 144.00 152.00 152.00 3.6 107.80 224.00 24.00 24.00 24.00		23	4400	0088	8540	7650	6240	4400
25 5420 10840 10520 9440 7700 26 5220 11700 11340 10180 8510 27 6270 12540 12170 10940 8510 27 6270 12540 13140 11500 9610 30 770 17540 17100 1400 14100 32 9280 16760 16800 13100 1370 34 9650 16800 1370 1370 35 10730 21460 2200 16800 1370 36 10730 21460 2200 15200 15200 36 11780 27400 1780 1780 1620 37 11420 22840 2200 2440 1700 40 1570 2740 2740 1700 41 14220 2840 26160 2340 2520 44 16520 35040 28200 28600	15/16	24	01/1	0816	0500	8250	6/20	7770
26 5850 11700 11840 10180 8810 27 6670 12540 12170 10940 9810 29 6670 12540 11840 11840 11600 32 8380 16260 14600 11000 34 9650 19300 18720 16800 13700 35 10730 18460 17700 14400 14400 36 10730 18720 16800 13700 14400 37 10770 20400 18720 14600 13700 38 10730 21460 22200 14200 14200 38 12780 22840 22400 1700 1700 40 13470 27400 1700 1700 41 14720 28440 27400 1700 44 16520 35040 28200 28200 28200 44 16520 35240 28200 28800	-	20	5420	10840	10520	9440	0022	5420
27 62/70 12540 121/10 110940 8910 30 67/70 115540 11800 9610 30 67/70 115400 11800 9610 32 8380 16760 16260 14600 11900 34 9520 19300 18720 16800 13700 37 10170 20446 20860 18700 17200 37 10470 22280 18700 17200 15200 38 12100 24280 22480 18700 18700 40 15470 24800 22400 19700 17200 40 15470 24800 2700 17200 40 15470 24800 2700 17200 40 15470 24800 24800 2500 40 1770 24800 2500 2500 41 1750 3200 25800 25800 42 1750		26	5850	11700	11340	10180	8310	5850
2D 6 / 7 / 0 135 / 0 135 / 0 135 / 0 145 / 0 135 / 0 145 / 0 1	1.1/16	17.	6270	12540	121/0	10940	8910	6270
30 7790 15540 15740 11050 32 8380 16760 16260 14600 11000 34 9650 10930 18720 16800 13700 34 9650 10930 18720 16800 13700 35 10730 21460 22200 18700 14500 36 10770 22860 18700 14520 37 11740 22200 1900 17200 40 13470 22840 22100 17200 41 14220 22840 27400 17200 42 14220 28440 27400 27400 43 1570 35040 2800 2800 44 16520 35340 32000 28800 25500 44 16520 35340 32800 28800 25800 53 22870 35200 28800 25800 54 16520 35200	1.1/8	67	6770	135/10	13140	11800	0196	6770
32 S\$S\$O 16760 16260 14600 11900 34 9620 1920 1700 14500 13700 34 9650 1870 1600 13700 13700 35 10170 21460 22200 19700 1420 38 12100 22200 22400 1970 1420 40 14400 22200 2340 1720 40 14770 2640 2440 1420 40 14770 2640 2440 1700 41 14770 28440 2740 1700 42 14770 2740 2740 2740 43 16520 35040 2700 2740 44 17620 3200 2580 2580 53 2420 3200 2580 2580 54 17620 3200 2580 2580 54 17620 3200 2580 2580		30	7790	15540	15100	13540	11050	7790
35 9250 18460 17000 16080 13100 34 9650 10300 18720 16800 13700 35 10730 21460 20860 18700 14500 36 10730 21460 20860 18700 15250 38 12100 27200 1970 15230 40 12780 22860 27400 17200 41 12420 22840 27400 18150 42 1480 22840 27400 2000 43 17750 31500 22800 22800 22800 44 16520 33040 22800 22800 25800 44 16520 35240 37400 27400 27500 54 24400 35800 28800 28500 25500 54 2450 35800 35800 25800 25600 55 2787 4770 4700 48700	1.1/4	32	8380	16760	16260	14600	11900	8380
3.4 9650 19300 18720 16800 13700 3.5 107170 20340 19770 17700 14450 3.6 107170 20460 18700 14520 15200 3.7 11430 22840 21000 17200 3.9 12100 22420 21000 17200 3.9 12420 22840 21000 17200 4.1 14220 28400 24800 2000 4.2 14220 28240 27400 21000 4.3 1570 31500 27400 2000 4.4 16520 38240 28200 28800 28500 4.4 16520 38240 32000 28800 28500 5.3 22870 38200 32800 28500 28500 5.4 16520 38240 3800 32500 28500 5.4 24400 47300 47300 47300 47300		99	9230	18460	DOG/T	16080	COLET	9230
35 10170 D0.440 19720 17700 14420 36 10730 224860 22220 12520 15230 37 14420 22280 12000 17200 38 12100 22480 22400 17200 40 15770 2640 24400 17200 41 15770 26940 24800 22000 43 15770 35040 25000 24800 22000 44 16520 35040 32000 25500 25000 54 16520 35040 32000 25500 25000 54 17620 35400 32000 25500 25000 54 17620 35400 32000 25000 25000 54 17620 35240 34200 25800 25000 54 17620 35240 34200 25000 25000 54 24200 34240 44400 3600 3		34	9650	19300	18720	16800	13700	9650
\$6 10730 21460 20860 18700 15250 \$7 11420 22200 24200 15200 15200 \$8 12100 24200 22400 15200 15200 \$9 12100 24400 22400 25440 21000 17000 \$4 14220 28640 27600 22400 21300 17000 \$4 14220 28640 27600 22400 21300 21300 \$4 16520 33040 22600 26100 21300 24000 \$4 16520 33040 32000 26000 25000 25000 \$4 16520 33040 32000 25800 25000 25000 \$5 22870 37400 37400 37400 37000 26500 \$5 22870 44700 32800 32800 32800 32800 \$5 24400 47300 47300 4700 4700 4700	1.3/8	20	10170	20340	19720	17700	14420	10170
87 11420 222800 22200 19960 15230 38 12100 224200 21000 17200 39 12100 25200 21000 17700 40 132470 26940 26160 23400 19100 41 14220 22960 24800 20100 20100 43 16750 31500 25000 24800 20100 44 16220 35240 25800 25800 25000 44 16270 31500 22800 26950 25000 48 16870 37910 30680 30600 25050 53 22870 44700 37400 35000 26050 54 24400 44700 35800 32500 35000 54 24400 44700 35800 32500 32500 55 22870 4500 47300 47300 4700 61 36220 6640 4		36	10730	21460	20860	18700	15250	10730
38 12100 23400 23400 21200 17200 40 15770 26540 25400 18400 18700 40 15470 26540 25400 24800 22000 41 14790 28940 27400 24800 22000 43 16750 35040 32000 28500 23500 44 16520 35040 32000 28500 25500 53 22870 43740 44500 25800 25000 54 24800 44700 36800 32500 25000 54 24800 44700 44400 32800 32500 54 24800 44700 44400 32800 32500 54 27270 44400 32800 32500 54 27270 44400 32800 44700 61 30520 60540 52800 45000 63 32520 60540 52800 4		18	11430	22860	00777	19960	08791	11430
39 17780 25500 25400 27200 18150 40 14220 28440 26160 28340 20200 41 14220 28480 27600 26100 21300 43 17770 31500 25000 26100 21300 44 16520 35040 32000 25500 25500 44 1770 31500 32000 25500 25500 53 22870 32800 32800 25500 54 24400 44700 37400 36500 54 24400 47800 47800 35500 57 27270 47400 35800 32500 54 24400 47800 47800 4700 57 27270 47400 5800 32800 45200 61 30320 60640 5800 52600 45200 61 30220 6040 52800 45200 61	1.1/2	88	12100	21200	23110	21000	17200	12100
40 13470 26940 26160 23440 19100 41 14220 259400 27400 24800 20100 43 16750 31500 26000 26100 21000 44 16520 38040 28000 28500 25500 46 17620 38240 38000 25000 26500 54 27670 37540 37400 26500 26500 55 22870 45740 47700 37400 26500 57 27770 45740 47700 37400 34700 57 27870 57800 47300 42500 34700 61 36320 6640 58800 42500 42700 63 3700 67400 67400 7700 47300 61 36220 6640 88100 42000 42000 62 37080 74100 68100 42000 63 37080 7410	Consumor Services	60	12780	25560	24800	22200	05181	12780
41 14220 28440 27600 24800 20200 43 17780 31750 37400 21000 21000 43 17750 315040 32000 26800 23500 44 17620 32400 32600 28500 25500 53 22420 32200 25800 25000 25000 54 24400 30500 26800 32500 54 24400 34700 44400 32800 32500 54 24400 44400 32800 32500 32500 54 2420 44400 44400 32800 32500 54 2420 44400 44400 32800 32500 54 2420 44400 44400 32800 32500 55 2420 44500 44700 44700 44700 61 3620 6040 52800 45000 44700 61 3420 6250 <td></td> <td>04</td> <td>13470</td> <td>26940</td> <td>26160</td> <td>23440</td> <td>19100</td> <td>13470</td>		04	13470	26940	26160	23440	19100	13470
42 14980 299C0 25000 26100 21300 43 14770 34500 35000 28800 28500 44 17620 35040 32000 28800 25500 48 18870 37940 36800 35800 25500 53 22870 37940 34000 26500 25500 54 24800 44700 35800 32500 32500 57 27870 44700 44400 38800 32500 57 27870 47640 47800 4700 61 30320 60640 58800 52800 43200 63 32220 60640 58800 52800 43200 64 30520 60640 58800 52800 45200 67 34700 67400 67400 67500 45200 67 34700 67400 67500 45200 67 34700 67400 54	1.5/8	41	14220	28440	27600	24800	20200	14220
4.3 1.57.50 3.1.500 3.0000 27400 22400 4.6 1.6220 382040 28800 28500 4.6 1.620 38240 32000 25800 5.1 2.1570 43740 34200 26950 5.3 2.2870 45740 47000 30500 26950 5.4 2.4400 48800 47300 42500 34700 5.7 2.7270 45400 42500 34700 42500 6.1 3.0320 6040 47300 42500 44700 6.1 3.0320 6040 47300 42500 4500 6.1 3.0220 6540 5280 45200 4500 6.2 3.2520 6540 6560 4500 47300 6.3 3.2520 6540 6560 4500 47300 6.3 3.2520 6540 6560 4500 47300 6.4 3.2520 6540 6560 <td></td> <td>42</td> <td>11980</td> <td>29960</td> <td>29000</td> <td>26100</td> <td>21300</td> <td>11980</td>		42	11980	29960	29000	26100	21300	11980
44 16520 35040 32000 28800 25500 46 17620 37540 36000 30600 25000 71 21570 47040 44700 37400 35800 53 22400 48740 47400 37400 37500 54 22400 48870 47400 37400 3700 57 27270 48870 47400 3700 32200 63 32520 60540 58800 48700 44700 64 37700 65400 58800 45200 46200 67 34700 65400 58800 45200 46700 67 34700 65400 55800 45200 46700 67 34700 65400 55800 45200 52600 67 34700 67400 67400 67400 57400 5600 67 34700 74100 74700 5600 52600 7<		4.3	15750	31500	30500	27400	22400	15750
46 1/620 35240 34200 30600 25900 61 18970 37810 30800 30900 26950 51 21870 47940 44400 39800 32500 54 224400 48800 47500 47100 34700 57 27270 54740 47300 42500 34700 61 30320 60640 58800 52800 43200 63 34700 67400 67400 49400 49400 67 34700 67400 67500 49500 49500 67 34700 67400 67500 49500 49500 67 34700 67400 67500 49500 52600 69 3208 7800 68500 52600 69 3400 7800 67500 52600 60 3400 7480 6900 52600 60 3400 7480 64500 5600	1.3/4	44	16520	33040	32000	28800	23500	16520
48 18970 37940 36800 33000 26950 51 21570 45740 44700 35800 32500 53 22870 45740 44700 35800 35000 54 24400 47800 47500 34700 57 27870 57800 4700 38700 61 30320 60640 58800 52800 43200 62 32220 60640 58800 52800 43200 64 37200 67400 67400 47000 46200 65 34700 67400 67500 46200 46200 67 37080 74160 71800 68700 52600 67 37080 74160 7700 68700 5600 70 40800 7800 77100 5800 71 4700 84500 77100 5800 72 4800 9720 77100 6900		46	17620	35240	00758	30600	00057	1/620
51 71570 41040 41700 37400 30600 53 22420 45740 44400 32800 32500 54 22420 48800 47800 42500 34700 57 27270 56760 48700 44700 44700 61 2820 60540 58800 45200 45200 63 32520 60540 58800 45200 45200 64 37700 67400 67100 58200 45200 67 34700 67400 67300 64500 52600 67 34700 67400 67300 64500 52600 70 4080 7480 7480 5600 52600 70 4080 7480 7480 5600 5500 70 4080 7700 7700 7700 5600 70 4720 7700 7700 7700 7700 70 4860 <td< td=""><td>1.7/8</td><td>81/</td><td>18970</td><td>37940</td><td>36800</td><td>33000</td><td>02692</td><td>18970</td></td<>	1.7/8	81/	18970	37940	36800	33000	02692	18970
53 22870 45740 44400 39800 32500 54 22400 48800 47500 42500 34700 57 27270 54540 54800 42500 34700 61 30220 60640 53800 43700 40700 63 32520 65040 53800 45200 64 37700 67400 65100 46200 67 34700 67400 67300 49300 67 34700 67400 67300 49300 67 34700 67400 67300 64500 52600 67 34700 67400 67500 64500 52600 69 34500 7800 7000 54500 5600 70 4080 8400 7100 5960 73 4700 89400 81500 7700 74 4700 89400 91500 6700 75 4800 <	C	1.5	21520	43040	41700	37400	00908	21520
54 24400 48800 47300 424500 384700 57 72720 74540 57800 47300 384700 59 78780 5650 49300 49300 48200 61 30320 60640 58800 52800 45200 63 32220 60540 58300 45200 45200 67 34700 67400 67400 45200 45200 67 34700 67400 67500 45200 52600 69 3400 67400 67500 4500 52600 67 34700 67400 67500 4500 52600 69 3400 7800 7100 5800 70 4080 8400 7100 5900 72 4800 8400 7700 6300 73 4800 9420 8420 6500 70 4800 9420 7000 7000 79<		53	22870	45740	44400	39800	32500	22870
57 27270 5A5AO 5A80O A730O A870O 61 30820 65640 5880O 4930O 4070O 61 30820 65640 5880O 4520O 63 32520 65040 5810O 4620O 64 3470O 6740O 6730O 4780O 67 3708O 7416O 7180O 6450O 5260O 69 3708O 7416O 7180O 6870O 5260O 70 4082O 710O 560O 5260O 70 4082O 710O 560O 5260O 70 4082O 710O 560O 5260O 71 420OO 840O 710O 596OO 72 4240O 845OO 7710O 596OO 75 4840O 9420O 7710O 596OO 75 4840O 9720O 7710O 6520O 74 4840O 9720O 9420O 7070O <	2.1/8	54	24400	48800	47300	42500	34700	24400
59 78780 676.00 78800 49300 40700 61 30320 60640 58800 52800 48200 63 32220 65040 58800 52800 48200 64 37700 67700 67300 47800 47800 67 37700 67400 67300 67500 52600 69 37450 71800 64500 52600 70 4700 74500 74500 58000 71 4700 84700 58000 71 4700 84500 7700 72 4800 84500 7700 75 4800 9750 7700 70 4800 9750 9750 70 4800 9750 9750 70 4800 9750 9750 70 4800 10240 10250 70 4800 10250 1950 70 4800 <	2.1/1	22	07070	54540	52800	47300	38700	27270
61 30520 60640 52800 52800 45200 653 200 653 200 653 60 650 650 650 650 650 650 650 650 650	- Contract Contract	or LC	28280	000000	54800	49300	40200	28280
6.3 3.22.20 6.50400 6.51000 45.5000 45.200 6.7 3.3.700 6.7400 6.7300 6.7500 4.7300 4.7300 6.7 3.7080 7.4160 7.1800 6.4500 5.2600 6.9 3.7080 7.4160 7.1800 6.4500 5.2600 7.0 4.000 8.4000 7.100 5.8000 5.8000 7.1 4.7000 8.4000 8.1500 7.7100 5.9600 7.5 4.7000 8.4000 9.1600 7.7100 5.9600 7.5 4.7000 8.4000 9.1600 8.200 6.7200 7.6 4.800 9.7200 9.4200 8.4500 6.7000 7.7 4.800 9.7200 9.4200 8.7500 7.000 7.9 4.800 9.600 10.2400 10.2500 10.9500 7.8000 8.1 5.10 1.007.40 10.6500 15600 7.8000	2.3/8	61	30320	60640	58800	52800	43200	30320
67 34700 67400 67500 678700 47800 67500	- 1	20	32520	65040	63100	56600	46200	32520
65 34700 69400 60400 60400 49300 655 35080 69400 78500 64500 556000 659 69400 55000 64500 55000 659 69400 55000 659 69400 55000 659 69400 55000 69400 55000 69400 55000 71 4200 89400 841500 7100 55000 75 44700 89400 91600 82200 67200 75 4600 94200 94200 94200 77 54800 94200 94200 105400 105500 75000 75000 105400 105500 75000 75000 75000 105400 105500 750000 750000 750000 75000 75000 75000 75000 75000 75000 75000 75000 75000 75000 750000 75000 75000 75000 75000 75000 75000 75000 75000 75000 750000 750000 75000 75000 75000 75000 75000 75000 75000 75000 75000 75000 75	×	75	33700	67400	002300	58700	47800	33700
67 \$7/080 741500 74800 64500 526000 526000 526		5 H	34700	00400	67300	60400	49300	34700
70 42450 75500	2.5/8	20	27080	74160	71800	64500	22600	27080
71 4700 84000 81500 73100 59600 73100 59600 73100 59600 73100 59500 73100 59500 73100 59500 73100 59500 73100 59500 731000 731000 73100 73100 73100 73100 73100 73100 73100 73100 73100 731000 73100 73100 73100 73100 73100 73100 73100 73100 73100 73100 731000 73100 73100 73100 73100 73100 73100 73100 73100 73100 731000 73100	0 214	0 0	00000	01070	70200	71000	00000	00000
73 47/00 89400 87/00 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63500 67/100 7/100 63500 7/100 63500 7/100 63500 7/100 63500 7/100 63/100 7/100 63/100 7/100 63/100 7/100 63/100 7/100 63/100 7/100 63/100 7/100 7/100 63/100 7/100 7/100 63/100 7/100		7-1	00000	00000	00110	73400	00000	00000
75 47250 97500 91600 82200 6/200 76 48600 97200 94200 87500 69000 77 49800 94000 91600 91500 70700 79 52.00 105400 102500 91500 78000	3// 6		44.000	XC400	20000	77700	000459	44 /00
76 48600 97200 97500 84500 70000 77 48800 96700 70700 70700 79 52700 105400 102500 91500 78000 81 54870 100740 106500 95500 78000		12	17750	94500	00000	82200	67200	17.050
77 49800 99600 96600 86700 70700 70700 70700 79 52700 105400 102500 91500 78000 81 57870 109740 106500 95500 78000	c	20	48600	97200	94200	84500	00065	78600
79 52/00 105400 102500 91300 /4800 81 5/18/0 109//0 106500 95500 /8000	MAC TO STATE	27	49800	00566	90000	86700	20700	49800
81 5/8/0 109/40 106500 95500 /8000	3.1/8	6/	52700	105400	102500	91300	74800	52700
		81	5/8/0	109740	106500	05500	78000	5/3/0

Web sling colour chart


Color	WLL (Straight lift)
Valdet	ton 1
Green	2 tons
Yellow	3 tons
Grey	4 tons
Eed	2,0000
Brows	6 tens
Blue	& forces
Orange	10 tons or above

Web sling lifting chart

			AS	W IN KG WI	TH ONE WEL	SWL IN KG WITH ONE WEBBING SLING	m	SWL IN F	WITH TW	SWL IN KG WITH TWO WEBBING SLINGS	SENINGS
/		Lifting method	straight	eyoup	basket	basket, inclination angle §	ngle §		angle of	angle of inclination §	
/ WE				~ ○	9 % ===================================	S=7-45°	fom-to \$=45°-60°	straight up to \$=45°	Son of the state o	straight from-to \$=45°-60°	choke from-to \$=45°-60°
Art. No.		Factor	1.0	8.0	2.0	1.4	1.0	1.4	1.12	1.0	8.0
HFS01	1000kg	violet	1000	800	2000	1400	1000	1400	1120	1000	800
HFS02	2000kg	dheen	2000	1600	4000	2800	2000	2800	2240	2000	1600
HFS03	3000kg	yellow	3000	2400	0009	4200	3000	4200	3360	3000	2400
HFS04	4000kg	grey	4000	3200	8000	2600	4000	2600	4480	4000	3200
HFS05	5000kg	led.	2000	4000	10000	7000	2000	7000	9800	9000	4000
HFS06	6000kg	Brown	9009	4800	12000	8400	0009	8400	6720	9009	4800
HFS08	8000kg	sine	8000	6400	16000	11200	8000	11200	0968	8000	6400
HFS010	10000kg	Orange	10000	8000	20000	14000	10000	14000	11200	10000	8300

25. BASIC RIGGING SIGNALS, TACKLES AND METHODS


	Cower THE LOAD	SLOWLY LOWER LOAD	dispressions of the following the body of	
Z	Hoist Iower	Hoist Iower - slow	DOG everyth ing – pause the motion	
СОММОИ		SLOWLY RAISE LOAD	Agreement in the part of the p	STOP
	Hoist up	Hoist up- slow	Stop – motion is finished	Emergency stop -







Wire rope slings with thimble **Bow and D shackle**





Slinging Methods

Web sling

26.DOCKING & UNDOCKING

activities in the yard. The following precautions are to be Docking and undocking of the ship is one of the major taken.

- 1. Docking and Undocking operations should be done only with the guidance of the dock Master, pilots or authorized person from CSL-MSRU,
 - Pre requisite checklist to be filled cleared by CSL-MSRU project manager. 2.
- Tugs or suitable supports should be ensured
- and water currents to be taken care of while planning Tide level, List and Trim of the vessel level, docking plan the docking & undocking €. 4
- Gangways shall be placed in a safe manner after the positioning the vessel 5.
 - Good condition of mooring ropes shall be ensured
 - Suitable floating life vest to be worn if any chance of fall into water bodies. 6.
- Docking and undocking checklist must me follow for each ω.

27.SLIPS, TRIPS AND FALLS

occur in all kinds of work places and under a range of A large portion of injuries at work are caused by slips, trips and falls. Whether on the same level or from height, fall can different conditions.

Some of the common reasons for Slips, Trips and fall are:

- Poor flooring
- Unsuitable foot wear
 - Slippery surfaces
- Obstruction in walk ways
- Poor lighting or restricted vision ω. 4. τ.

6. Undue care and attention.

accidents is by keeping your work-area clean, tidy and free The biggest contribution you can make in preventing such from obstructions.

- Use proper routes and walkways. Avoid short cuts 7;7
- Make sure that any temporary opening in walkways is secularly fenced off. On completion of work, replace
- grating and covers securely. Report to your immediate supervisor whether there are damaged or obstructions on floor surfaces, lack of handrails and fencing as well as inadequate illuminated რ
- Correct use of ladders firm level surface, secured at the top and extended beyond the step-off point or the top and extended beyond the step-off point adequate separate handhold. 4.



28.FIRE

a. Basic chemistry of fire

Any fire, once it starts, will continue to burn as long as there is something to burn and oxygen is present. There must be reasons for a fire to start and the way it burns. There are

reasons for certain substances to be more or less flammable than the others.

b. The nature of fire(combustion)

The combination of a substance with oxygen is called an oxidation process. It is a chemical process. Energy is given off during this process, usually in the form of heat. The oxidation process in case of a fire or combustion is rapid. The burning Production of energy in the form, of heat and light is rapid, so we substance combines with oxygen at a very fast and high rate. can feel the heat and see the light as flames.

c. Elements of fire

The essential requirements of a sustainable fire (combustion) are the presence of three elements, i.e. FUEL, HEAT and supply of free OXYGEN, usually in air (formation of fire triangle)

28.1 Fire Prevention

Prevention is the best form of defense. Fires can be prevented by following some simple rules.

- Don't let rubbish or items accumulate in one area, especially under stairs.
 - Don't overload electrical outlet sockets
- Don't use make shift wiring extensions
- Hot works carried out onboard vessel only through Permit To Work. 2 κ. 4.
- Lighting of incense and candle is not allowed inside your 5.
- Don't store any flammable items inside the room unless it is meant for. 9
- Don't hang clothes to electrical equipments such as fans, AC and in the corridors. Always keep Entry/exit
- Suitably designed equipment and its installation (intrinsic œ.
 - Inspection and maintenance of equipment and electric circuits. 6
- 10. Maintaining and properly using portable equipment and flexible cables.
- 11. Adopting safe working practices and procedures

28.2 Discovery of fire

On discovering of fire, your prompt action could save lives:

- Warn all personal in the area by fire, fire, fire Use first aid fire fighting appliances in that area.
 - If it is not possible, call CSL-MSRU fire service.

must not be tampered with and must Remember: - Firefighting equipment be kept clear of all all obstruction

29.GENERAL PERSONAL FACTORS LEAD AN INCIDENT

should be more vigilant while on duty, otherwise it may lead to The following personal factors are to be taken care of and they ncidents.

- Ensure sound sleep.
- Eat sufficient breakfast.
 - Avoid over eating
- Sickness suffered by any family member or near & dear ones(Frustration) 4.
 - Acute financial crisis

6.5


- Quarrel with others (Emotional disturbance)
 - Over confidence . 8. 9.
- Influence of medications
- Fatigue due to lack of rest

30.0FFICE SAFETY

- Don't stand and talk in front of closed doors which may open suddenly.
 - Walk cautiously around blind corners
- Sit squarely on office chairs, and not on the edge of 3.5
- Running at any time in an office may result in injury from slipping, tripping or collision. Avoid running in offices. 4.
- Walk slowly and cautiously up and down stairs. Use hand rail where possible. 5.

- The gummed strips on envelopes should not be moistened with tongue. ٠.
 - shoes shall heeled exercise extra caution to prevent falls. high Office employees wearing ζ.
 - Don't use lift in case of fire.
- While lift break down, shout for help or make call to **CSL-MSRU Emergency number for help** ფ. <u>ტ</u>

Desk stretch exercise for continuous use of computers



31.WASTE MANAGEMENT

A waste is a material which is discarded or intended to be discarded.

Waste identification and classification

Type of Wastes are classified in CSL-MSRU activities

- Waste Oil/Oil Sludge
- Oil soaked cotton waste
- Used copper slag
- Empty paint drums Zinc Anodes
 - Used Batteries 6.5
- Electronic Waste Steel Scrap
- Industrial Waste . 8. 9.
 - 10.Cut Cable

Waste disposal policy

- No dumping of items in the yard premises and same shall be taken out from the yard as per the QHSE requirement. ÷.
- Respected vendor /agency is the responsible to dispose the waste according to state statutory requirements. 2

32.OCCUPATIONAL HEALTH

ife style diseases and the various physical and chemical hazards. The employees are exposed to various levels of health hazards, Proper awareness about the health hazards is a required for an Occupational health deals with man (both physically and mentally) in relation to his work and work environment. employee to lead a healthy life

The various measures to be taken for reducing Health hazards

1. Employees who are involved in handling hazardous chemical, gases and other substances should be made aware about its

health hazards and the precautions to be taken in handling

- The MSDS of the chemical being handled should be made available to the workers. 7
- Statutory Periodical health checkups should be done by the company ω.
- Non statutory health check up should be done at least once in two years in order to detect Life style diseases such as High Cholesterol, Diabetics, Blood pressure, allergies to any chemical or substances etc 4.
- Employees should maintain all his medical records and should be made available in case of an emergency. 5.
- various personal factors also can lead to accidents and subject Stress of employees that is either job related or caused by the victim to various diseases. 9

33.FIRST AID

First aid is the immediate emergency care / treatment given to the victim of an accident or sudden illness, till medical aid is available.

Aims of first aid

- To preserve / save life
- To prevent further injury & worsening of casualty's condition
- To promote recovery <u>်</u>

Ten Commandments for first aiders

- 1. reach the accident spot quickly be calm and speedy
- ensure safety of the place
- look for life threatening conditions first 4.
 - give FA in the order of priority 5.
- reassure the casualty if conscious
 - clear the crowd
- do not leave the casualty alone
 - arrange for safe transport
- do not attempt too much / do no harm

Look for condition of the victim in the following order

- is the victim conscious
- is the victim breathing is there severe bleeding

 - is the victim in shock is the victim in pain 4. 7.

33.1. Control of bleeding

- Apply direct pressure over the wound
- Cover wound with sterile dressing and bandage firmly
- Raise the injured part above level of heart
 - Apply pressure over pressure points

4. 5. 9

- Immobilize the injured part
 - Look for signs of shock
- Send to hospital in lying down position

33.2 Fracture

Suspect fracture when there is tenderness, swelling, deformity, abnormal movements etc.

- Control any bleeding and cover any wounds
- Do not move the casualty unless life is endangered
- Immobilize the injured area as well as the joints above and below using suitable splints
- Call for ambulance to send to hospital 4.

33.3 Burns

- If clothing on fire—stop, drop and roll ⊢i
- Cool the burnt area by holding under cold running water for at least 10 minutes
- Do not apply ointments, oils or any other substance რ
 - Cover the wound with sterile non-sticky dressing 4.
 - Call for ambulance 5.

33.4 Eye injuries

- Removal of foreign body should not be attempted
- Do not apply ointment or oil 2.
- Apply sterile pad and loose bandage
 - Send to hospital

33. 5 Chemical burns of the eye

- Immediate washing of the eye with clean water continuously for at east 20 minutes
- Apply sterile pad and bandage
- Send to hospital 2 . 8

33.6. Suffocation

- Remove the casualty from the site of accident to safe area to get fresh
- Clear the airway
- Restore breathing by artificial respiration æ.
- Send to hospital 4.

33.7 Electric shock

- do not touch the casualty while he is still in contact with live source
 - switch off the power immediately
- do not attempt first aid until the contact has been broken æ.
- check response and breathing
- give cardiopulmonary resuscitation (CPR) if the casualty is unconscious and is not breathing 5.

33.8 Unconsciousness

- Check response
- If no response look for breathing
- Start giving CPR if unresponsive and is not breathing
- If breathing is normal, keep the casualty in recovery position till he gets medical attention

33.9 Chest pain

- If casualty is conscious, keep him in half sitting position and advise to
- Call for ambulance and continue CPR till he gets medical help or show If unconscious, check D.R.A.B.C (Dangerous, Response, Airway, Breathing and Circulation) and start giving CPR if necessary signs of life.

33. 10 Cardiopulmonary Resuscitation (CPR)

CPR is the emergency first aid procedure done when the casualty is unconscious and not breathing.

thereby delay tissue damage, so that more definite treatment will be CPR maintains flow of oxygenated blood to the brain and the heart, effective

If you see a motionless person, follow the steps below

- Assess the area for any safety hazards before proceeding
- Check the response by shaking the shoulders and calling loudly
- Check for breathing by looking rise and fall of chest wall for 5 to 10 If there is no response, open the airway by head tilt and chin lift ж. 4.

If there is no breathing start giving CPR 5. CPR consists of artificial circulation & artificial respiration given at regular sequence. CPR is effect only if performed within 4-5minutes of the stoppage of blood flow. CPR sequence of steps is now

C-A-B

C- Chest compression

 A - Airway

 ${f B}$ - Breathing

Chest compression

- Place the heel of one hand at the centre of lower part of chest and place the other hand on top of the first.
 - Begin chest compression push hard and push fast
- The rate of compression should be at least 100 per minute.
- Depress the chest at least 2 inches (5 cms) and allow full recoil of chest wall before next compression 2 .. 4
- Give 30 compressions at one stretch
- 6.5

Air way opening


- Open airway by head tilt and chin lift
- Check breathing by watching rise and fall of chest wall for 5 to 10 seconds.

Breathing

If the casualty is not breathing, give two rescue breaths in two seconds

Continue CPR by giving 30 chest compressions followed by 2 rescue ۲.

Continue CPR until there are signs of life or until emergency medical personnel take over



SERVICE MANIFOLDS/PIPE LINES & ELECTRICAL DISTRIBUTION **TYPES** WITH CODING 34.COLOUR

CONSEQUENCE MANAGEMENT

The purpose of consequent Management is to provide a fair and consistent approach to dealing with every ones conduct, behavior and/or performance whose conduct, behavior and/or performance falls below acceptable falls below acceptable standards or regulatory requirements. It will apply standards or regulatory requirements will be subject to corrective action. Everyone is expected to conduct themselves in a manner which conforms to HSE standards of workplace behavior and conduct. When a violation of an established standard occurs, cases will be investigated thoroughly and disciplinary action will be administered on the merits of each case.

35. SAFETY REVIEW MEETING

discussed in a constructive manner and necessary measures needed to Safety review meeting conducted every month to address any deficiencies and improvement opportunities in the system are being improve it.



This meeting will be chaired by unit head, execution and QHSE team will be part of the meeting. Secretary of the meeting is a from QHSE

36.STEPS TO REDUCE ENVIRONMENTAL IMPACTS

- Continual Improvisation of the system to reduce the use of natural resource (Eg: Electricity, water, paper) in CSL-MSRU.
- Continual Improvisation of the system to reduce the pollution resource (Eg: air, water and soil) in CSL-MSRU.
 - Promotion of use of environment friendly materials in CSL-MSRU.
- Action to reduce any leakage of water in CSL-MSRU. If water leakage is observed in your area, report immediately.
- Avoid Improvised connections and use of standard leak proof couplings for getting water.
- Electrical equipments to be switched off when it is not
- Promote the use of one side paper in offices.
- Avoid dumping oil or paint sludge directly in sea water.
- Paint drums, oil drums, blasting materials etc. are to the taken away from the dock floor before flooding the dock and area will be cleaned.

कोचीन शिपयार्ड लिमिटेड



COCHIN SHIPYARD LIMITED
(A Government of India Category-1 Ministra Company, Ministry of Shipping)

The 12 Salient Safety Rules are the fundamental safety standards expected from everyone in CSL rolls, Partners,

RULES SAFETY **12 SALIENT**























USE CERTIFIED SCAFFOLDING











OBTAIN DAILY SAFE ENTRY
PERMIT REFORE ENTERING
CONFINED SPACE & COMPLY
GAS MANAGEMENT















OUT WORK ACTIVIT DRIVING OR CARRY

DON'T CARRYOUT HOT WORK AND PAINTING WORK SIMULTANEOUSLY

societies to comply with, at all times

Subcontractors & their workmen and Owners/Classification

Every individual is responsible and obliged to request for

When work does not comply with 12 Salient Safety Rules:-

"सुरक्षा केलिए रुके"

"WHAT TO DO" FLOW CHART

Observation of Non-Compliance [Violation of 12 Salient Safety Rules]

[Intervention to "STOP" the Immediate Danger] Request for "सुरक्षा केलिए रुकें

Do a Safety Conversation [Gentle Re affirmation]

Restart after Corrective actions [Corrective actions to be verified]

Safety & Fire Services Department



"Protect our earth"

"They are waiting you at home"

Paste your family photo here

ENCL.6

Specific Terms & Conditions

Enq no: MP1/ARC/FRESH WATER/CMSRU

- 1. Payment Terms of Payment: 100% payment as per actuals shall be released on monthly basis as per the scope of work/work order and submission of invoice along with work completion / delivery report duly verified by authorized CMSRU staff.
- 2. Vendors are strongly advised to visit work site prior to quoting.
- 3. Cochin Shipyard Limited (CSL) has registered in the TReDS Portal viz., RXIL, M1xchange and Invoice Mart. Those MSME vendors who have registered in the TReDS portal may upload the invoice in the respective portal under an intimation to concerned executing officer for processing the payment through TReDS portal. Suppliers are requested to check with the concerned executing officer regarding the Quality inspection status, where ever applicable, before uploading the invoices in TReDS portal.
- 4. All the necessary passes to be arranged accordingly by the vendor.
- 5. The contractor to provide all arrangements and support for entire completion of scope.
- 6. CMSRU reserves the full right to change the work scope/amend the work scope according to the site condition.
- 7. CMSRU reserve the right to offload the job to more than one subcontractor (parallel contract) to meet the schedule against this tender.
- 8. CMSRU have the full right to modify (Deletion) the work scope in line with the final requirement and time lines.
- 9. CMSRU have the full right to issue the work order based on overall L1 Turnkey basis. Final decision shall be under CMSRU.
- 10. L1 firm has to provide detailed price split up (if required) within 03 days from the date of confirmation from CMSRU.
- 11. Firm to provide necessary valid certificates (wherever required).
- 12. Firms should have related similar experiences as per the work scope mentioned and the supporting documents as a proof to match the work experiences shall be submitted to CMSRU
- 13. CSL/CMSRU has the full right to withdraw the tender in partial or full during the course of this tender without giving any prior notice / clarifications to vendors.
- 14. CSL/CMSRU has the right to accept or reject any or all of the offers.
- 15. Vendors are requested to submit the bid in the attached price bid format **(in Two Bid)** for avoiding discrepancies/confusions during the comparison stage.
- 16. Vendors are requested to submit a signed copy of Encl. 2, 3, 4, 6, 7, 8, 9, 10 & 11 along with unpriced Price bid format clearly indicating quoted/not quoted against each job scope with the Tech. bid for verification.
- 17. All documents submitted against this tender shall be signed and sealed by authorized persons and the compliance matrix shall be submitted in the company letter head of the vendor. Otherwise it may be rejected without prior notice.
- 18. All tools and shackles for successful completion of the job shall be arranged by the contractor.
- 19. Contractor shall abide by the CSL safety rules.
- 20. All consumables for the job shall be in the scope of vendor.

- 21. All Material passes and Man entry Passes to be arranged by contractor. Required authorization letter only will be issued from CMSRU.
- 22. Forward offers and communications from mail IDs starting with words as highlighted in below message, since the message will be blocked and may not necessarily reach the indented ID, as indicated in below.

info
support
admin
sales
customersupport
helpdesk
mail
mailadmin
billing
hello
careers

- 23. Safety Measures that are to be ensured by contractors are:
 - 1. Db IP44 type with ELCB
 - 2. Blower with guard on both side
 - 3. 24 volt lamp with wire and DB
 - 4. Flash back and non return valve for Cylinder (DA and Oxygen is allowed)
 - 5. Welding machine with ELCB of 30 mA to provided
 - 6. Power tools like Grinding Machine should have handle and guard
 - 7. Proper PPEs need to provided by the contractor to workers
 - 8. Induction class need to attend by the new workers

General Manager (CMSRU)

GENERAL TERMS AND CONDITIONS FOR THE TENDER

- 1. Tenderers are to carefully go through the terms and conditions and the technical specification of the items for which offers are called for. Deviations, if any, shall be specifically brought out in the offer. On-board inspection if required may be arranged prior to submitting the quotation.
- 2. Corrections and additions, if any, must be attested. Incomplete/ambiguous offers are likely to be rejected.
- 3. In case of bids sent through email, then the documents should be password protected and the passwords should be passed on to the concerned officer while attending the bid opening or by email / SMS immediately before the tender opening against the request from officer.
- 4. Indigenous tenderers should quote prices for delivery of materials at CSL/CMSU stores and in the case of foreign bidders the same shall be on Ex Works / FOB basis only. C&F prices shall also be indicated in the offer. Insurance in all cases shall be arranged by CSL/CMSRU.
- 5. No enhancement of rate for whatever cause will be allowed once the offer is accepted and an order is placed. Withdrawal of the quotation after it is accepted or failure to make the supply within the stipulated delivery period will entail cancellation of the order and forfeiture of Earnest Money Deposit/Security deposit, if any and/or risk purchase.
- 6. Taxes and duties, if any, payable extra are to be indicated in the price part for single bid and in techno-commercial part for two bid.
- 7. Delivery term and delivery time / work completion time required for completing the job scope should be indicated in the offer.
- 8. The firm/ bidder winning the contract shall sign an agreement with Cochin Shipyard Ltd for "Fall clause". Accordingly, during the contract period, the firm / bidder cannot offer the item/s to anyone

- else at rates lower than the rates quoted, or the same lowest rate shall be applicable to the contract with CSL/CMSRU.
- 9. Manufacturer's name, their trademark and brand, if any, should invariably be mentioned and illustrative leaflets giving technical particulars etc., should be attached to the offer.
- 10. Products supplied shall be nontoxic and harmless to health. In the case of toxic materials, Material Safety Data Sheet may be furnished along with the material.
- 11. Samples are to be supplied free of cost in the event of requirement by CSL/CMSRU. The detailed working drawing, if called for, is also to be furnished for approval before commencement of manufacture.
- 12. The quantities in each item to be purchased may vary according to actual requirement at the time of placing orders.
- 13. Force Majeure condition: Should failure in performance of the contract or part thereof arise from war insurrection, restrain imposed by Government, Act of Legislature or other Statutory Authority or illegal strike, riot, legal lock-out, flood, fire, explosion, act of God or any inevitable or unforeseen event beyond human control which may be construed as reasonable ground for an extension of time, CSL/CMSRU may allow such additional time as is mutually agreed, to be justified by the circumstances of the case. The occurrence/cessation of force majeure situation is to be informed with documentary evidence within 15 days from the date of occurrence/cessation.
- 14. Risk Purchase: If the supplier fails to supply the items ordered within the delivery date or violate any of the terms and conditions of the purchase order, CSL/CMSRU shall have the following rights.
- (i) To terminate the contract with 15 days' notice forfeiting the security deposit.
- (ii) To initiate alternate procurement action at the risk and cost of the supplier.
 - 15. Suppliers are allowed to depute their authorized representative to be present at the time of opening of the price bid.

- 16. Indian Agent: Cochin Shipyard Ltd. is a fully owned Govt. of India Enterprise and prefers to deal directly with the supplier. However, if the supplier appoints an Indian Agent to deal with Cochin Shipyard Ltd., the commission payable by the supplier to such an agency shall be intimated. The Indian agent shall be enlisted with Director General of Supplies and Disposals under the compulsory registration scheme of Ministry of Finance.
- 17. Jurisdiction: All questions, disputes or difference arising under, out of, or in connection with contracts shall be subject to the exclusive jurisdiction of the Courts at Ernakulum, Kerala, India.
- 18. Conditional discounts, if any, will not be reckoned for tender evaluation/ comparison purposes. However the same will be considered while placement of purchase order if the firm turns out to be L1.
- 19. After submission of tender, no unsolicited correspondence will be entertained.
- 20. Cochin Shipyard Limited does not bind itself to accept the lowest or any tender but reserves to itself the right to reject any or all or a part of any tender at its discretion.
- 21. Deviations, if any, in the offer submitted from that of the tender enquiry in any form, should be clearly furnished in a separate document titled as "List of Deviations", failing which it will be presumed that all the terms and conditions are acceptable.
- 22. Reason for non-submission of quotation in case of regret shall be noticed without fail, if failure may not consider for future requirements.
- 23. This tender shall be based on CSL MSME circular No. MAT/MSME/2016 dtd. 27.09.2018. Please refer https://cochinshipyard.com/Msme for the circular.

COMPLIANCE MATRIX

(TO BE SUBMITTED WITH THE "Technical" BID)

SL.NO.	DESCRIPTION	REMARK
1.	ACCEPT THE ENTIRE SCOPE OF WORK AS PER ENQUIRY	YES / NO
2.	IF THE ANSWER TO QUESTION 1 ABOVE IS NO, PLEASE LIST THE SPECIFIC JOBS NOT BEING UNDERTAKEN AS A DEVIATIONS LIST AND ATTACH WITH THIS MATRIX.	
3.	ACCEPT THE GENERAL TERMS AND CONDITIONS AND TENDER TERMS & CONDITIONS INDICATED IN THE ENQUIRY.	YES / NO
4.	IF THE ANSWER TO QUESTION 3 ABOVE IS NO, LIST THE DEVIATIONS AND ATTACH WITH THIS MATRIX.	LIST OF DEVIATIONS FROM GTC.
5.	PAYMENT TERMS AS INDICATED IN ENQUIRY IS ACCEPTABLE.	YES / NO

(Signature of the Contractor)

Seal of the firm.

	UNPRICE BID FORMAT		
MP1/ARC	C/FRESH WATER/CMSRU		Encl.9
	MENTION	N: QUOTED/NO	QUOTED
	ANNUAL RATE CONTRACT FOR SUPPLY OF FRESH AT CMSRU		
SI No.	Description	Unit rate per Ton (Rs.)	GST(%)
1	Supply of Fresh Water as per scope of work, terms & conditions		

Contractor's Seal & Signature

Health, Safety& Environment Contract Guidelines for OEMs /Turnkey jobs/ Sub contract works inside CSL

Encl: 10

Introduction

CSL is the largest public sector shipyard in India in terms of dock capacity, and caters to clients engaged in the defence sector in India and clients engaged in the commercial sector worldwide.

CSL is committed to provide safe and healthy work environment for the prevention of work- related injury and ill health by following the best practices in safety.CSL is certified Occupational Health and Safety management System and Environmental Management system under ISO standards/international standard.

Many of the works of CSL at various sites are executed by the sub-contractors. During these works, sub-contractors personnel are likely to be exposed to different types of hazards. Similarly unsafe acts of contractors personnel may create hazards for CSL staff or workmen of other contractors working at the site. Such unsafe acts may also pose danger to the existing installations and even to members of public.

CSL ensures that the requirements of its HSE Management System are convened by contractors and their workers. This guide is prepared to facilitate safe working during execution of contract works. The General guide lines and HSE requirements are given below for compliance in CSL.

I. General guidelines

- 1. OEMs/Turnkey jobs /Contractors are selected to work inside the CSL based on their track record.
- 2. Along with the contract order/Registration, a copy of the HSE Safety Handbook (CSL/QMS/S&F/SOP 02) of CSL is given to all contractors. The details of all HSE requirements to be followed in CSL for the various types of work are detailed in the hand book. The OEMs/Turnkey jobs /Contractors shall go through all the details and strictly follow the relevant HSE guidelines for their work. In case of any doubt the same shall be clarified from Chief Safety Officer (CSO). Being ignorant of these HSE requirements will not be treated as an excuse for any HSE violations during course of work.
- 3. OEMs/Turnkey jobs /Contractors workmen are given a multilingual HSE induction and Emergency Response training. The individual passes for contractors and their workers are issued only after successful completion of this training. The passes are revalidated every year after successful completion of refresher training. Training requirements of other roles of the subcontractor's staff shall be complied as per the CSL requirements time to time.
- 4. Before start of any work, the CSL officer in charge explains the scope of work and the safety precautions, hazards, PPE usage as per PPE matrix of CSL, Work Instructions, SOPs, Emergency responses to the contractor and his workers. Only trained worker with necessary skills are allowed to work as per the requirement. Necessary PPEs for the work are to be arranged by the contractor.
- 5. Workmen shall have Cotton coverall with identifiable logo on the dress. Supervisors, fire watch man if required, safety staff and other work force shall be deployed as per CSL guide lines.
- 6. The site work supervisor of the OEMs/Turnkey jobs /Contractors shall be ensured that works are being carried out by CSL HSE requirements on daily basis and till the completion of works. The safe start and safe end requirements shall be verified by the site work supervisor on daily basis.
- 7. OEMs/Turnkey jobs /Contractors HSE performance will be evaluated on HSE matters as per the CSL policies time to time.
- 8. During the course of work if any HSE violation is noticed the same is dealt as per the Rewards and Reprimand (R&R) Policy of CSL.

II. HSE requirements

Revision: A00 Sept 2020 Page 1 of 2

- 1. The OEMs/Turnkey jobs /Contractors shall take all safety precautions during the execution of awarded work and shall maintain and leave the site safe at all times. At the end of each working day and at all times when the work is temporarily suspended, he shall ensure that all materials, equipment and facilities will not, cause damage to existing property, personal injury or interfere with the other works of the project or Station.
- The OEMs/Turnkey jobs /Contractors shall provide and maintain all type of lights, guards, fencing, warning signs, caution boards and other safety measures for vigilance as and where necessary or as required by the CSL officer-in-charge or Safety staff. The caution boards shall also have appropriate symbols.
- 3. Where Permit to work (PTW) is required, the work has not started without obtaining the necessary permit and the PTW requirements are followed strictly throughout the work.
- 4. For Project specific or non-routine work on the existing installations, separate Job Safety Assessment (JSA) is to be prepared by the contractor, cleared by the Dept in charge and approval obtained from CSO before start of work.
- 5. A separate HSE plan will be required for the new projects in the yard or any turnkey projects. It shall be in line with CSL HSE requirements and same shall be routed through respective S&F dept and approved by respective HOD.
- 6. OEMs/Turnkey jobs /Contractors shall hold toolbox talks with his workers on daily basis to convey matters regarding the Safety aspects of the work.
- 7. The OEMs/Turnkey jobs /Contractors shall plan his operations so as to avoid interference with other Departmental works and other Sub-Contractors at the site. In case of any interference, requires, coordination shall be sought by the contractor from the Department for safe and smooth execution of work. This shall be done through CSL executing officer.
- 8. The OEMs/Turnkey jobs /Contractors shall at all times keep their work spot, site office and surroundings clean and tidy from rubbish, scrap, surplus materials and unwanted tools and equipment. Welding cables, hoses and electrical cables shall be so routed as to allow safe way to all concerned.
- 9. All waste generated in course of the work shall be segregated as per the yard requirements and shall be disposed at the respective collection pallets / points of the work areas as the case may be. Any kind of pollution made by the subcontractor shall attract the reprimand proceedings.
- 10. All necessary precautions shall be taken to prevent outbreak of fires at the work site. Adequate provisions shall be made to prevent the possibility of fires and ensure the availability of fire extinguishers at site.
- 11. The OEMs/Turnkey jobs /Contractors shall be held responsible for non-compliance of any of the safety measures and delays, implications, injuries, fatalities and compensation arising out of such situations of incidents including statutory obligations.

Revision: A00 Sept 2020 Page 2 of 2

Experience of previously executed orders/works:

SI No	Name & address of the organization	Value of contract		tion of tract
			From	То

Acceptance Criteria for Pre-Qualification: Only firms satisfying the below criteria will be technically qualified and necessary supporting documents to be submitted: -

Minimum qualification criteria for participating in the tender will be as follows:

i) Firms should provide proof for previous experience in executing contract for supply services to vessels / ships inside MbPA - Mumbai Port in the last 3 years

Note: If the experience claimed by the bidder is of no relevance with respect to scope of work, then such experience will not be considered for qualification. Decision taken by CSL in this regard will be final.