TENDER ENQUIRY

Dt. 17.02.2025

Tender Ref No: MP1/ARC/INDUSTRIAL GASES/CMSRU

Dear Sir,

Sealed Tenders in **Two Bid**, super scribing the Enquiry Number & Last date for receipt of Quotations on the envelope, are invited in two separate covers as 'Part I Techno Commercial' & 'Part II Price' for Annual Rate Contract for supply of Industrial Gases at **CSL MSRU (Cochin Shipyard Ltd- Mumbai Ship Repair Unit), Mumbai**.

- 1 The offers as above should reach the undersigned on or before the last date and time shown. Tenders should be addressed to "The Deputy General Manager (CMSRU), Cochin Shipyard Ltd-Mumbai Ship Repair Unit, Mumbai Port Trust, and Mumbai-400001".
- 2. Techno Commercial offers can also be made by e-mail, with price bid duly Locked with password, before 11.00 hrs (IST) on 11 March 2025, if delivery of sealed offers cannot be ensured at CSL on the due date.
- 3. The offer shall indicate payment terms and other terms and conditions.
- 4. Vendors should be able to supply gases at CMSRU, Mumbai within the given duration of time.
- 5. Quotation should be valid for a period of 06 months.
- 7. Quotation can be submitted by email as a password protected document (price part only) to the following email address.

ashutosh.pande@cochinshipyard.in

lijo.jacob@cochinshipyard.in

cmsru.materials@cochinshipyard.in

OR

In a sealed envelope addressed to "The Deputy General Manager (CMSRU), Cochin Shipyard Ltd-Mumbai Ship Repair Unit, Mumbai Port Trust, and Mumbai-400001".

Last Date & Time of Receipt of Tender: 11 March 2025 at 11:00 Hrs IST.

Last Date & Time of Clarification: 07 March 2025 at 17.00 Hrs IST.

Tender Opening date &time: 11 March 2025 at 11:30 Hrs IST.

NOTE: Amendment if any will be notified on CSL/Govt. Website. The bidders are requested to keep themselves informed of the development by visiting CSL website www.cochinshipyard.com and the CPP portal www.eprocure.gov.in regularly. Such amendments shall be binding upon them.

Enclosures: -

- 1. Special Instruction for Two Bid Systems
- 2. Scope of supply
- 3. Price bid
- 4. Unprice bid
- 5. General Terms & conditions
- 6. Specific Terms & conditions
- 7. Compliance matrix
- 8. Prequalification criteria
- 9. HSE Booklet
- 10. H&S Contract Guidelines for Sub_contract work in Side CSL

Signed copy of following documents shall be submitted along with <u>unpriced Price bid format</u> <u>clearly indicating quoted/not quoted</u> against each job scope as per CSL P- bid format (Un priced bid no need to protect with password, if send as soft copy in E mail).

- 1. Scope of supply
- 2. Price bid
- 3. General Terms &conditions
- 4. Specific Terms &conditions
- 5. Compliance matrix
- 6. Prequalification criteria
- 7. HSE Booklet
- 8. H&S Contract Guidelines for Sub_contract work in Side CSL

Price bid duly signed and sealed by the authorized person need to be protected with password and shall be separately attached/enclosed in the mail. Offer submitted in single bid will not be considered.

In case of technical queries, please contact Mr. <u>Phaneendra Varanasi (Manager-CMSRU)</u> (Mob No. 9884945788)

Yours faithfully,

Deputy General Manager (CMSRU)

CSL-MUMBAI SHIP REPAIR UNIT (CMSRU) Mumbai SPECIAL INSTRUCTION FOR TWO BID SYSTEMS

1. MODE OF SUBMISSION OF TENDERS

Tenders should be submitted in two separate sealed covers super scribed in capital letters as **PART-I "TECHNO-COMMERCIAL" & PART-II "PRICE"** indicating the tender number, due date and name & address of the tenderer.

2. TECHNO-COMMERCIAL PART SHOULD CONTAIN FOLLOWING DETAILS:-

- I. Drawings & Technical Literature, if any
- II. Other conditions, if any
- III. Signed and stamped copy of Scope of Work (Encl 2), Rules for engaging contractor's workmen in CSL-MSRU (Encl 4), Specific terms & Conditions (Encl 5), General Terms and Conditions (Encl 6), Compliance Matrix (Encl 7).
- IV. Deviation list, if any
- V. Price bid without price clearly indicating quoted/ not quoted against each line item/DL(Encl:8).

3. PRICE PART SHOULD CONTAIN FOLLOWING DETAILS: -

- a. Price against each work.
- b. Taxes & duties as applicable shall be indicated.
- 4. CSL/CMSRU reserves the right to alter, modify the scope of supply at them discretion and consistent with the Navy Policy as applicable to the contract from time to time.
- 5. The Techno-commercial part alone will be opened initially on the due date and time of tender. The price part will be opened only after evaluation of the Techno commercial Part. Firms will be intimated the date of opening of the price part, whose Techno commercial bid is acceptable, in due course.
- 6. The tenderer shall ensure that their Indian Agent is not representing any other suppliers for the same Tender. In other words, Indian Agents are not permitted to represent more than one firm for a particular Tender.
- 7. Deviations, if any, in the offer submitted from that of the tender enquiry in any form, should be clearly furnished in a separate document titled as "List of Deviations".

- 8. Details of optional items, if any, should be indicated under separate heading in the technical bid and the respective price details should be given in the price bid.
- 9. After submission of quotation / price bid opening, no unsolicited correspondence will be entertained.
- 10. Clarifications, either technical or commercial, should be submitted to points specially asked for only. The opportunity so given should not be used for correcting/changing amending the data/conditions already submitted with the tender.
- 11. Price should be quoted separately for each item. Combining of figures against more than one item and ambiguous clauses will lead to rejection of the bid.
- 12. Offers should be clear and unambiguous. Incomplete/ambiguous offers are likely to be rejected.
- 13. The bidder shall submit a signed & sealed copy of the tender document including Encl 2, 4, 5, 6, 7, 8 & 9 along with their bid as token of acceptance of terms & Conditions.
- 14. An Integrity Pact as per CSL/CMSRU format is to be signed and submitted later (if necessary).
- 15. The quantity projected in the scope of work is estimated. There may be upward/downward variations in actual quantity.

Deputy General Manager (CMSRU)

SCOPE OF SUPLY

MP1/ARC/INDUSTRIAL GASES/CMSRU Encl.1

SL NO.	Type of Industrial Gases	Capacity Of Cylinder	No of Quantity (Cylinder)	UOM
1	Acetylene	6m3	900	Nos
2	Oxygen	7m3	1800	Nos
3	Co2	30 Kg	300	Nos

Note:

i). Vendor need to supply the Gas cylinders based on CMSRU request. One day prior request will be given from CMSRU end ,

ii). Quantity mentiond is approximate and is subjected to variation by +/- 50%.

Seal&Sign of authorised person

TERMS AND CONDITIONS

(To be duly filled and submitted along with offer)

Sr. no.	Description	Compliance by the supplier (Yes/No). In case of 'No', reasons to be provided.
1	The First supply should be as given below: DA – 50 Nos; Oxygen – 100 Nos: Co2 – 10 Nos	YES NO
2	The acceptance of the cylinders will be based on prior checking of weight. If it is found that weight is less than required, the same will be rejected and to be replaced within 24 hours. If it is observed that repeated violation is happening, then the firm will be disqualified and necessary action as deemed necessary by competent authorities will be taken	YES NO
3	Payment will be done as per actuals on monthly basis and certification of the same by CMSRU authorities	YES NO
4	Period of Supply: The period of supply shall be one year from the date of placement of our Letter of Intent / Purchase Order.	YES NO
5	Delivery: Delivery shall be made FOR CMSRU site. The material should be delivered on priority basis either through formal/verbal/telephonically order as the mode may be by CMSRU Stores Department. As timely delivery is the essence of the contract, the supplier has to supply required numbers of cylinders as per the instruction of Stores Department from time to time.	YES NO
	Vendor need to supply the Gas cylinders based on CMSRU request. One day prior request will be given from CMSRU end.	
6	The supplier must be capacity to supply 50 Nos of cylinders at any point of time upon request from engineer in charge of CMSRU / stores department.	YES NO
7	The supplier will be allowed to take back the empty cylinders only after supplying filled cylinders within 24 Hrs. from the intimation. It is not allowed to take the empty cylinders first and return post refilling	YES NO
8	Minimum lot for refilling cylinders should be as mentioned below DA – 10 Nos, Oxygen – 10 Nos, Co2 – on request	YES NO
9	Liquidate Damages: LD at the rate of 0.5 % of the contract value per week or part thereof subject to a maximum ceiling of 10 % of the contract value, will be deducted from the contractor's bill, in the event of failure of the contractor to complete the work	YES NO

	within the stipulated completion period or by the expiry of any extension period granted by CSL.	
10	a) Loading, Unloading & transportation and any other expenses etc. shall be at supplier scope	YES NO
10	b) Standard safety practice needs to follow while loading & unloading the cylinders in a at most care Mann	
11	All Safety rules and regulation of the shipyard to be adhered by contractor	YES NO
12	Man, entry Passes to CMSRU will be provided Free of cost. Dock entry permits for movement of material in dock shall be arranged by contractor. Necessary recommendations for the dock entry permit will be issued by the CMSRU.	YES NO
13	The decision of the CSL officer-in-charge will be final and binding on the contractor as regard the quality and suitability of the material.	YES NO
14	Purity certificate to be supplied along with cylinders	YES NO
15	Taking MbPT Gate entry & exit pass for gas cylinders will be the part of vendor scope.	YES NO
16	Necessary formalities for the custom clearance inside MbPT premises need to be taken care by the Vendor	YES NO
17	All items shall be delivered at CMSRU stores (inside MbPT premises, Hughes Dry Dock , Mumbai) on door delivery basis	YES NO
	The gas cylinder shall conform to Gas	YES NO
18	Cylinder Rules, 2016 and any other Rules as current and to the specification approved by the Petroleum Explosive safety organization (PESO)	ILS NO
	Identification marks i.e. Logo / trade Mark etc. Should be embossed / engraved /punched on the cylinder, in which the Industrial Gases will be supplied	IVEO INO
19	2. Necessary Cap to be provided for all cylinders	YES NO
	3. Supplied Cylinder should have Valid Hydro Tested Date.	
	4. Cylinder should have proper color coding as per Industrial Gas Rule.	
20	Security Deposit: 10% shall be deducted from contractor's each invoice and shall be released within one month after successful completion of the contract period.	YES NO

21	Earnest Money Deposit : The tenderer has to pay Rs.50000/- as EMD for participating in the tender in favour of Cochin shipyard Ltd Mumbai Ship Repair Unit in the form of DD. EMD shall be released to the non L1 vendors after finalization of the contract and to the L1 vendor after completion of the contract period.	YES NO
2	I/we hereby give an undertaking that I/we understood the terms and conditions mentioned in the subject enquiry and I/ we are ready to adhere to the terms and conditions of the subject work.	YES NO

Contractor's Seal & Signature

	PRICE BID MP1/ARC/INDUSTRIAL GASES/CMSRU Encl.2						
SL NO.	Type of Industrial Gases	Capacity Of Cylinder	No of Quantity (Cylinder)	UOM	Unit rate (rate of one cylinder)	Total rate (No. of cylinder*unit rate)	GST%
1	Acetylene	6m3	900	Nos			
2	Oxygen	7m3	1800	Nos			
3	Co2	30 Kg	300	Nos			

0 100:		
Seal&Sign o	t authorised	person

	UNPRICE BID MP1/ARC/INDUSTRIAL GASES/CMSRU Encl.3						
					Mention:Q	uoted/Not quoted	l against Xን
SL NO.	Type of Industrial Gases	Capacity Of Cylinder	No of Quantity (Cylinder)	иом	Unit rate	Total rate	GST%
1	Acetylene	6m3	900	Nos	xx		
2	Oxygen	7m3	1800	Nos	xx		
3	Co2	30 Kg	300	Nos	xx		
TOTAL AMOUNT							
TOTAL AMOUNT INCLUSIVE OF GST							

Seal&Sign of authorised person

General Terms and Conditions

- 1. Tenderers are to carefully go through the terms and conditions and the techno commercial specification of the items for which offers are called for. Deviations, if any, shall be separately listed and specifically brought out in the offer. CSL reserves the right to accept / reject the deviations.
- 2. Corrections and additions, if any, must be attested. Incomplete/ ambiguous offers are likely to be rejected.
- 3. In case of bids sent through email, then the documents should be password protected and the passwords should be passed on to the concerned officer while attending the bid opening or by email / SMS immediately before the tender opening against the request from officer.
- 4. Indigenous tenderers should quote prices for delivery of materials at CSL/CMSRU stores
- 5. Prices should be valid for acceptance for a period of three months (03 months) from the date of opening of tender.
- 6. No enhancement of rate for whatever cause will be allowed once the offer is accepted and an order is placed. Withdrawal of the quotation after it is accepted or failure to make the supply within the stipulated delivery period will entail cancellation of the order and forfeiture of Earnest Money Deposit/Security deposit, if any and/or risk purchase.
- 7. Taxes and duties, if any, payable extra are to be indicated in the price part for single bid and in techno-commercial part for two bid.
- 8. Delivery term and delivery time / work completion time required for completing the job scope should be indicated in the offer.
- 9. CSL/CMSRU terms of payment is 100% payment after delivery of items and in case of service after satisfactory completion of job, within 45 days from the date of submission of Invoice along with all mandatory documents.
- 10. The firm/ bidder winning the contract shall sign an agreement with Cochin Shipyard Ltd for "Fall clause". Accordingly, during the contract period, the firm / bidder cannot offer the item/s to anyone else at rates lower than the rates quoted, or the same lowest rate shall be applicable to the contract with CSL/CMSRU
- 11. Manufacturer's name, their trademark and brand, if any, should invariably be mentioned and illustrative leaflets giving technical particulars etc., should be attached to the offer.
- 12. Materials supplied shall be new and unused and shall confirm to CSL/CMSRU specifications and drawings.
- 13. Products supplied shall be nontoxic and harmless to health. In the case of toxic materials, Material Safety Data Sheet may be furnished along with the material.
- 14. Samples are to be supplied free of cost in the event of requirement by CSL/CMSRU. The detailed working drawing, if called for, is also to be furnished for approval before commencement of manufacture.
- 15. The quantities in each item to be purchased may vary according to actual requirement at the time of placing orders.
- 16. Force Majeure condition: Should failure in performance of the contract or part thereof arise from war insurrection, restrain imposed by Government, Act of Legislature or other Statutory Authority or illegal strike, riot, legal lock-out, flood, fire, explosion, act of God or any inevitable or unforeseen event beyond human control which may be construed as reasonable ground for an extension of time, CSL/CMSRU may allow such additional time as is mutually agreed, to be justified by the circumstances of the case. The occurrence/

- cessation of force majeure situation is to be informed with documentary evidence within 15 days from the date of occurrence/cessation.
- 17. LD Clause: In case of delay in supply of ordered materials / delay in completion of work beyond the stipulated delivery / completion period which is not attributable to CSL, vendor is to pay liquidated damages (and not by way of penalty) a sum equivalent to ½%(half percent) per week or part of the week of the order value (basic price) in the case of machinery/equipment and of the value of materials / services delayed in the case of all other items/services subject to a maximum of 10% of the order value (basic price). For service orders, completion date as confirmed by the executing officer shall be reckoned for LD calculation.
- 18. Risk Purchase: If the supplier fails to supply the items ordered/complete the job scope within the delivery/completions date or violate any of the terms and conditions of the contract, CSL/CMSRU shall have the following rights.
 - (1) To terminate the contract with 15 days' notice forfeiting the security deposit.
 - (2) To initiate alternate procurement action at the risk and cost of the vendor.
- 19. Guarantee: The equipment supplied shall be guaranteed for satisfactory performance for 12 months from the date of commissioning or 18 months from the date of delivery of items whichever is earlier against faulty design, defective materials and bad workmanship. Supplier should supply and install free of cost immediately any part found to be defective for the above reasons within the guarantee period. The Services shall be guaranteed for a minimum period of 06 months from the date of successful commissioning/final acceptance.
- 20. Suppliers are generally allowed to depute their authorized representative to be present at the time of opening of the price bid. However this will be subject to the discretion/SOP of CSL, in view of the restrictions imposed by Govt/local body/CSL due to Covid-19 outbreak. At present, in view of COVID-19 pandemic, Vendors are not allowed inside CSL to attend opening of the price bid.
- 21. Cochin shipyard Ltd prefers to deal directly with the supplier. However, if the supplier appoints an Indian agent to deal with Cochin shipyard ltd., the agency commission payable by the supplier to such an agency shall be intimated. If manufacturers affect the supply through agents only, authorization in writing from manufacturers in favour of the agent for supply to CSL shall be furnished. In case where an agent participates a tender on behalf of a foreign manufacturer Indian agent should submit specific authorization from the authorized person of foreign manufacturer. In a tender, either the Indian agent on behalf of the principal/ OEM or principal/ OEM itself can bid but both cannot bid simultaneously for the same item/ product in the same tender. If an agent submits bid on behalf of principal/ OEM, the same agent shall not submit a bid on behalf of another principal/ OEM in the same tender for the same item/product. Indian agents cannot represent more than one firm or quote on their behalf for any particular tender. Clarifications, either technical or commercial, should be submitted to points specially asked for only. The opportunity so given should not be used for correcting/changing/amending the data/conditions already submitted with the tender.

- 22. Jurisdiction: All questions, disputes or difference arising under, out of, or in connection with contracts shall be subject to the exclusive jurisdiction of the Courts at Ernakulum, Kerala, India.
- 23. In case advance payment is sought, interest at prime lending rates prevailing in India will be charged. In addition, a Bank Guarantee in the CSL format equivalent to advance amount is to be executed to cover the period till the advance payment is adjusted. Normally Advance payments are not encouraged.
- 24. Conditional discounts, if any, will not be reckoned for tender evaluation/ comparison purposes. However the same will be considered while placement of purchase order if the firm turns out to be L1.
- 25. After submission of tender, no unsolicited correspondence will be entertained.
- 26. Cochin Shipyard Limited does not bind itself to accept the lowest or any tender but reserves to itself the right to reject any or all or a part of any tender at its discretion.
- 27. Deviations, if any, in the offer submitted from that of the tender enquiry in any form, should be clearly furnished in a separate document titled as "List of Deviations", failing which it will be presumed that all the terms and conditions are acceptable.
- 28. Public Procurement Policy initiatives of Govt. of India, pertaining to MSME's, startup etc as per CSL website (www.cochinshipyard.in) shall be applicable for this tender.
- 29. Vendor is solely responsible for the safety of its personnel inside CSL. Service provider will be responsible for the safety of personnel engaged and shall adopt all safety measures to comply with safety regulations in force in CSL. Service representative working onboard should maintain proper dress code as per CSL standards. They shall submit electronic challan remittance copy of ESI&EPF details of their employees and employee compensation policy details for employees not falling under ESI limit during the submission of invoice, documents supporting for facilitating gate access. They are bound to follow safety guidelines applicable in CSL like safe usage of tools & tackles, electrical safety guidelines, gas management system etc. Scrap management system & disposal of hazardous chemicals used to dispose by contractor itself on his own responsibility. Work place hygiene to be ensured by contractor itself.
- 30. Asbestos should not be part of any material /packing material supplied to CSL.
- 31. Shall abide by CSL rules for entry and exit of man and materials. Vendor and personnel will comply with: (1) all procedures and policies provided by CSL, including CSL's, environmental, health, safety, and security procedures, and related management systems when performing services at CSL facilities.
- 32. Service provider will have to abide by the various laws & regulations such as Contract Labour Regulation (Abolition) Act, ESI Act 1948, EPF Act 1952 etc as applicable. In case your employees are already covered under EPF/ESI scheme, their respective account numbers are to be furnished along with copy of challans as proof for remittance of ESI & EPF. If any employee is exempted from ESI, valid proof for the same also shall be submitted before commencement of work. Labor deputed for the work shall not have crossed over 60 years. Submission of above documents is statutory for issue of entry passes for working inside CSL. This is also required for releasing the payment since CSL site is permanently covered under above noted regulations. The certificate of compliance from Contractor as per attached format shall also be filled and submitted along with submission of bills for payment. Bills without duly certified "certificate of compliance from Contractor" shall not be passed for payment. (Form for Compliance of Provisions of various labour Enactments attached as Enclosure 4)

- 33. Vendor will package products according to instructions of CSL provided in the purchase order, and if nothing is provided, then according to good commercial practice to ensure safe arrival of the products. Avoid plastic materials for packing to the extent possible. Packing material shall be ecofriendly. Vendor should follow the statutory requirements of the products offered. In case of chemicals and toxic materials being supplied, vendor should furnish material safety data sheet (MSDS) compulsorily along with the material.
- 34. Acknowledge the receipt and acceptance of purchase order/Work order by signing and returning a copy of the same within three days of receipt of the same. If the acknowledgement is not received, it will be presumed as accepted.
- 35. Subcontracting to other vendors shall be only after written intimation and approval of competent CSL authorities. Vendor shall not delegate or subcontract any of its obligations under the agreement without CSL's written consent. Vendor will remain liable for all subcontracted obligations and all acts or omissions of its subcontractors.
- 36. The procedures of work, standard operating procedures of work including documents like welding procedure specifications developed by CSL are intellectual property of CSL. Vendors shall not use or copy the procedure in any format without the written consent of competent authorities of CSL.
- 37. Vendors shall take back rejected products, if any, and immediately supply new product/rectified product at vendor's expense, including all freight costs.
- 38. For product that is discovered defective during the warranty period, vendor will, at vendor's expense replace or repair defective product and re-deliver such repaired or replaced product to CSL within a commercially reasonable timeframe agreed by CSL
- 39. Except as specifically stated in the purchase order, vendor will be responsible for all costs incurred in connection with providing the services, including personnel's expenses.
- 40. CSL is not obligated to pay any invoice submitted 180 days or more after a product is shipped or services are completed.
- 41. Vendor shall return the CSL resources to CSL immediately after provision of all deliverables and services or any termination of the agreement.
- 42. Vendor warrants that the products and services will comply with their specifications and will be of good quality acceptable to CSL/ship and must be fit for any purpose made known to vendor.
- 43. Vendor warrants that the products will be new, unused, and not refurbished at the time of delivery, and will be safe for normal use and free from defects in design, materials, and workmanship during the warranty period.
- 44. Vendor warrants that for software provided by vendor, (1) there is no open source software in the products (or any other items provided by vendor), unless vendor has notified CSL in writing before delivery and CSL has consented in writing to accepting this open source software, and (2) the software will not damage, interfere with, or permit unauthorized access to any other existing products or systems on which it is installed or any information residing on those products or systems.
- 45. Vendor and personnel will (1) keep confidential the terms of the agreement and all non-public and proprietary CSL information, and will only use such information to provide products and services under the agreement, and will not disclose such information except to the extent required by law after giving reasonable notice to CSL, if permitted by law; and (2) not use in providing products or services or disclose to CSL any materials or documents of another party considered confidential or proprietary unless it has obtained written authorization from that party and CSL.

- 46. Vendor will indemnify CSL and its affiliates, directors, officers, and employees against all liabilities, damages, losses, costs, fees (including legal fees), and expenses relating to any allegation or third-party legal proceeding (including action by a government authority) to the extent arising from an allegation that use, possession, or sale of the products or services violates or infringes a third party's rights, including intellectual property rights; or an allegation that any personnel are entitled to employee compensation, benefits, or other rights or transfer law rights, except to the extent caused by CSL's unlawful acts or omissions.
- 47. No enhancement of rate for whatever cause will be allowed once the offer is accepted and an order is placed. Withdrawal of the quotation after it is accepted or failure to make the supply within the stipulated delivery period will entail cancellation of the order and forfeiture of earnest money deposit/security deposit, if any and/or enforcement of risk purchase clause.
- 48. List of deviations from the general terms and conditions shall be submitted and the same shall be mutually acceptable. In the event of no deviation list submitted by the vendor, it is presumed that all conditions are accepted by the vendor.
- 49. All certificates called for in order specification must be sent to CSL at the time of delivery of items all the material supplied must satisfy CSL quality requirements.
- 50. Invoice:
 - (i) All invoices must be sent to CSL on delivery of items /work completion as per the order terms
 - (ii) Purchase order number and date and dispatch particulars should be clearly mentioned in the invoice.
 - (iii) Wherever payments are authorized through bank, copy of the invoice should be forwarded directly to CSL under intimation so as to facilitate release of document in time. All bank charges will be to vendor's account.
 - (iv)When the payment is in installments, separate invoice is required for each payment.
 - (v) 100% payment will be made against your invoice on satisfactory completion of the work.

The documents for releasing payment - original invoice with service report duly signed by vessel owner and CSL officer-in-charge along with documentary proof of expenses after satisfactory completion of work.

51. "In case imported items are part of the items required for the job Customs duty exemption can be availed by CSL if order for these imported items is placed on high sea sales basis by CSL or direct import order on bidder's principals for import items by CSL. In case of import orders/ high sea sales, the offer has to be on CFR basis to the nearest airport/as mentioned in the enquiry.

The customs clearance, DO charges payment and IGST payment against bill of entry shall be done by CSL.

In case of direct import orders by CSL, copy of Airway bill, foreign currency invoice and packing list would be required. In case of High Sea Sale, HSS agreement and INR invoice in addition to copy of Airway bill, foreign currency invoice and packing list shall also be required.

The copy of all documents to be forwarded to CSL by email at least two days prior to arrival of the consignment at Airport for CSL to arrange the Customs exemption documents and file Bill of entry prior/latest on date of arrival of the consignment itself. In case of any delay

in receipt of documents, the bill of entry late filing fine shall be adjusted from the vendors payment."

Tender conditions for Restriction of bidders sharing land border with India is attached below and certificate as required in the below conditions to be submitted along with tender documents.

Tender conditions for Restriction of bidders sharing land border with India vide Office memorandum dt 23.7.2020 Order - Public Procurement no 1 dt 23.7.2020, Order no 2 dt 23.7.2020 and Order no 3 dt 24.7.2020

Α	Requirement of registration
Any bidder from a country which shares a land border with India will be eligible to tender only if the bidder is registered with competent authority as per C below contracts, including turkey contracts, contractors shall not be allowed to sub contra any contractor from a country which shares a land border with India unless such coregistered with Competent authority. Relevant certificate to be submitted by bid country which shares land border with India except for bidders to which Govt of extended lines of Credit or in which Govt of India has development projects, along wire as proof of registration with competent authority, failing which the offer will not be a contributed by the bidder for compliance with the order referred a with tender documents for consideration of offer (Wordings are as per Clause below certificate given by a bidder whose bid is accepted is found to be false, this would be for immediate termination and further legal action in accordance with law.	
2	Wordings of certificate to be submitted along with tender documents
	I have read the clause regarding restrictions on procurement from a bidder of a country which shares a land border with India. I hereby certify that this bidder is not from such a country or, if from such a country, has been registered with the competent authority. I hereby certify that this bidder fulfils all requirements in this regard and is eligible to be considered. (Evidence of valid registration by the competent authority shall be attached wherever applicable).
2	Wordings of certificate to be submitted along with tender documents for Works involving possibility of subcontracting
	I have read the clause regarding restrictions on procurement from a bidder of a country which shares a land border with India and on subcontracting to contractors from such countries. I certify that this bidder is not from such a country or if from such a country has been registered with the competent authority and will not subcontract any work to a contractor from such countries unless such contractor is registered with the competent authority. I hereby certify that this bidder fulfils all requirements in this regard and is eligible to be considered (Evidence of valid registration by the competent authority shall be attached wherever applicable)
В	Validity of registration

1	Registration should be valid at the time of submission of bids and at the time of acceptance of bids. In respect of supply otherwise than by tender, registration should be valid at the time of placement of order. If the bidder is validly registered at the time of acceptance /order placement, registration shall not be a relevant consideration during contract execution.		
С	Competent authority and Procedure for registration		
1	The competent authority for the purpose of registration under the order shall be Registration committee constituted by the Department of Promotion of Industry and Internal Trade (DPIIT) Details of the committee and procedure for registration and restrictions shall be as per Ann of the Order - Public Procurement no 1 dt 23.7.2020 issued by Ministry of Finance, departmen of Expenditure.		
D	Definition of Bidder and Bidder from a country sharing land border with India		
1	Bidder is defined as any person or firm or company including any, member of a consortium or joint venture, every artificial, juridical person not falling in any of the descriptions of bidders stated hereinbefore, including any agency, branch or office controlled by such person, participating in a procurement process.		
2	"Bidder from a country which shares a land border with India" for the purpose of this Order means:- a) An entity incorporated, established or registered in such a country; or b) A subsidiary of an entity incorporated, established or registered in such a country; or c) An entity substantially controlled through entities incorporated, established or registered in such a country; or d) An entity whose beneficial owner is situated in such a country; or e) An Indian (or other) agent of such an entity; or f) A natural person who is a citizen of such a country; or g) A constitution or joint venture where any member of the consortium or joint venture falls under any of the above.		
3	Type of business entity (Private Limited Company/ Public Limited Company/ Sole Proprietorship/ One Person Company/ Partnership/ Limited Liability Partnership/ Joint Venture/ Trust/ NGO) In case of incorporated entity - to attach certificate of incorporation		
	Beneficial Owners - as defined in the Department of Expenditure Order (Public Procurement No.1) issued vide No. F.No.6/18/2019-PPD dated 23 rd July, 2020. Details of all beneficial owners having entitlement of more than 01% of shares or capital or profit to be given, in the format as given in Annexure-I duly certified by practicing Chartered Account in India.		

52. Following are the Tender Conditions Preference to Make in India

А	be applicable as per below		
1	In the procurement of all goods/services/works in respect of which there is sufficient local capacity/local competition, only Class I Local suppliers shall be eligible to bid irrespective of purchase value		
2	In the procurement of all goods/services /works which are not covered as above and with estimated value of purchase less than Rs 200.0 Crores, only Class I local suppliers along with Class II local suppliers shall be eligible to bid.		
	Purchase preferences for Class I local suppliers		
В	In the procurement of goods/works covered under 2 above and which are divisible in nature, Class I local supplier shall be eligible for Purchase preference over Class II/Non local supplier as per following		
1	If L1 bid is not a Class I local supplier, 50% of the order quantity shall be awarded to L1. Thereafter the lowest bidder among Class I local supplier will be invited to match the L1 price for the remaining 50% quantity subject to Class I local supplier quoted price falling within 20% margin. Contract for that quantity shall be awarded to such Class I local supplier subject to matching L1 price. In case such lowest eligible Class I local supplier fails to match L1 price or accept less than offered quantity, next higher Class I local supplier within 20% margin shall be invited to match the L1 price for the remaining qty and so on. If some quantity is left uncovered on Class I local supplier, such balance quantity shall be ordered on L1 bidder.		
2	For procurements that are not divisible in nature and in procurement of services evaluated on price alone, Class I local supplier shall get purchase preference over Class II/Non local supplier as per below		
3	If L1 is not a Class I local supplier, lowest bidder among Class I local supplier will be invited to match L1 price subject to Class I local supplier quoted price falling within 20% of L1 price and contract will be awarded to such Class I local supplier, subject to matching L1 price. In case such lowest eligible Class I local supplier fails to match L1 price, procedure same as para 3 above will be opted. In case none of Class I local suppliers within 20% margin matches L1 price, contract shall be awarded to L1 bidder. The purchase preference as above will be only for Class I local supplier and Class II local supplier will not be eligible for any Purchase preference		

С	Local content requirement to categories a supplier as Class I/Class II /Non local supplier shall be as per below. Definition of local content shall be as per order dt 4.6.2020 ie amount of value added in India which shall be the total value of the item procured (excluding net domestic indirect taxes) minus the value of import content in the item (including all customs duties) as a proportion of total value in percentage.	
1	Class I -Local content equal to or greater than 50%	
2	Class II-Local content greater than 20%, less than 50%	
3	Non local -Local content less than 20%	
D	Declaration of local content	
1	Class I local supplier /Class II local supplier at the time of tender shall indicate % of local content and provide self certification that offered item shall meet the local content requirement for ClassI/Class II as applicable including details of locations at which local value addition is made.	
2	In case of procurement for a value in excess of Rs 10.0 Crores Class I/Class II local supplier is to provide a certificate from statutory auditor/cost auditor(for companies) /practicing cost accountant/Chartered accountant (suppliers other than companies) indicating % of local content	
3	Verification of the Certificates issued by the bidder shall be carried out by CSL on random basis. False declarations will attract actions as stipulated in the order referred, including other actions as permissible by law.	
4	Exemption is applicable from provisions of order for purchases with estimated values less than Rs 5.0 lakhs	
5	Notwithstanding above, exemptions for meeting local content as per relevant Clause of order dt 4.6.2020 and as amended from time to time shall apply.	

53. ARBITRATION:

- 1. Any disputes arising the currency of the contract shall, in the first instance be settled by mutual discussions and negotiations. The results of such resolution of dispute shall be incorporated as an amendment to the contract, failing which the parties can resort to arbitration.
- 2. If any dispute, disagreement or question arising out of or relating to or in consequence of the contract, or to its fulfillment, or the validity of enforcement thereof, cannot be settled mutually or the settlement of which is not herein specifically provided for, then the dispute

shall within thirty days from the date either party informs the other in writing that such disputes, disagreement exists, be referred to arbitration. The arbitrators shall be appointed and the arbitration proceedings shall be conducted in accordance with and subject to the Arbitration and Conciliation Act, 1996 (No. 26 of 1996) as amended form time to time and the decision of the Arbitrators shall be final and binding on the parties hereto. The arbitration will be done by a Board comprising one officer nominated by each party, and a mutually agreed Umpire. Each party shall bear its own cost of preparing and presenting its case. The cost of arbitration shall be shared equally by the parties unless the award provides otherwise. The enforcement of the award shall be governed by the rules and procedures in force in the State in which it is to be executed. Performance under this Contract shall however, continue during arbitration proceedings and no payment due or payable by the parties hereto shall be withheld unless any such payment is or forms a part of the subject matter of arbitration proceedings.

3. In case of disputes, the same will be subjected to the jurisdiction of courts at Ernakulam, Kerala, India only.

Specific Terms & Conditions

Enq Ref No. MP1/ARC/INDUSTRIAL GASES/CMSRU

- Payment –Payment shall be released against invoice certified by store officer/executing officer and other Mandatory documents as per purchase order within 45 days from the date of Submission of invoice. Payment will be done as per actuals.
- 2) CSL/CMSRU has the full right to withdraw the tender in partial or full during the course of this tender without giving any prior notice / clarifications to vendors.
- 3) The period of supply shall be one year from the date of placement of our Letter of Intent / Purchase Order.
- 4) Liquidate Damages: LD at the rate of 0.5 % of the contract value per week or part thereof subject to a maximum ceiling of 10 % of the contract value, will be deducted from the contractor's bill, in the event of failure of the contractor to complete the work within the stipulated completion period or by the expiry of any extension period granted by CSL.
- 5) Quote is required along with SAC/HSN code. CMSRU will issue Purchase order as Per the offer.
- 6) All items shall be delivered at CMSRU stores (MbPA) on door delivery basis to Hughes Dry Dock (Indira Docks), Mumbai Port Trust, Mazagon, Mumbai.
- 7) Loading, unloading, transportation and any other expenses etc. shall be at supplier Scope.
- 8) Qty projected may vary according to site requirement.
- 9) Tender shall be issued on OTE basis and processed based on Overall L1. However, final decision shall be under CMSRU.
- 10) All the items against this enquiry shall be accepted after inspection only. Inspection shall be done at CMSRU site.
- 11) The materials supplied shall be free from surface defects.
- 12) In case of rejection, the rejected item shall be taken back by the supplier from CMSRU site and replace the same with new without any additional cost. The Replacement has to be completed within 24 hours from the date of intimation.
- 13) Final amount shall be calculated on the basis of supplied quantity against certified invoice by CSL executing officer/store officer.
- 14) Vendors are requested to submit the bid in the attached price bid format for avoiding discrepancies/confusions during the comparison stage.
- 15) All documents submitted against this tender shall be signed and sealed by authorized persons. Otherwise it may be rejected without prior notice.
- 16) Vendors are strongly advised to visit work site prior to quoting.
- 17) All the necessary passes to be arranged accordingly by the vendor.
- 18) The contractor to provide all arrangements and support for entire completion of scope.
- 19) CMSRU reserves the full right to change the work scope/amend the work scope according to the site condition.
- 20) CMSRU reserve the right to offload the job to more than one subcontractor (parallel contract) to meet the schedule against this tender.
- 21) CMSRU have the full right to modify (Deletion) the work scope in line with the final requirement and time lines.
- 22) L1 firm has to provide detailed price split up (if required) within 03 days from the date of confirmation from CMSRU.

- 23) Firm to provide necessary valid certificates (wherever required).
- 24) Firms should have related similar experiences as per the work scope mentioned and the supporting documents as a proof to match the work experiences shall be submitted to CMSRU.
- 25) CSL/CMSRU has the full right to withdraw the tender in partial or full during the course of this tender without giving any prior notice / clarifications to vendors.
- 26) CSL/CMSRU has the right to accept or reject any or all of the offers.
- 27) Vendors are requested to submit the bid in the attached price bid format (**in Two Bid**) for avoiding discrepancies/confusions during the comparison stage.
- 28) All documents submitted against this tender shall be signed and sealed by authorized persons and the compliance matrix shall be submitted in the company letter head of the vendor. Otherwise it may be rejected without prior notice.
- 29) Contractor shall abide by the CSL safety rules.

Seal & Sign of Authorized Person

Dy. General Manager (CMSRU)

COMPLIANCE MATRIX

(TO BE SUBMITTED WITH THE "Technical" BID)

SL.NO.	DESCRIPTION	REMARK
1.	ACCEPT THE ENTIRE SCOPE OF WORK AS PER ENQUIRY	YES / NO
2.	IF THE ANSWER TO QUESTION 1 ABOVE IS NO, PLEASE LIST THE SPECIFIC JOBS NOT BEING UNDERTAKEN AS A DEVIATIONS LIST AND ATTACH WITH THIS MATRIX.	LIST OF DEVIATIONS FROM SCOPE OF WORK ATTACHED/ NOT ATTACHED
3.	ACCEPT THE GENERAL TERMS AND CONDITIONS AND TENDER TERMS & CONDITIONS INDICATED IN THE ENQUIRY.	YES / NO
4.	IF THE ANSWER TO QUESTION 3 ABOVE IS NO, LIST THE DEVIATIONS AND ATTACH WITH THIS MATRIX.	LIST OF DEVIATIONS FROM GTC.
5.	PAYMENT TERMS AS INDICATED IN ENQUIRY IS ACCEPTABLE.	YES / NO

(Signature of the Contractor)

Seal of the firm.

TENDER QUALIFICATION CRITERIA

ARC SUPPLY OF INDUSTRIAL GASES FOR CMSRU

TECHNICAL EXPERIENCE CRITERIA: -

- 1. Tenderer should have executed Supply of Industrial Gases including similar kind of work orders in the last seven years preceding 31st march 2024 as per following;
 - a. At least 03 orders greater than 16.8 Lakhs.

(or)

b. At least 02 orders greater than 21 Lakhs.

(or)

c. At least 01 orders greater than 33.6 Lakhs.

FINANCIAL CRITERIA: -

- Average Annual financial turnover during the last 3 years, ending 31st March of the previous financial year should be at least INR 12.6 Lakh.
- 2. CSL/CMSRU reserve the right to reject your bid based on your financial statement / work completion certificate in case of any apprehension on your financial / technical capability to execute the Supply on time.


BASIC SHIP TERMINOLGY

6. Bulbous Bow 1. Funnel

7. Bow 2. Stern

4. Port Side [Right side "Starboard side"] 9. Super Structure 8. Deck 3. Propeller

5. Anchor



Cochin Shipyard Limited Mumbai Ship Repair Unit QHSE Department



HSE Hand book

Rev A00 - Jan-2019

Emergency Felephone Numbers

022-?????

WHILE MAKE AN EMERGENCY CALL!!!

Clearly State;

- What type of emergency (eg. Ambulance, fire/rescue
- Where is the emergency (eg: Repair dock BY 90 tank no. 2(p))
- Guide the emergency crew to the location
- Responsible person or supervisor must be with victim



INDEX

- 1. INTRODUCTION.
- 2. QHSE POLICY
- 3. HSE MANAGEMENT SYSTEM IN CSL-MSRU
- 4. SAFETY INDUCTION
- 5. WORK AREAS IN CSL-MSRU
- 6. RESTRICTED ENTRY AREAS IN CSL-MSRU
- 7. GENERAL SAFETY GUIDELINES
- 8. HSE GUIDELINES
- 9. RESPONSIBILITIES OF CONTRACTOR
- 10. REPORTING OF INCIDENTS
- 11. PERMIT TO WORK SYSTEM
- 12. PERSONAL PROTECTIVE EQUIPMENT
- 13. HOUSE KEEPING
- 14. WELDING & CUTTING
- 15. SURFACE PREPARATION
- 16. PAINTING
- 17. WORKING AT HEIGHTS
- 18. WORKING OVER WATER
- 19. CONFINED SPACE
- 20. HAND TOOLS AND POWER TOOLS
- 21. WORKING ON MEACHINE TOOLS AND MACHINERES

- 22. HANDLING ELECTRICITY
- 23. MANUAL HANDLING
- 24. LIFTING OPERATIONS
- 25. BASIC RIGGING SIGNALS, TACKLES AND

METHODS

- 26. DOCKING & UNDOCKING
- 27. SLIPS, TRIPS AND FALLS
- **28. FIRE**
- 29. GENERAL PERSONAL FACTORS LEAD AN INCIDENT
- 30, OFFICE SAFETY
- 31. WASTE MANAGEMENT
- 32. OCCUPATIONAL HEALTH
- 33. FIRST AID
- 34. COLOUR CODING WITH TYPES OF SERVICE MANIFLODS/PIPE LINES & ELECTRICAL

DISTRIBUTION BOXES


- 35. CONSEQUENCE MANAGEMENT
- 36. SAFETY COMMITTEE
- 37. STEPS TO REDUCE ENVIORNMETAL IMPACTS

its employees on rolls, Partners, subcontractors & their workmen and Owners/ Classification societies and will do (CSL-MSRU) places utmost importance on the safety of INTRODUCTION
 Cochin Shipyard Limited – Mumbai Ship Repair Unit
 ts best to provide and maintain a safe and healthy working environment.

personnel. Every employee in the yard from the Managerial Grade down to the Workman level has a The responsibility for safety does not end with the safety definite role to play their work is safe.

This Safety hand book has been compiled by QHSE Department for the use of all personnel working or visiting inside the yard.

clarification on HSE requirements, QHSE team will guide This book does not replace the detailed requirements, safety rules in vogue practiced by CSL-MSRU, for further you to work safely.



2. QHSE POLICY



We are committed to provide ship building, ship repair services and training of marine engineers to the total satisfaction of customers. We undertake these in healthy & safe working conditions, an eco friendly environment and ensure continual improvement of management systems performance.

We endeavour to achieve the above by:-

Meeting or exceeding customer requirements.

Assuring quality of the products and services.

Developing competent marine engineers.

Preventing occupational ill health and injuries.

Ensuring safe work sites.

Conserving natural resources.

Preventing / Minimising air, water and land pollution.

Handling and disposal of hazardous wastes safely.

Complying with statutory & regulatory and other requirements. Developing skills and motivating employees.



Chairman & Managing Director

3. HSE MANAGEMENT SYSTEM IN CSL-MSRU

3.1 QHSE Statement

The long-term business success of CSL-MSRU depends on our ability to continuously its performance in providing assured quality of the ship repair services. Enhanced the occupational health of the employees, Environment & safety, by following best practices within the organization and sustained environmental protection for the benefit of the society.

3.2 Health & Safety

CSL-MSRU strives to conduct all its activities in such a way as to prevent injuries and ill health to our employees, contractors and visitors. CSL-MSRU record and investigate all the incidents occurring in the work place in order to identify the cause and take necessary measures within the ship yard. CSL-MSRU achieving this by identifying the high risk hazards, eliminating or if not at least reducing the risk involved to acceptable level. CSL-MSRU take necessary measures to educating all people involved in ship repair activities on health and safety practices within the work place and off the job safely.

3.3 Environment

CSL-MSRU commitment to the Mother Nature is demonstrated through the ongoing effort to reduce the adverse impact on the environment and reinforcing the positive contribution. This is achieved by identifying the significant environmental aspects related to its activities and products and developing programs and processes to reduce or control them with an aim of protecting the environment.

SAFETY INDUCTION

All entrants to CSL-MSRU are made aware about basic CSL-MSRU requirements with respect to Health, Safety, Environment & Emergency Response. This training is imparted to all newly inducted CSL-MSRU Employee/ Trainees/ Contractors workmen, who will be engaged in ship repair/ maintenance / construction activities on installations. The individual passes will be issued only

after successful completion the HSE induction training programme.

WORK AREAS IN CSL-MSRU 5

- a. Dry dock 305 X 30 X 15 meters
 - Berth- 5,6,7 & 8 (Indira Dock)
 - Shops ن ف

RESTRICTED ENTRY AREAS IN CSL-MSRU ဖ

Due to potential hazards, entry restricted to authorized persons in the following areas.

- Substations a.
- Flammable gas storage area Ь.
- Barricade the locations with warnings as and when required.

7. GENERAL GUIDELINES

- the guidelines mentioned towards an interdependent Every individual is responsible and obliged to "Suraka Keliye Rukem" for the non compliance of 12 Silent Safety Rules published by CSL and this is to be performed as per safety culture. 1
 - Smoking is strictly prohibited
 - Unauthorized use of cameras and mobile phones in CSL-MSRU is forbidden. 35
- Parking of vehicle is only in approved parking locations. Priority is for Material Movement and private vehicles shall
 - make way for material movement. 40
- The use or possession or influence of non-prescription drugs, alcohol and the abuse of substances is strictly prohibited in CSL-MSRU. 6
- Speed Limit of vehicle in the yard is 20km/Hr
- Fishing is not permitted in yard C 8 6
- Everyone should observe and obey regulatory signs.
- 10)Use of mobile phones is strictly prohibited while at work
- and driving including while cycling. 11) Horse play is not entertained in CSL-MSRU. (Example: Direct compressed air or gas on any person)
 - 12)Hiring or bringing the materials / equipments / machinery in CSL-MSRU premises to be followed as per the guidelines, Refer entry management system for

Hiring or bringing the materials / equipments / machinery (Annexure 4 - Entry Checklist for equipment and toos)

8. HSE GUIDELINES

- 1) Usage of Safety Helmet with chin strap, safety shoe and cotton working dress are compulsory at CSL-MSRU work site, in addition suitable PPEs which are job specific are to be used. (refer CSL- PPE'S Matrix)
- before commencement of work. These measures are to be approved by CSL-MSRU officer In charge and confirm by QHSE Dept. These control measures are to be communicated to the workers involved through tool box Risk assessments of non routine works are to be done before the work is started and control measures identified talks. These works to be performed through Job Safety Analysis (JSA)(Refer Annexure 2) 5
- Workers and supervisors engaged in the works shall be competent. 3
- Supervisor In charge is to Brief the hazards and preventive measure related to the work to be carried out during daily tool box talks. 4
- group only. In case a person has to work alone, the same shall be known to at least two persons who are working People are to be engaged in work activities preferable in 2
- 6) Using Paint tin, CO₂ welding cable bobbin and oil drums as working platform is strictly prohibited.
- Thinner is not to be store in beverage bottles
- Ensure necessary state of mind (eg: lack of proper sleep) by having rest at periodic intervals during extended working hours especially during night time. 8

- Adequate precautions should be taken during welding or gas cutting against hazards such as electric shocks, burns, fumes, explosion and arc eyes.
- 10)Adequate ventilation should be provided while working in confined spaces.
- 13) Check and ensure the adjacent areas compartments are free from flammable hazards and suitable protections are taken before commencing hot work.
- 14) Never start hot work cutting the bottom/side shell of ship from outside to inside.
- 15) During hot work at elevated positions, precautions should be taken to prevent sparks or hot metal slag falling on to the people or material below / nearby and suitable barricade to be done at the ground.
- 16)Industrial Oxygen is not to be used for ventilation purpose.
 - Simultaneous operations of Hot work and painting are not to be carried out in the same area.
- 18) Ensure that no hot work should be carried out in the presence of hydrocarbon fumes.
 - 19)All electrical equipments including AC welding machine should be properly earthed.
 20)Ensure that ELCB/RCCB is fitted on all Welding Machines
- and extension boards.

 21) Ensure cables have sufficient current carrying capacity that
- is used for all electrical equipments/tools.
 - 22)Voltage Reducing Devices (VRD) (Safety relay) must be fitted on AC welding Machines.
 - 23) Never Bypass Safety Relay on AC welding machines
- 24) Electrical extension switch boards are in metallic construction with ELCB/RCCB & and individual MCB. Only industrial type plug and socket to be used.
- 25)Only authorized persons are allowed to operate any machine/equipment / Switch boards. Unauthorized operation strictly prohibited. work on yard switch boards only allowed to CSL-MSRU electrical team.
- 26) Never tamper with machine guards.
- 27) Ensured that all portable equipments, welding transformers/rectifiers must be switched off after use.
- 28)230 V hand lamps are not permitted in the yard. Use 110 V hand lamps in open area and 24 V hand lamps are to be uses in confined spaces.

- 29) 24 V Flame proof lamps shall be used inside tanks where while there was hydrocarbon presence and during painting in confined spaces.
 - 30)Users are to daily inspect welding cables, cutting hoses and hand tools must be used in the yard.
- 31)All the temporary electrical connection including connection of welding sets, distribution box etc shall be made with the approval of yard electrical safety officer
- 32) Excavated materials should be put away from the edge of the excavated trench to avoid slopping of the excavated materials into the trench.
- 33)Never enter into tanks without permit. Refer Confined space entry procedure.
- 34)People working in tanks or pits must acquaint with the hazard present there and supervisor should advise his employees of the hazards present and precautions that are to be taken.
 - 35)Open manholes and places people are liable to fall, those areas must be protected by strong barricade with intermediate railings. Man hole covers should be replaced promptly when work is suspended.
- 36) Jumping from moving vehicle is prohibited. They should wait until the vehicle stop before attempting to enter or leave.
- 37)Any dangerous situation affects the safety of an employee or his fellow employees shall be immediately brought to the notice of site supervisor or reported to CSL-MSRU OHSE team.
- 38)Standing under suspended loads is dangerous and is avoided.
- 39) Compressed air should not be used to clean dust in the clothing.
- 40)Any kind of Gas cylinders (empty/full) should be secured in upright position and away from direct sunlight.
 - 41)Air hoses, welding cables, fuel hoses and electric cables should not be allowed to lie across walkways and area they should be suspended from overhead hooks.
- 42)Inflammable liquids must be handled in cans or containers meant for storing it and are to be stored in space having good ventilation. All such containers must be clearly labeled and warnings exhibited visibly.

- 43) Material Handling Equipments to crane tracks through the authorized route only.
 - 44)If a threat to any person's life is observed, anybody can clear the threat and wait for authorized rescue persons for further actions. Rescue operations should be done by authorized persons only.
- 45) Everybody should be responsible for housekeeping at their work site.
- 46) Avoid activity/action that leads to air/water/soil pollution.
- 47)All the pressure line joints must be connected with whiplash/whip sock arrestor.
- 48) Gas management for cutting operations to be complied as the procedure(Annexure 3- Gas management Procedure)

RESPONSIBILITIES OF CONTRACTORS 6

- be issued with these CSL-MSRU HSE quidelines and firm is expected to give a declaration that he receives one copy of the CSL-MSRU HSE guidelines and The Contractor before starting any work in the CSL-MSRU will comply with laid therein. premises will 7
- The contractor should convey the HSE guidelines to his workers and make them aware through tool box talks. 5
- A responsible safety Incharge is to be designated by the firm for the activities. The details of the safety Incharge shall be communicated to QHSE team. He shall take a lead to ensure safe work environment for their work sites. 3
- CSL-MSRU reserves its right it suspend work in the event of the contractor not complying with the HSE guide lines with regarding to HSE practices for which no claim of any kind will be entertained. 4
- To ensure the safe conduct of safety operation a representative of the contractor should maintain appropriate contract with the CSL-MSRU officer-in-charge of the work as may be necessary to acquaint himself with any changed conditions of other matters relating to the HSE performance. 2
- The contractor shall ensure that all his employees understand their obligations and they follow all CSL-MSRU HSE rules. 6
- It is the responsibility of the sub-contractor firm to provide their employees with all the necessary PPE'S. \sim

- The contractor is also responsible for controlling the control their must movement to and from the work site. behavior of his personnel and 8
 - The HSE plan of Contractor is detailed in the procedure. (Annexure -5 - Refer HSE Plan of Contractor) 6
- 10) For further clarifications on HSE matters, Contact CSL-HSE Officer.

10.REPORTING OF INCIDENTS

MSRU premises during the duty/after duty hours should be All injury incidents to employees/ trainees/sub-contractors & their workmen/visitors/Ship staff occurring inside CSL reported by supervisor to project manager.

Form 02) to be initiated by the officer in charge of the area CSL-MSRU personal injury reporting form (CSL / SMS / S&F/ and reach to QHSE dept within 24 hrs.

suggestions, violation etc) other than personnel injury Format of HSE Observations (near miss, property damage, incidents shall be available at HSE site cabins/offices.

11.PERMIT TO WORK SYSTEMS

The following activities must not commence unless obtaining issued work permits. (Refer PTW procedure annexure) The type of work permits are:

1) ON BOARD SHIP

- a) Hot work (Oxy Acetylene cutting/Welding On Board Ships)
- Tanks/Confined Confined .⊑ Spaces/other compartments) paintings Buffing (Brush/Spray Painting Q
 - Electrical on (Works Shut down installation/Equipments) Electrical \circ

2) INSTALLATIONS

- Excavation/Trenches Opening (any) a) Work at Height/fragile roofb) Excavation/Trenches Openicc) Excavation/Fuel or electrica
- Excavation/Fuel or electrical trench opening)

TYPES OF WORK THAT REQUIRE A PTW (STATUTORY)

- Radioactive materials, Any Expose of radio Active materials) Radiography (NDT tests using
- Electrical Shut Down (Works on Electrical distribution of nstallations/closed proximity system) a

4) JSA FOR NON ROUTING WORKS

- Chemical cleaning pipe line, tanks, equipment's and spaces etc.
 - STP cleaning a
- Tank testing by filling air(APT) ⊕ `

 \circ

- Pressure testing of AC lines and plants
 - Charging of Refrigerents
 - Puff filling
- Use of liquid nitrogen
- Simultaneous Operations (SIMOPS)
 - Fumigation (£) (£) (£) (£)
- Any Other works directed by the yard QHSE team

(Refer Annexure 2 -JSA)

12. PERSONAL PROTECTIVE EQUIPMENTS

associated with hazards they are exposed to. All PPE'S must Employees are responsible to wear appropriate PPE'S comply with approved Indian or international standards e.g: ISI, BŚ, DIN, ANSI or CE

Basic PPE'S requirement at CSL-MSRU Site. 1) Safety Helmet

- Safety Shoes
- Cotton Working dress
- Safety Glasses or face shield or goggles (appropriate to work) 266
- Hand gloves appropriate to work should be worn
- While welding PPE's like apron, gauntlet, leg guard, face shield should be worn 6 9
 - While grinding helmet with face shield should be worn 83
 - For further information refer PPE'S Matrix

13.HOUSE KEEPING

personnel to maintain the highest possible standard of important part of HSE the responsibility of all housekeeping in their work area. an it is <u>.s</u> management system; Good housekeeping

This can be maintained by:

- commencing the task and at the end of a work shift <u>.s</u> place that the work or completion of the task. a. Ensuring
 - Ensure obstruction free access to all work places.
- All the waste generated during project taken back out from CSL-MSRU premises. . ن ف

Items shall be stored in such a way that it is easily identifiable and traceable.

- Suitable control measures shall be ensured while storing of flammable materials and chemicals. θ.
- measure are to be kept stand by in case of spillage working there. Appropriate first aid and fire fighting The MSDS (Material Safety Data Sheet) of each chemical are to be displayed and known to all on people handling it or during any fire. ė.



14.WELDING & CUTTING

All welding and cutting operations must be carried out by qualified personnel while working inside the yard. While working onboard the vessel the work should be in The principal hazards associated with welding and cutting accordance with the conditions specified in the work permit. operations are

- Fire
- Explosions
- Burns
- Respiratory disease. Eye injury

Additional hazards which may result from arc welding are electric shock, ultra violet radiation.

retardant cloth should be placed in case the flammable Whenever, welding or cutting operations are being carried out, flammable materials should be removed from the area, where ever possible, and covered with a wetted fire materials cannot be removed.

14.1 Electric Arc welding

Check equipment thoroughly, all welding cables shall be fully insulated and periodically check for cuts that could accidently "short" when in contact with an earthed section of any structure. Do not lay cables in water.

insulated connecters shall be used. All cables and connectors must be of adequate current carrying capacity to perform When connecting cable lengths together, only approved and

designated and fully insulated, and rated to handle the Avoid lengthy cables if possible and lay between wooden blocks, or cover or hang the cables on hooks or stands to prevent tripping hazard. Only electrode holders specifically maximum current required by the task, should be used.

radiation leads to reddening of the skin and irritation. The The arc produces Ultra-violet (UV) radiation. Exposure of UV eyes are very sensitive to UV radiation, the effect varying from temporary to permanent damage of the retina.

Ensure VRDs (Safety Relay) & ELCB/RCCB are fitted on the AC welding transformers

correct shaded filter glass to suit the type of work and also Gauntlet type welding gloves, leather aprons, leggings and All welders must wear the appropriate protective clothing, all welding cable must be tested every 6 months.

14.2 Cutting Operations

fasting by double ear end clip or crimping and **not jubilee clips** which is prohibited by CSL-MSRU. The color code for Hoses must be fitted to the equipment using crimped Oxygen and acetylene hoses are black and red color Respectively. While checking for leaks, only "Soapy water" to be used. Only Acetylene and Oxygen gases are used for Only proprietary fittings should be used on flexible gas line. cutting operations.

equipment while working with the gas cylinders. Suitable gas regulator area to check the cylinder and hose side While working with the gas cylinders flash back arrestors must be fitted at regulator and torch end, and non-return valve must be fitted between the hose and cutting ranged and Calibrated pressure gauges shall be fitted on at pressure.



All cutting equipment must be removed from the vessels or enclosed spaces to open spaces/weather deck when not in use for a prolonged period of time ie, during breaks or end

of the shift. This will prevent the build-up of gas, if there are any minute leaks.

If the atmosphere becomes oxygen enriched due to leakage, the work area must be purged with fresh air and all clothing/flammable materials must be well ventilated to prevent the risk of spontaneous combustion. Gas hoses shall be disconnected from the manifold/cylinder for the stoppage of work on the day and to be locked at manifold or cylinder side.

All the gas hose must be tested every 6 months. Only oxygen and acetylene gas's are allowed inside the CSL-MSRU premises.

14.3 Gas Cylinders

Before use, all gas cylinders must be fixed and secured in an upright position, and placed at a safe distance from any heat

When the cylinders are not in use, the valves must be closed. Prior to fitting the regulator, the valve should be opened slightly to blow away any dust or grit from the

Oxygen regulator valves or fittings should be free of Oil and grease to prevent spontaneous combustion in the case of any oxygen leakage.

Cylinders should be kept and moved in purpose built trolleys, when attempting to move cylinders not mounted on trolleys, the regulators and hose must be detached.

If cylinders are to be lifted by crane, they should be secured in a special carrier. On no account they should be lifted by holding the valve as they are not designed to take the stress and no attempt must be made to lift them with chains, ropes or slings as there are chances for it to slip.

Oxygen cylinders and fuel gas cylinders must be stored well apart, at least 6 meters in open space, to prevent an explosive mixture forming from any leakage.

All fuel gases (Acetylene) whether full or empty, must be stored upright and not in a lying position they should be stored separately.

The cylinders should be shielded from direct sun light, or other heat source, to avoid the buildup of excess internal pressure. Valid certificates of cylinders shall be produced while bringing the cylinders to be yard.

15 SURFACE PREPARATION

Surface preparation includes activities such as buffing, grinding etc. The control measures for these activities are discussed in the power tools section in this book.

Surface preparation is also done by blasting using iron shots, copper slag or high pressured water (hydro blasting). Suitable blasting suites, hoods with coolant tubes shall be used while doing such operation. Barricade with warnings to be erected while blasting operations are being carried out.

16 PAINTING

Smoking or any hot working (welding/gas cutting etc) in the vicinity of painting activity is prohibited. Electrical equipments and fittings in the vicinity should be flame proof. For maintaining the air current, blowers should be used at one end and exhaust blowers at the other end.

While painting inside confined spaces, workers should wear air lines respirators with close fitting rubber masks and the equipments should be of the type that the user himself is able to regulate the air pressure.

A worker inside the confined space should be aided by one helper who could be contacted in case of an emergency through a suitable arrangement.

17 WORKING AT HEIGHTS

A suitable means of access and egress must be provided for all working places which cannot be reached from ground level. All work places that are 2 meters or above and does not have a proper working platform, scaffolding are to be made available. All platform structures / scaffolding shall be only erected, altered or dismantled by the authorized scaffolder. The certified scaffolding will have a green tag near the access and if it is not certified, red tag is placed

near the access. Certification of scaffolding done by QHSE Team. Scaffolding requirements are





Red Tag

Green tag

The key points to be observed when erecting scaffolding are.

- The ground must be firm enough to carry the weight of the scaffold, and the load the scaffolding will be carrying.
- There should not be any gaps in the working platform
- Hand rails with mid rails at 1 meter and half meter height should be ensured for the working platform
- Access ladders shall be provided to reach the working platform. Access ladders are to be provided zig zag manner if the height is more than 2 meter.
- Toe boards must be provided on the working platform.
 - Scaffolding materials must be inspected by CSL-MSRU QHSE team and it shall be made of MS.
- Secondary Platform must be place if the scaffolding height more than 6 meters.
- Scaffolding validity is 15 days from the issue date after 15 days re inspection must be requires.

17.1 Full body Harness

When it is necessary to work in temporary work platform areas where it is liable to fall a full body harness shall be worn. The full body harness should be anchored on a rigid structure, and length of the lanyard should be minimized in such a way that the fall height will be minimal. Anchoring hook shall be of scaffold hook.



18 WORKING OVER WATER

Where work takes place over or near water, the following precautions shall be ensured.

- Suitable hand rails shall be ensured to prevent fall of persons into water also full body harness must be worn
 - Safety net shall be used wherever practicable.
- Buoyancy aids shall be made available near the work area.

19 CONFINED SPACE

The term "Confined spaces" covers a great variety of workplaces which have limited access and inadequate ventilation. Confined spaces are therefore potentially dangerous places to work because workers may get trapped in hazardous concentration of toxic or flammable gases or vapors. Daily inspection of confined spaces to be done before commencing the operation on the day or shift and details are available at access of the space. Continuous monitoring of the space is required if situation warrants. (Refer CSL Confined space entry procedure for details)

Confined space is also liable to become deficient in oxygen. Very often the dangerous atmosphere can occur in confined space as a result of the work being done, for instance, welding, painting, and flame-cutting or the use of adhesives and solvents.

The following guidelines to follow while entering into confined spaces.

- Ensure adequate ventilation prior to entry and constant circulation while personnel are inside. Flameproof blowers shall be used where containing hydrocarbons in the spaces.
 - Use only 24V hand lamps while working in confined spaces.
- Petroleum and Safety Organization (PESO) while entry or do hot work in fuel tanks. (Refer CSL Confined space entry procdure)



20 HAND TOOLS AND POWER TOOLS

All personnel using hand or power tools shall be made aware of any dangers which may arise during their use. Adequate supervision must be provided to ensure that the use of such tools is correct and safely performed.



20.1 Hand tools

Hand tools are among the simplest of our work aids and the hazards associated with them are simple and well understood. Because of this simplicity, the safety precautions associated with them are often ignored or forgotten, to the users subsequent regret.

The main cause of injury is the general misuse of tools, the use of unsuitable or poorly maintained tool and improper storage. Injuries can of course be caused by breakage, it is therefore essential that only tools manufactured from the best materials by reputable tool companies are used.

Misuse of tools causes many problems, the use of screwdrivers as chisels, spanners to hammer nails, and pliers to screw up or unscrew nuts are prime examples of this common misuse.



When working at elevated location, all tools should be placed in a tool box to prevent loose tools being dropped from the heights. Where there is a risk of injury from flying objects such as striking two hard surfaces together, e.g. hammer, chisel, punch or similar articles, better to wear an eye protection.

20.1.1Hammer

The faces of hammers should be kept clean and free from grease, and be of sound condition (not pitter or broken edged) and in good shape (Not mushroomed)

Wooden shafts must be of the correct size and securely fixed to the hammer head with fitting wedges – They must be kept from oil and grease and undamaged. Crack or split shafts must not be used.

20.1.2Chisels and punches

There are several types of cold chisels and punches. These must be of good quality materials, properly maintained and inspected, especially for mushrooming of head. All chisels and punches should be dressed frequently to maintain a safe profile.

Cutting edges should be kept sharp to permit accurate working and to avoid the hazards arising from unnecessary hammer striking.

20.1.3Files

A file must never be used without a correct fitting handle; this is to prevent the tang from causing injury to the hand.
Oil must never be applied to files; they must never be struck by other tools as they are brittle and will shatter. To maintain files when clogged with filings clean out the teeth with a file card or fine wire brush.

20.1.4Screw Drivers

Screwdrivers are probably the most common and abused of all the hand tools. When using a screwdriver, make sure that the blade fits the slot in the screw properly. Too large or too small a blade will damage the screw, and not work efficiently. Screw driver blades must be kept square and have a patter to the

The shanks are not designed to withstand twisting strain from pliers or grips, which are often mistakenly applied to obtain additional leverage on a stubborn screw. Never expose the blade to excessive heat as this alters the temper of the steel making it too soft or too brittle for this job.

Do not use screwdrivers as scrapers, chisels or levers and the handles may split if hammered. Serious puncture wounds can be sustained as the result of carrying screwdrivers in the pocket of clothing or coveralls.

20.1.5Hacksaws

When using hacksaws, select the correct blades for the work to be carried out. Thick materials require coarse blades to allow chippings to escape. Thin hard materials require a fine blade. Always ensure that at least three consecutive teeth are in contact with the work.

The blade should always be correctly tensioned in the frame, taut but not over tensioned. Use a steady, forward cutting

stroke with just sufficient pressure to cut through the material.

After use when the hacksaw is to be stored, the tension on the blade should be released, and re-tensioned before future

20.1.6 Spanners and wrenches

Always select a spanner which exactly fits the nut or bolt head, never use packing pieces to make the spanner fit as they may slip, causing injury, and also damage the hexagonal contour of the nut or bolt head.

Open-ended spanners should not be tilted. Ring spanners are probably the strongest if they can be used in a particular situation, less chance of slipping.

Pieces of pipe or similar device must not be placed over the end of spanners as extensions to increase the torque.

When using adjustable wrenches, fit tightly against the faces of the nut or bolt head and apply the torque in the direction of the fixed jaw to prevent the spanner from opening.

Spanners and wrenches should not be exposed to excessive heat, or be ground in order to alter their shape as this may ruin the temper of the working parts.

Periodically inspect all spanners and wrenches for any signs of damage or wear. All worn or damaged tools should be discarded or where necessary, moving parts replaced.

20.2 Powered Portable Tools

The efficient and safe use of all powered tools can come only through proper maintenance and from adequate supervision. The power from this type of equipment is usually supplied from Compressed air or electricity.

20.2.1 Pneumatic Tools

All compressed air hose must have standard hose couplings, never use jubilee clips or similar fittings. Tools required clean air and correct lubrication for smooth functioning of the same.

20.2.2 Electrical Tools

body type. Portable electric power tools must not be used if any defect is suspected or any damage apparent. Repair and routine maintenance shall be carried out by trained and All electrical hand tools shall be of double insulated and fiber qualified electricians.

Only chuck keys of the correct type shall be used to operate chucks. Operators shall ensure that the key is removed from the chuck before operating the equipment and ideally, clipped to the cable to avoid improvisation.

20.2.3 Powdered Disc Grinders

to use. Care must be taken to avoid knocking or sudden impact of the disc to prevent damage and possible disintegration of the disc. The RPM of the grinding machine of the disc and condition must be checked before attempting Powered disc grinders can be air or electrically driven. General operation applies equally to both types. The security should be lower than the RPM of the grinding disk

use excessive pressure. Allow the disc to come a stop before Disc that are chipped, out of true or out of adjustment must never be used. Apply the disc to the work piece and do not laying the grinder down. Impact protection must be worn.

Sparks from the disc may ignite flammable materials, or cause injury to personnel in the area.

20.2.4Compressed Air

may be present in compressed air. If it enters the body, it Extreme caution must be used when using compressed air, as it is delivered at high pressure. Iron dust and rust particles can rupture internal organs and cause serious injury and even death. Do not attempt to clean off coveralls or clothing as it can force harmful particles through the skin.

21 WORKING ON MACHINE TOOLS AND MACHINERIES

While working with Machine tools and machineries the following precautions should be taken.

- Authorized persons should be allowed to use a machine tools and machineries
 - Suitable eye & hand protections shall be worn
- Ensure sufficient illumination at the point of operation
- In wood planing machines, Push sticks and push blocks should be used for guiding the wood to the planing machines 2 κ. 4.
- Stand at a safe distance from the machineries to protect the operator from kick backs, flying materials, moving machinery parts etc. 5.
 - Switch off the machine after use
 - Ensure machinery guards in place 9.7.8
- Ensure lubrication oil or coolants are not spillover near and on the machines.

22 HANDLING ELECTRICITY

The main hazards in electrical works are electrocution, burns, fire and explosion.

- All wires must be treated as live wires until it is positively known that they are dead ÷.
 - No repairs are to be made to electrical equipments by anyone except qualified authorized electricians ζ.
- Never use an electric light extension cord unless it has an approved insulated handle and standard lamp guard. З.
 - All portable equipments must be grounded
- Always wear rubber gloves when working around circuits of 110 volts or above 4. 7.
- Do not overload or overuse circuits
- after the repair on electrical installations, Clearance from Before starting any repair works or resuming the supply proper authority should be taken. 6.

- 8. Before resuming the power supply it should be ensured that the grounding of the line or equipment at the work spot has been removed and all men are off the line or equipment
- 9. If any one comes in contact with live wires or cable and becomes unable to release his grip on the wires, do not attempt to pull him off with bare hands. Shut off the current and protect the hands with rubber gloves or if they are not available, use thick fold of dry clothes to cover hands before attempting to release the victim. If wires are directly on top of the victim use a dry stalk to remove them

23 MANUAL HANDLING

Manual handling is a process where the person is prime source of power in moving material and equipment. It includes lifting, pilling, pushing, carrying or moving.

Correct manual lifting and handling can help prevent strains and backaches. Once your back has been injured, that weakness can remain with you for the rest of your life.

To avoid injury, follow these guidelines:

Asses the weight of the load, get help if it is beyond your capacity use mechanical or hydraulic equipment.

Size up the job make sure you have a clear path way to where the load is going. Look for nails or splitters and wear gloves where appropriate.

Adopt the correct stance stand close to the object with your feet apart, giving a balanced position. One foot advance of the other, pointing in the direction you intend to move.

Bend your knees to a crouch position, keeping your chin tucked in and your back straight (not necessarily vertical)


Take a firm grip with the palm and roots of the fingers and thumb, keeping your arms as close to the body as

possible. Keep your shoulders level and face the direction of travel.

Lift with your leg muscles, not back muscles. Carry out the lifting movements smoothly, do not jerk or twits.

Utilize body weight to create momentum and forward with the load.

Use the reverse procedure when setting down the load.



24 LIFTING OPERATIONS

Lifting machineries such as cranes, winches hoists and other lifting tools and tackles include (wire rope sling, web sling, D Shackles, eye bolts chain block etc.) are widely being used in CSL-MSRU.

Lifting must, by its very nature, be regarded as a hazardous operation. The improper usage and inadequate maintenance of lifting tools and machineries may lead to serious consequence to life and property.

Operational Guide lines are:

 Only authorized, competent persons are allowed to operate cranes.

- Crane operators must only take instruction from designated rigger 5
- short periods, unless all loads have been removed, the At no time should the crane be left unattended, even for power off and brakes are to be applied. 3
- Crane and Transporter (Commeto) within CSL-MSRU area must be accompanied by a rigger or banks men, they will guide the movements safely. 4. 5.
 - Do not use rigging and slinging unless you have been trained and instructed to do so.
- Use correct lifting hooks fitted with safety latches or shaped to prevent accidental displacement of slings. 6.
- Position the lifting hook over the load as to prevent the
 - load swinging when it is raised. Do not tie a knot in a chain to make it shorter, or attempt to drag if from under a load. ω.
- Check wire ropes for kinks, signs of wear and broken 6
- 10.All lifting equipment must have valid test certificates issued by competent person.
 - 11. All lifting equipment must be test once in a year.



Wire rope - Lifting chart

New	Wire	Wire Rope Dlameter 	Sling	Two legged	Eged Sling	g with different Angles		included —
NGC NGC 1000 1340 1700 1700 1700 1700 1700 1800 17	Inch	m.m	10.70	0.0	30°	40°	°06	120°
8 7.00 10.0			Ke.	Ke.	KE.	KR	Ke	X
9 7700 15AD 14AD 15AD 15	5/16	œ i	000	1000	1040	930	700	000
11 1030 2060 2010 1800 1470 1750 1760 17	c c	7 5	000	04x	277	2,40	0707	000
12 1180 2560 2700 2700 2700 1680 1	//16	11	1030	2060	2010	1800	11/0	OROL
15 1750 2750 2750 2750 1760 14 1720 2840 2720 2710 2720 2720 2720 15 1920 2840 3720 2720		1.0	1180	2360	0000	2000	1680	1180
14 11/20 3840 3850 21/20 2420 15 1920 3840 4720 3840 2720 2720 16 2170 4240 4470 4470 460 4470 3650 17 2570 5140 4470 4470 4600 4000 4000 4000 21 3650 5140 5240 5420 4470 4600 4000 22 4400 8200 7950 7140 5820 6720 5240 23 4400 8200 7950 7140 5620 5220 24 4400 8200 7950 7140 5220 5220 25 4400 8200 7950 7140 5240 5240 27 4700 11800 11800 11900 11900 5200 28 5850 16760 12400 12500 12500 12500 27 1780 17	1/1	r;	OCC F	2700	2590	2320	1900	1350
15	9/16	14	1720	3440	0999	2990	2470	1720
16 2120 4240 4470 3650 17 2820 5840 4980 4000 4000 18 2820 5840 5820 4200 4000 21 3870 5100 5220 5820 7140 4000 22 4400 8200 7550 7140 5820 7240 4000 23 4400 8200 7550 7240 5240 5240 24 4400 8200 7550 740 5240 5240 25 5850 11700 11340 10180 8310 26 5850 11700 11340 11040 8310 27 6770 12540 1770 11040 8310 27 1070 11340 11040 8310 28 1220 11340 11420 11420 29 1220 11400 11420 11420 21 10250 11520<		15	1920	3840	3720	3370	2720	1920
17 2570 5140 4980 4470 3650 18 2080 6100 5920 6240 4900 4000 4000 27 3570 7140 6720 6710 7570 720 28 4100 8800 7850 7140 6240 6240 27 4400 8800 8540 7240 6240 6240 27 4400 8800 8200 7240 6240 6240 27 4400 8800 8200 740 6240 6240 27 4400 8800 9200 8250 6240 6240 26 4700 11840 1210 11840 8310 27 4700 11840 1210 11840 1210 28 12100 12200 12200 1420 1220 29 1210 12200 12200 12200 12200 20 20 1220	5/8	e F	2120	4240	7110	3690	0000	0410
18 28820 55400 54700 4000 4000 21 3750 7140 6790 7140 7500 7140 7500 7200 7200 7200 7200 7200 7200 6720 7200 6720 7200 6720 7200 6720 7200 672	11/16	77	2570	5140	0 0 0 0 0	4470	3650	2570
1D 3050 5100 5210 5210 7820 21 4700 8200 7950 7710 7070 22 4400 8200 7950 7710 5820 23 4400 8800 8540 7650 6/240 24 4700 1080 9200 8250 6/240 25 5850 11700 11840 10480 8310 27 6/70 12540 12140 11040 9610 27 6/70 12540 12140 11500 9610 29 9280 11700 14400 14400 14400 20 10550 19300 18720 16800 13700 31 10780 18720 14600 14200 32 10780 18720 16800 13700 34 10780 18720 14600 14700 34 10780 18720 14600 17200	*	18	2820	2640	5470	4000	4000	2820
22 4100 8200 7950 7140 5820 23 4400 8200 7950 7140 5820 24 4400 8800 8240 7650 6240 24 4400 8800 8240 7650 6240 25 5470 1070 9400 8210 6240 27 6770 11700 11340 10180 8310 27 6770 11840 11840 110180 8310 29 1220 11700 11340 11010 8310 30 7790 16760 12400 14400 11000 31 10730 1870 14600 11900 1810 32 10730 1870 14600 11900 1810 34 10730 1870 1470 1470 1470 34 10730 1870 1470 1470 1470 35 10730 1870 <td< td=""><td>2/4</td><td>15</td><td>3020</td><td>6100</td><td>25.70</td><td>5810</td><td>7880</td><td>0000</td></td<>	2/4	15	3020	6100	25.70	5810	7880	0000
23 4400 8800 9840 7650 6240 24 4400 9800 9820 7650 6240 26 5850 11700 1180 9810 970 26 5850 11700 1180 9810 9710 27 6270 12540 12170 11800 9810 27 6270 12540 12170 11800 9810 27 6270 12540 12170 11800 9810 28 6270 12540 12170 11800 14400 30 8380 16760 14600 11800 14400 31 10170 10300 18700 15200 15200 32 12100 22280 17200 14400 15200 34 10170 20300 28400 17200 15200 34 10170 27400 15200 15200 35 11480 28400 27400	13/10	5 /	3570	CILL	0000	07.0	2070	3570
2.9 44400 90000 92400 82500 6720 6720 2.6 5.470 10840 10180 8210 6720 2.6 5.470 11840 11840 7700 2.7 6.270 11240 11840 9410 2.7 6.270 11840 11840 9410 2.7 6.270 12840 12170 11800 2.7 6.270 12840 1770 11800 2.7 10170 12840 1770 11800 2.8 10750 12460 12600 1370 2.8 10750 12460 20860 1870 1520 3.6 10750 21460 20860 1870 1520 3.6 10750 21460 20860 1870 1520 3.6 10750 21460 28400 2440 1520 3.6 10750 22840 27400 1870 1870 4.7	2/18	N :	4100	8200	7950	7140	5820	4100
25 57.70 108.0 108.0 94.00 7700 26 5850 11700 118.40 10180 8310 27 6470 12540 118.40 11040 8210 27 6470 12540 12170 10940 9410 29 82 12580 16260 14600 11900 32 8380 16260 14600 11900 34 9650 19300 18720 14600 13700 35 10730 18720 16800 13700 36 10730 18720 14600 13700 37 10740 18720 14600 13700 38 10730 21460 22000 17700 14420 38 11200 22900 22000 17200 17200 40 14420 22840 22000 24800 17200 41 1420 22440 24200 24800 2500	2 4 7 7 4	5 5 5	4400	0000	0400	000/	0779	4400
26 5850 11700 11840 10180 8510 27 6270 12540 12170 10940 8910 27 6270 12540 12170 11800 9510 30 6270 15540 15140 11800 9510 31 9520 16760 16800 13700 34 9620 1970 17700 14420 37 10170 20340 1870 1500 38 12100 2220 1970 14420 38 12100 2720 1970 1420 38 12100 2720 1980 1520 39 12100 2720 1980 1720 30 12100 2720 1980 1720 30 12100 2720 1980 1720 30 1210 2720 1980 1720 31 1778 2720 2700 1720 32 </td <td>10110</td> <td>- 4</td> <td>277</td> <td>0000</td> <td>0000</td> <td>0 0 0 0</td> <td>1000</td> <td>2000</td>	10110	- 4	277	0000	0000	0 0 0 0	1000	2000
27 62.70 12540 12170 10040 8910 29 67.70 13540 13140 11800 9610 29 67.70 13540 11840 1940 32 8380 16760 16260 14600 1370 34 9650 19300 18720 16800 13700 35 10730 21460 20860 18700 18720 38 10730 22260 22200 1920 18720 39 17780 27560 2700 18750 18750 40 13470 27500 18700 18750 41 14220 28440 27000 18750 42 14080 29960 2900 26100 21300 44 14750 37400 37400 37500 44 16520 28400 26100 25000 51 2750 28400 27400 27400 44		. v	0585	11700	11340	10180	07.4%	0886
2D 6 / / 0 13540 13140 11800 9610 30 7790 16740 16740 117400 1400 1400 32 9250 16750 16260 1370 1370 34 9650 19300 18720 1870 1370 35 10730 21460 20860 1870 1520 36 10750 21460 20860 1870 1520 37 11420 22280 1870 1520 1520 38 12100 24200 2840 21000 1520 40 13420 22840 21000 1520 41 14220 28440 2400 18150 44 14520 28440 2400 2500 44 16520 35040 26100 2100 44 16520 35200 28800 25200 51 22870 47400 3800 25200 52 </td <td>1.1/16</td> <td>N</td> <td>6270</td> <td>12540</td> <td>121/0</td> <td>10040</td> <td>2403</td> <td>6270</td>	1.1/16	N	6270	12540	121/0	10040	2403	6270
32 83280 16760 15760 11050 11050 32 83280 16260 14600 11050 11050 32 83280 16260 16260 11050 11050 32 32 32 32 32 32 32 3	1,1/8	25	0//9	13540	OLISI	11800	5610	0//9
32 8380 16760 16260 14600 11900 34 9220 18460 17900 15000 13100 34 9650 18720 16800 13700 13700 35 10770 21460 22200 18700 18700 18700 36 10770 22200 22400 19700 18700 18700 38 12100 27200 2840 2700 17200 17200 40 13470 2640 27400 17200 17200 17200 40 13470 2640 27400 17200 17200 17200 40 13470 27400 27400 17200 17200 17200 41 14720 28440 27600 22800 22000 27400 18100 44 16520 35040 32000 28800 25000 25000 51 17700 47400 27400 27400 27400 </td <td>200 00 000</td> <td>oc.</td> <td>7790</td> <td>15540</td> <td>15100</td> <td>13540</td> <td>11050</td> <td>7790</td>	200 00 000	oc.	7790	15540	15100	13540	11050	7790
32 9250 1834b0 17000 18600 13700 34 10670 19300 18720 16800 13700 35 10730 22260 18700 15250 37 10730 22260 18700 15250 38 12100 27200 1900 15250 40 13470 27200 1700 17200 41 13420 28440 2700 17200 42 13470 26160 23400 17100 43 14720 28940 27400 17200 44 14720 28940 27400 27400 44 16520 35040 27600 2800 44 16520 35040 2800 28500 51 1750 37400 37400 2700 44 16520 35200 28500 28500 52 22870 34200 24200 25000 54 <td< td=""><td>1.1/4</td><td>32</td><td>8380</td><td>16760</td><td>16260</td><td>14600</td><td>11900</td><td>8380</td></td<>	1.1/4	32	8380	16760	16260	14600	11900	8380
3.4 9650 19300 18720 16800 13700 3.5 10710 201460 22200 18700 15450 3.6 10730 21460 22200 19720 15450 3.7 11430 22280 22400 17500 17500 3.8 12400 22400 21000 17500 4.0 13470 26940 26160 23440 19100 4.1 14220 22840 27400 27400 2000 4.1 14520 32440 27400 27400 2000 4.2 14760 31500 25000 25000 25000 4.4 16520 35040 32000 25000 25000 4.4 16520 35040 32000 25000 25000 5.1 7150 45040 47300 7400 7500 5.2 2220 35200 32800 32800 32800 5.2 22270		30 30	9230	18460	17500	16080	13100	9230
3.5 10170 70.400 149720 147700 14420 3.6 10730 21460 20860 18700 15230 3.7 11430 222800 12100 17200 3.8 12100 22400 22400 17200 40 13470 26400 2700 17200 41 14220 28440 27400 24800 20100 43 14750 31500 25000 24800 21000 44 16520 35040 32000 28800 25500 44 16520 35040 32000 28800 25500 53 22420 32000 28800 25000 25000 54 17520 41040 44700 30400 25000 54 17520 41040 44700 30500 25000 54 17520 41040 44700 30500 25000 54 24400 48800 44700		34	9650	19300	18720	16800	13700	0996
3.6 110730 214660 208600 18700 15220 3.8 12100 272800 198700 15230 3.8 12100 272800 21000 17200 4.0 13770 26460 28440 21000 17200 4.1 14220 28940 26480 28900 20000 20000 4.1 14780 28960 29000 24800 20200 20200 4.1 14780 28960 28000 28800 23500 4.1 14650 37400 28000 28500 28500 4.2 14650 37540 37000 25500 25500 4.2 1460 37500 3700 2500 25500 5.1 2750 47400 37400 37500 37500 5.2 22870 48740 47500 47500 47500 5.2 22870 48740 47500 47500 47500 5.2 <td>1.3/8</td> <td>Ę</td> <td>10170</td> <td>20.340</td> <td>19720</td> <td>17700</td> <td>14420</td> <td>10170</td>	1.3/8	Ę	10170	20.340	19720	17700	14420	10170
38 11430 222860 22200 15050 15200 39 12100 24200 24800 12000 15220 40 13470 26940 24800 24800 2000 18100 41 14220 28440 27600 24800 2000 2000 43 15750 35040 25000 25800 25000 25000 44 16520 35040 32000 26800 25000 25000 44 16520 35040 32000 26800 25000 25000 44 16520 35040 35000 26500 25500 25500 51 7650 37500 37500 26500 25500 25500 52 22870 37500 37500 32500 35500 25500 53 22870 44700 37500 26500 35000 26500 54 24400 47500 47500 47500 47500		90	10730	21460	20860	18700	15250	10730
38 12100 25740 21000 17700 49 13470 26940 25140 14700 40 13470 26940 26160 23440 19100 41 14420 228440 27400 20100 43 16520 29960 26160 25400 20100 44 16520 35040 32000 26500 25500 46 14650 35240 32000 26950 25000 51 7150 45040 34200 35800 25800 54 24400 35800 32800 25800 25800 54 24400 35800 32800 32800 25800 54 24400 36800 32800 32800 32800 54 24400 44700 34800 44700 34800 55 2820 44700 34800 44700 34800 64 3770 6640 5800 44800		\ n	11430	22860	22200	19960	16230	11430
49 1.7780 7.8760 7.9700 1.8780 1.8780 1.8780 1.8780 1.8780 1.8780 1.8780 1.8780 1.8780 1.8780 2.8940 2.4840 2.7400 2.8100 2.0200 4.3 1.6780 2.8940 2.4800 2.0200 2.0000	1,1/2	00 (12100	24200	23/10	21000	17200	12100
41 42420 28440 24440 12140 42 44220 28440 27600 24840 21000 43 17750 35040 27600 27400 27400 44 16520 35040 32000 28500 25500 46 17620 35440 32000 28500 25500 51 22870 37400 3000 26500 26500 53 22870 37400 37400 35500 26500 54 24400 44400 38500 32500 35500 57 2770 5740 47500 32500 35500 57 2770 5740 47500 32500 3500 61 38250 65400 52800 42500 3500 63 3250 65400 52800 42500 42500 64 370 67400 67300 42500 42500 67 3740 67400		ው (ሮ. የ	17780	25550	24800	22200	18150	12780
12.20 25960 250000 250000 250000 250000 25000 25000 25000 25000 25000 25000 25000 25000	A 1. 700	2 5	10410	0440	00707	000000	COTAT	77407
43 15750 25700 257	1.5/0	100	14220	20440	00000	24800	21200	144000
44 16520 35040 32000 28800 28500 46 17620 35040 32000 28800 25500 51 21570 43040 30800 30800 25500 53 22870 45740 44400 39800 32500 54 22400 44400 32800 32500 57 27270 57400 47400 37400 57 27270 57400 47400 37400 63 30320 60640 52800 42500 64 30250 60640 52800 42500 65 3250 65040 52800 42500 67 3770 65040 52800 42500 67 3770 65400 65200 42500 67 3770 65400 67700 47800 67 3740 6770 67700 64500 67 3745 7770 64500 5500 </td <td></td> <td>4 5</td> <td>11000</td> <td>24 700</td> <td>00000</td> <td>27700</td> <td>000000</td> <td>700017</td>		4 5	11000	24 700	00000	27700	000000	700017
46 17620 35240 34000 25000 25000 48 18970 37940 36800 30000 26950 53 22870 41700 47700 26950 54 22870 47700 47700 3500 57 27770 47400 35800 34700 61 30320 60540 58800 45200 45700 63 32250 60540 58800 52800 45200 64 30700 67400 67100 47000 47000 67 37700 67400 67100 4700 47000 67 37700 67400 67100 5500 4500 67 3700 67400 67100 68100 5500 67 3700 7200 77100 5500 70 4700 8400 77100 5500 71 4700 8400 7700 8500 72 4	1 3/4	1 4	0650	33040	32000	00886	00522	16520
18970 37940 30800 30000 26950 251 71570 43040 44700 37400 32500 322870 45740 44700 37400 325000 325000 325000 325000 325000 325000		46	17620	35240	34200	30600	25000	1/620
51 21520 41040 41700 37400 30500 53 22420 48870 44400 52800 52500 54 22420 48800 47800 42500 34700 61 30520 48800 47800 47100 38700 62 38780 5780 58800 52800 40700 63 32520 60640 58800 52800 40700 64 36700 67400 57300 45200 67 37700 67400 67300 47800 67 37700 67400 67300 52600 67 37700 67400 67300 52600 67 37700 67400 7700 68200 52600 70 4700 89400 8600 7700 68200 73 44700 89400 8600 7700 68200 74 4700 8700 9700 7700 6700	1.7/8	78	18970	37940	36800	33000	26950	18970
19 22870 45740 44400 58800 52500 52400 47500 47500 34700 34700 47500 47500 34700 34700 47500 34700	r,	5	21520	43040	41700	37400	30500	21520
19	100	53	22870	45740	44400	39800	32500	22870
1	2.1/8	54	24400	48800	47300	42500	34700	24400
59 78780 56560 58800 52800 45200	2.1/11	22	07070	54540	52800	47300	38700	27270
61 80820 60640 528800 45200 45200 63 28800 52800 45200 65 28800 52800 45200 65 28800 65 28800 46 2000 65 28 25 28 25 20 20 20 20 20 20 20 20 20 20 20 20 20	10 Miles	ው ሆ	28280	000000	24800	00004	40200	28280
63 32220 650400 65100 65600 46200 64 33700 67400 67300 67800 47800 65 37080 74160 77800 64500 52600 65 37080 74160 77800 64500 52600 65 37080 74160 77800 64500 55600 70 40800 7400 74500 74000 55000 71 42000 84000 84500 77100 55000 72 44000 84000 84500 77100 55000 73 44400 84400 84500 77100 55000 74 74250 94500 91600 82200 65200 75 48600 97500 94500 84500 70700 77 48600 97500 96000 96000 70700 81 5780 109740 105500 78000 78000	2.3/8	61	30320	60640	58800	52800	43200	30320
65 34700 64400 67300 64500 47800 65 57080 74160 71800 64500 52600 65 57080 74160 71800 64500 52600 65 52600 65 65 65 65 65 65 65		n •	32520	65040	63100	56600	46200	32520
673 324700 424000 42500 4450	111-1	50	24700	00400	00000	00000	40200	20700
69 39450 78900 76500 68700 56000 70 40820 84000 74100 58000 71 42700 84000 71100 53600 73 42700 89400 86600 77100 53600 72 42800 97200 97200 97200 97200 72 42800 72500 97200 97200 70700 72 72800 72800 72800 72800 72800 72800 72800 72800 72800 72800 72800 72800 7280000 728000 728000 7280000 728000 728000 728000 7280	8/50	27.9	37080	74160	71800	64500	52600	2007
70 40820 81640 79200 71000 58000 71000 58000 73100 59600 73100 884000 88500 77100 59600 731300 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 7313000 73130000 73130000 73130000 73130000 73130000 731300000 73130000000000		69	39450	00087	76500	00/89	26000	39450
71 42000 84000 81500 73100 59600 73 74200 82400 82600 77700 82200 62200 76 7600 77500 97500 97500 97500 97500 97500 77 49800 99600 96600 97500 70700 79 57800 109740 102500 91500 78000 78000 78000 78000 7800000 7800000 780000 780000 780000 780000 780000 780000 780000 780000 780000 780000 780000 780000 780000 7800000 7800000 7800000 7800000 7800000 780000 7800000 780000 7800000 7800000 7800000 7800000 7800000 7800000 780000 780000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 780000 780000 780000000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000 7800000000 7800000 7800000 7800000 7800000 7800000 7800000000 7800000 7800000 7800000 780000000000	N/2.6	20	40820	81640	29200	71000	58000	70820
73 44.00 89400 82500 77700 65500 725 74.00 94500 94500 82200 67200 67200 72 72500 94700 94700 84700 72700 94700 94700 72700 72700 72700 72700 72700 72700 72700 72700 81 57870 72700		7.1	42000	84000	81500	73100	00969	30027
76 48600 97500 91600 82200 6/200 76 48600 97500 94500 87500 69000 77 49800 99000 96000 70000 79 52/00 105400 105500 78800 81 54870 109740 106500 95500 78000		/3	44/00	89400	00998	11/00	00589	44 / UC
76 A8600 97200 94200 84500 69000 77 49800 96000 96000 702500 105400 105500 91500 74800 81 5480 109740 105500 95500 78000		75	17250	00510	00916	82200	67200	7/250
7. 424800 494881 91880 74800 78000 81 54870 109740 106500 95500 78000 78000	r:	76	18000	97200	94200	84500	00060	78600
81 5/8/0 109//0 106500 05500 /8000	3/ 5		002707	20070	007005	20725	00202	100 C. 1
	0.4.0	81	2/8/2	109740	106500	000550	0008/	5/3/6

Web sling colour chart


Color	WLL (Straight lift)
1000000	400
Green	2 (100)
Yellow	3 tons
Grey	4 tons
Rost	14460
British	6 tons
Bine	& foots
Orange	19 tons or above

Web sling lifting chart

			AS	YL IN KG WI	TH ONE WE	SWL IN KG WITH ONE WEBBING SLING	m	SWL IN	KG WITH TM	SWL IN KG WITH TWO WEBBING SLINGS	SENIES
1		Liffing method	straight	choka	basket	basket, inclination angle §	ingle §		angle of	angle of inclination §	
WIT		. /		~ 0		3 % V	form-to \$=45°-60°	Stage S	\$ 5 T & S	straight from-to \$5=45°.60°	choke from to \$=45°-60°
Art. No.		Factor	1.0	8.0	2.0	1.4	1.0	14	1.12	1.0	0.8
HFS01	1000kg	Notes.	1000	800	2000	1400	1000	1400	1120	1000	800
HFS02	2000kg	useub	2000	1600	4000	2800	2000	2800	2240	2000	1600
HFS03	3000kg	yellow	3000	2400	0009	4200	3000	4200	3360	3000	2400
HF S04	4000kg	grey	4000	3200	8000	2600	4000	2600	4480	4000	3200
HFS05	5000kg	1991	2000	4000	10000	7000	2000	7000	9999	9009	4000
HFS05	6000kg	Crowns	9009	4800	12000	8400	0009	8400	6720	9009	4800
HFS08	8000kg	plus	8000	6400	16000	11200	8000	11200	0968	8000	6400
HFS010	10000kg	Orange	10000	8000	20000	14000	10000	14300	11200	10000	8000

25. BASIC RIGGING SIGNALS, TACKLES AND METHODS

	Cower THE LOAD	SLOWLY LOWER LOAD	class hands in front of free properties in front of body body EVERYTHING	
Z	Hoist Iower	Hoist Iower - slow	DOG everyth ing – pause the motion	
СОММОИ	The state of the s	SLOWLY RAISE LOAD	Particular de la constantina del constantina del constantina de la constantina del const	ALL STOP
	Hoist up	Hoist up- slow	Stop – motion is finished	Emergency stop -







Wire rope slings with thimble **Bow and D shackle**





Web sling

26.DOCKING & UNDOCKING

Docking and undocking of the ship is one of the major activities in the yard. The following precautions are to be taken.

- 1. Docking and Undocking operations should be done only with the guidance of the dock Master, pilots or authorized person from CSL-MSRU.
 - Pre requisite checklist to be filled cleared by CSL-MSRU project manager. 2
- Tugs or suitable supports should be ensured
- Tide level, List and Trim of the vessel level, docking plan and water currents to be taken care of while planning the docking & undocking ω. 4.
- Gangways shall be placed in a safe manner after the positioning the vessel 5.
 - Good condition of mooring ropes shall be ensured
- Suitable floating life vest to be worn if any chance of fall into water bodies. 6.
- Docking and undocking checklist must me follow for each ω.

27.SLIPS, TRIPS AND FALLS

occur in all kinds of work places and under a range of A large portion of injuries at work are caused by slips, trips and falls. Whether on the same level or from height, fall can different conditions.

Some of the common reasons for Slips, Trips and fall are:

- Poor flooring
- Unsuitable foot wear
 - Slippery surfaces
- Obstruction in walk ways
- Poor lighting or restricted vision 4. 7.

6. Undue care and attention.

accidents is by keeping your work-area clean, tidy and free The biggest contribution you can make in preventing such from obstructions.

- Use proper routes and walkways. Avoid short cuts
- Make sure that any temporary opening in walkways is secularly fenced off. On completion of work, replace 7;7
- grating and covers securely. Report to your immediate supervisor whether there are damaged or obstructions on floor surfaces, lack of handrails and fencing as well as inadequate illuminated ω.
- Correct use of ladders firm level surface, secured at the top and extended beyond the step-off point or adequate separate handhold. 4.



28.FIRE

a. Basic chemistry of fire

Any fire, once it starts, will continue to burn as long as there is something to burn and oxygen is present. There must be reasons for a fire to start and the way it burns. There are

reasons for certain substances to be more or less flammable than the others.

b. The nature of fire(combustion)

oxidation process. It is a chemical process. Energy is given off during this process, usually in the form of heat. The oxidation process in case of a fire or combustion is rapid. The burning Production of energy in the form, of heat and light is rapid, so we The combination of a substance with oxygen is called an substance combines with oxygen at a very fast and high rate. can feel the heat and see the light as flames.

c. Elements of fire

The essential requirements of a sustainable fire (combustion) are the presence of three elements, i.e. FUEL, HEAT and supply of free OXYGEN, usually in air (formation of fire triangle)

28.1 Fire Prevention

Prevention is the best form of defense. Fires can be prevented by following some simple rules.

- Don't let rubbish or items accumulate in one area, especially under stairs.
- Don't overload electrical outlet sockets
- Don't use make shift wiring extensions
- Hot works carried out onboard vessel only through Permit To Work. 2 κ. 4.
- Lighting of incense and candle is not allowed inside your room. 5.
- Don't store any flammable items inside the room unless it is meant for. 9
- Don't hang clothes to electrical equipments such as fans, AC and in the corridors. Always keep Entry/exit clear.
- Suitably designed equipment and its installation (intrinsic safety) œ.
- Inspection and maintenance of equipment and electric circuits. 6
 - 10. Maintaining and properly using portable equipment and flexible cables.
 - 11. Adopting safe working practices and procedures

28.2 Discovery of fire

On discovering of fire, your prompt action could save lives:

- Warn all personal in the area by fire, fire, AAA
- Use first aid fire fighting appliances in that area.
 - If it is not possible, call CSL-MSRU fire service.

must not be tampered with and must Remember: - Firefighting equipment oe kept clear of all all obstruction

29.GENERAL PERSONAL FACTORS LEAD AN INCIDENT

The following personal factors are to be taken care of and they should be more vigilant while on duty, otherwise it may lead to ncidents.

- Ensure sound sleep.
- Eat sufficient breakfast.
- Avoid over eating Sickness suffered by any family member or near & dear ones(Frustration) 4.
- Acute financial crisis

6.


- Quarrel with others (Emotional disturbance)
 - Over confidence 7.89.9
- Influence of medications
- Fatigue due to lack of rest

30.0FFICE SAFETY

- Don't stand and talk in front of closed doors which may open suddenly.
- Walk cautiously around blind corners
- Sit squarely on office chairs, and not on the edge of them. ς. κ.
- Running at any time in an office may result in injury from slipping, tripping or collision. Avoid running in offices. 4.
- Walk slowly and cautiously up and down stairs. Use hand rail where possible. 5.

- The gummed strips on envelopes should not be moistened with tongue. 9.
 - shoes shall heeled exercise extra caution to prevent falls. high Office employees wearing
 - Don't use lift in case of fire.
- While lift break down, shout for help or make call to **CSL-MSRU Emergency number for help** 89.0

Desk stretch exercise for continuous use of computers



31.WASTE MANAGEMENT

A waste is a material which is discarded or intended to be discarded.

Waste identification and classification

Type of Wastes are classified in CSL-MSRU activities

- Waste Oil/Oil Sludge
- Oil soaked cotton waste
- Empty paint drums Used copper slag
 - Zinc Anodes
 - Used Batteries
- Electronic Waste
 - Steel Scrap
- Industrial Waste Cut Cable

Waste disposal policy

- No dumping of items in the yard premises and same requirement. ij.
 - Respected vendor /agency is the responsible to dispose the waste according to state statutory requirements. 2

32.OCCUPATIONAL HEALTH

ife style diseases and the various physical and chemical hazards. The employees are exposed to various levels of health hazards, Proper awareness about the health hazards is a required for an Occupational health deals with man (both physically and mentally) in relation to his work and work environment. employee to lead a healthy life

The various measures to be taken for reducing Health hazards

1. Employees who are involved in handling hazardous chemical, gases and other substances should be made aware about its

health hazards and the precautions to be taken in handling

- The MSDS of the chemical being handled should be made available to the workers. 2
- Statutory Periodical health checkups should be done by the company З.
- Non statutory health check up should be done at least once in two years in order to detect Life style diseases such as High Cholesterol, Diabetics, Blood pressure, allergies to any chemical or substances etc 4.
- Employees should maintain all his medical records and should be made available in case of an emergency. 5.
- various personal factors also can lead to accidents and subject Stress of employees that is either job related or caused by the victim to various diseases. 6.

33.FIRST AID

First aid is the immediate emergency care / treatment given to the victim of an accident or sudden illness, till medical aid is available.

Aims of first aid

- To preserve / save life a)
- To prevent further injury & worsening of casualty's condition
- To promote recovery ()

Ten Commandments for first aiders

reach the accident spot quickly

- be calm and speedy
- ensure safety of the place
- look for life threatening conditions first
 - give FA in the order of priority
- reassure the casualty if conscious clear the crowd
- do not leave the casualty alone 6. 8.
 - arrange for safe transport
- do not attempt too much / do no harm

Look for condition of the victim in the following order

- is the victim conscious
- is the victim breathing is there severe bleeding
 - is the victim in shock
 - is the victim in pain 4. 7.

33.1. Control of bleeding

- Apply direct pressure over the wound
- Cover wound with sterile dressing and bandage firmly
- Raise the injured part above level of heart
- Apply pressure over pressure points 4.
- Immobilize the injured part
 - Look for signs of shock 9
- Send to hospital in lying down position

33.2 Fracture

Suspect fracture when there is tenderness, swelling, deformity, abnormal movements etc.

- Control any bleeding and cover any wounds
- Do not move the casualty unless life is endangered
- Immobilize the injured area as well as the joints above and below using suitable splints
- Call for ambulance to send to hospital

33.3 Burns

- If clothing on fire—stop, drop and roll
- Cool the burnt area by holding under cold running water for at least 10 minutes
- Do not apply ointments, oils or any other substance
- Cover the wound with sterile non-sticky dressing 4.
- Call for ambulance

4 Eye injuries 33.

- Removal of foreign body should not be attempted
- Do not apply ointment or oil
- Apply sterile pad and loose bandage
- Send to hospital

33. 5 Chemical burns of the eye

- Immediate washing of the eye with clean water continuously for at east 20 minutes
- Apply sterile pad and bandage 7
 - Send to hospital.

33.6. Suffocation

- Remove the casualty from the site of accident to safe area to get fresh
- Clear the airway
- Restore breathing by artificial respiration
- Send to hospital 4

33.7 Electric shock

- do not touch the casualty while he is still in contact with live source
- switch off the power immediately
- do not attempt first aid until the contact has been broken
- check response and breathing 4.
- give cardiopulmonary resuscitation (CPR) if the casualty is unconscious and is not breathing

33.8 Unconsciousness

- Check response
- If no response look for breathing
- Start giving CPR if unresponsive and is not breathing
- If breathing is normal, keep the casualty in recovery position till he gets medical attention

33.9 Chest pain

- If casualty is conscious, keep him in half sitting position and advise to take rest
- Call for ambulance and continue CPR till he gets medical help or show If unconscious, check D.R.A.B.C (Dangerous, Response, Airway, Breathing and Circulation) and start giving CPR if necessary signs of life.

33. 10 Cardiopulmonary Resuscitation (CPR)

CPR is the emergency first aid procedure done when the casualty is unconscious and not breathing.

CPR maintains flow of oxygenated blood to the brain and the heart, thereby delay tissue damage, so that more definite treatment will be effective

If you see a motionless person, follow the steps below

- Assess the area for any safety hazards before proceeding
- Check the response by shaking the shoulders and calling loudly
- Check for breathing by looking rise and fall of chest wall for 5 to 10 If there is no response, open the airway by head tilt and chin lift
- If there is no breathing start giving CPR seconds 5.

sequence. CPR is effect only if performed within 4-5minutes of the CPR consists of artificial circulation & artificial respiration given at regular stoppage of blood flow. CPR sequence of steps is now

C-A-B

 $\mathsf{C} ext{-}\mathsf{C}$ Chest compression

 A - Airway

 ${f B}$ - Breathing

Chest compression

- Place the heel of one hand at the centre of lower part of chest and place the other hand on top of the first.
 - Begin chest compression push hard and push fast
- The rate of compression should be at least 100 per minute.
- Depress the chest at least 2 inches (5 cms) and allow full recoil of chest wall before next compression 2 .. 4
- Give 30 compressions at one stretch
- 6 .5


Air way opening

- Open airway by head tilt and chin lift
- Check breathing by watching rise and fall of chest wall for 5 to 10 seconds.

Breathing

If the casualty is not breathing, give two rescue breaths in two seconds.

Continue CPR by giving 30 chest compressions followed by 2 rescue Continue CPR until there are signs of life or until emergency medical personnel take over breaths



SERVICE MANIFOLDS/PIPE LINES & ELECTRICAL DISTRIBUTION 9 **TYPES** WITH CODING 34.COLOUR BOXES

CONSEQUENCE MANAGEMENT

The purpose of consequent Management is to provide a fair and consistent approach to dealing with every ones conduct, behavior and/or performance whose conduct, behavior and/or performance falls below acceptable falls below acceptable standards or regulatory requirements. It will apply standards or regulatory requirements will be subject to corrective action. Everyone is expected to conduct themselves in a manner which conforms to HSE standards of workplace behavior and conduct. When a violation of an established standard occurs, cases will be investigated thoroughly and disciplinary action will be administered on the merits of each case.

35. SAFETY REVIEW MEETING

deficiencies and improvement opportunities in the system are being discussed in a constructive manner and necessary measures needed to Safety review meeting conducted every month to address any improve it.



This meeting will be chaired by unit head, execution and QHSE team will be part of the meeting. Secretary of the meeting is a from QHSE team.

36.STEPS TO REDUCE ENVIRONMENTAL IMPACTS

- Continual Improvisation of the system to reduce the use of natural resource (Eg: Electricity, water, paper) in CSL-MSRU.
 - Continual Improvisation of the system to reduce the pollution resource (Eg: air, water and soil) in CSL-MSRU.
- Promotion of use of environment friendly materials in CSL-MSRU.
- Action to reduce any leakage of water in CSL-MSRU. If water leakage is observed in your area, report immediately.
- Avoid Improvised connections and use of standard leak proof couplings for getting water.
- Electrical equipments to be switched off when it is not
- Promote the use of one side paper in offices.
- Avoid dumping oil or paint sludge directly in sea water.
- Paint drums, oil drums, blasting materials etc. are to the taken away from the dock floor before flooding the dock and area will be cleaned.

कोचीन शिपयार्ड लिमिटेड



COCHIN SHIPYARD LIMITED
(A Government of India Category-1 Ministra Company, Ministry of Shipp

RULES SAFETY **12 SALIENT**



DISCUSS WORK RELATED SAFE OPERATING PROCEDURES IN DAILY TOOL BOX MEETING (TBM)







 \leftarrow

























USE TESTED & CERTIFIED LIFTING TOOL & TACKLES, GAS HOSES AND ELECTRICALLY

OPERATED TOOLS

IPPROPRIATE PPE'S AT WORK

GOOD HOUSEKEEPING PROMOTES HEALTH, SAFETY & ENVIRONMENT QUALITY, PRODUCTIVITY AND

BASIC PPEs









DON'T CARRYOUT HOT WORK AND PAINTING WORK SIMULTANEOUSLY

DO NOT USE MOBILE PHONES WHILE DRIVING OR CARRYING OUT WORK ACTIVITY

The 12 Salient Safety Rules are the fundamental safety Subcontractors & their workmen and Owners/Classification standards expected from everyone in CSL rolls, Partners, societies to comply with, at all times

When work does not comply with 12 Salient Safety Rules:-

Every individual is responsible and obliged to request for "सुरक्षा केलिए रुके"

"WHAT TO DO" FLOW CHART

Violation of 12 Salient Safety Rules Observation of Non-Compliance

[Intervention to "STOP" the Immediate Danger] Request for "सुरक्षा केलिए रुकें

Do a Safety Conversation [Gentle Re affirmation]

Restart after Corrective actions [Corrective actions to be verified]

Safety & Fire Services Department



"Protect our earth"

"They are waiting you at home"

Paste your family photo here

Health, Safety & Environment Contract Guidelines for OEMs /Turnkey jobs / Sub contract works inside CSL Encl: 9

Introduction

CSL is the largest public sector shipyard in India in terms of dock capacity, and caters to clients engaged in the defence sector in India and clients engaged in the commercial sector worldwide.

CSL is committed to provide safe and healthy work environment for the prevention of work- related injury and ill health by following the best practices in safety. CSL is certified Occupational Health and Safety management System and Environmental Management system under ISO standards/international standard.

Many of the works of CSL at various sites are executed by the sub-contractors. During these works, sub-contractors personnel are likely to be exposed to different types of hazards. Similarly unsafe acts of contractors personnel may create hazards for CSL staff or workmen of other contractors working at the site. Such unsafe acts may also pose danger to the existing installations and even to members of public.

CSL ensures that the requirements of its HSE Management System are convened by contractors and their workers. This guide is prepared to facilitate safe working during execution of contract works. The General guide lines and HSE requirements are given below for compliance in CSL.

I. General guidelines

- 1. OEMs/Turnkey jobs /Contractors are selected to work inside the CSL based on their track record.
- 2. Along with the contract order/Registration, a copy of the HSE Safety Handbook (CSL/QMS/S&F/SOP 02) of CSL is given to all contractors. The details of all HSE requirements to be followed in CSL for the various types of work are detailed in the hand book. The OEMs/Turnkey jobs /Contractors shall go through all the details and strictly follow the relevant HSE guidelines for their work. In case of any doubt the same shall be clarified from Chief Safety Officer (CSO). Being ignorant of these HSE requirements will not be treated as an excuse for any HSE violations during course of work.
- 3. OEMs/Turnkey jobs /Contractors workmen are given a multilingual HSE induction and Emergency Response training. The individual passes for contractors and their workers are issued only after successful completion of this training. The passes are revalidated every year after successful completion of refresher training. Training requirements of other roles of the subcontractor's staff shall be complied as per the CSL requirements time to time.
- 4. Before start of any work, the CSL officer in charge explains the scope of work and the safety precautions, hazards, PPE usage as per PPE matrix of CSL, Work Instructions, SOPs, Emergency responses to the contractor and his workers. Only trained worker with necessary skills are allowed to work as per the requirement. Necessary PPEs for the work are to be arranged by the contractor.
- 5. Workmen shall have Cotton coverall with identifiable logo on the dress. Supervisors, fire watch man if required, safety staff and other workforce shall be deployed as per CSL guide lines.
- 6. The site work supervisor of the OEMs/Turnkey jobs /Contractors shall be ensured that works are being carried out by CSL HSE requirements on daily basis and till the completion of works. The safe start and safe end requirements shall be verified by the site work supervisor on daily basis.
- 7. OEMs/Turnkey jobs /Contractors HSE performance will be evaluated on HSE matters as per the CSL policies time to time.
- 8. During the course of work if any HSE violation is noticed the same is dealt as per the Rewards and Reprimand (R&R) Policy of CSL.

II. HSE requirements

1. The OEMs/Turnkey jobs /Contractors shall take all safety precautions during the execution of awarded work and shall maintain and leave the site safe at all times. At the end of each working day and at all times when the work is temporarily suspended, he shall ensure that all materials,

Revision: A00 Sept 2020 Page 1 of 2

- equipment and facilities will not, cause damage to existing property, personal injury or interfere with the other works of the project or Station.
- The OEMs/Turnkey jobs /Contractors shall provide and maintain all type of lights, guards, fencing, warning signs, caution boards and other safety measures for vigilance as and where necessary or as required by the CSL officer-in-charge or Safety staff. The caution boards shall also have appropriate symbols.
- 3. Where Permit to work (PTW) is required, the work has not started without obtaining the necessary permit and the PTW requirements are followed strictly throughout the work.
- 4. For Project specific or non-routine work on the existing installations, separate Job Safety Assessment (JSA) is to be prepared by the contractor, cleared by the Dept in charge and approval obtained from CSO before start of work.
- 5. A separate HSE plan will be required for the new projects in the yard or any turnkey projects. It shall be in line with CSL HSE requirements and same shall be routed through respective S&F dept and approved by respective HOD.
- 6. OEMs/Turnkey jobs /Contractors shall hold toolbox talks with his workers on daily basis to convey matters regarding the Safety aspects of the work.
- 7. The OEMs/Turnkey jobs /Contractors shall plan his operations so as to avoid interference with other Departmental works and other Sub-Contractors at the site. In case of any interference, requires, coordination shall be sought by the contractor from the Department for safe and smooth execution of work. This shall be done through CSL executing officer.
- 8. The OEMs/Turnkey jobs /Contractors shall at all times keep their work spot, site office and surroundings clean and tidy from rubbish, scrap, surplus materials and unwanted tools and equipment. Welding cables, hoses and electrical cables shall be so routed as to allow safe way to all concerned.
- 9. All waste generated in course of the work shall be segregated as per the yard requirements and shall be disposed at the respective collection pallets / points of the work areas as the case may be. Any kind of pollution made by the subcontractor shall attract the reprimand proceedings.
- 10. All necessary precautions shall be taken to prevent outbreak of fires at the work site. Adequate provisions shall be made to prevent the possibility of fires and ensure the availability of fire extinguishers at site.
- 11. The OEMs/Turnkey jobs /Contractors shall be held responsible for non-compliance of any of the safety measures and delays, implications, injuries, fatalities and compensation arising out of such situations of incidents including statutory obligations.

Revision: A00 Sept 2020 Page 2 of 2